

© 1995-2004, SolidWorks Corporation

300 Baker Avenue Concord, Massachusetts 01742 USA All Rights Reserved

U.S. Patents 5,815,154; 6,219,049; 6,219,055; 6,603,486; and 6,611,725; and certain other foreign patents, including EP 1,116,190 and JP 3,517,643. U.S. and foreign patents pending.

SolidWorks Corporation is a Dassault Systemes S.A. (Nasdaq:DASTY) company.

The information and the software discussed in this document are subject to change without notice and should not be considered commitments by SolidWorks Corporation.

No material may be reproduced or transmitted in any form or by any means, electronic or mechanical, for any purpose without the express written permission of SolidWorks Corporation.

The software discussed in this document is furnished under a license and may be used or copied only in accordance with the terms of this license. All warranties given by SolidWorks Corporation as to the software and documentation are set forth in the SolidWorks Corporation License and Subscription Service Agreement, and nothing stated in, or implied by, this document or its contents shall be considered or deemed a modification or amendment of such warranties.

SolidWorks, PDMWorks, and 3D PartStream.NET, and the eDrawings logo are registered trademarks of SolidWorks Corporation.

SolidWorks 2005 is a product name of SolidWorks Corporation.

COSMOSXpress, DWGEditor, eDrawings, Feature Palette, PhotoWorks, and XchangeWorks are trademarks, 3D ContentCentral is a service mark, and FeatureManager is a jointly owned registered trademark

of SolidWorks Corporation.

COSMOS, COSMOSWorks, COSMOSMotion, and COSMOSFloWorks are trademarks of Structural Research and Analysis Corporation.

FeatureWorks is a registered trademark of Geometric Software Solutions Co. Limited.

ACIS is a registered trademark of Spatial Corporation.

GLOBEtrotter and FLEXIm are registered trademarks of Globetrotter Software, Inc.

Other brand or product names are trademarks or registered trademarks of their respective holders.

COMMERCIAL COMPUTER SOFTWARE - PROPRIETARY

U.S. Government Restricted Rights. Use, duplication, or disclosure by the government is subject to restrictions as set forth in FAR 52.227-19 (Commercial Computer Software - Restricted Rights), DFARS 227.7202 (Commercial Computer Software and Commercial Computer Software Documentation), and in the license agreement, as applicable.

Contractor/Manufacturer: SolidWorks Corporation, 300 Baker Avenue, Concord,

Massachusetts 01742 USA

Portions of this software © 1988, 2000 Aladdin Enterprises.

Portions of this software $\ensuremath{\mathbb{C}}$ 1996, 2001 Artifex Software, Inc.

Portions of this software © 2001 artofcode LLC.

Portions of this software $\ensuremath{\mathbb{C}}$ 2004 Bluebeam Software, Inc.

Portions of this software \bigcirc 1999, 2002-2004 ComponentOne

Portions of this software © 1990-2004 D-Cubed Limited.

Portions of this product are distributed under license from DC Micro Development, Copyright © 1994-2002 DC Micro Development, Inc. All rights reserved

Portions © eHelp Corporation. All rights reserved.

Portions of this software \bigcirc 1998-2004 Geometric Software Solutions Co. Limited.

Portions of this software $\ensuremath{\mathbb{C}}$ 1986-2004 mental images GmbH & Co. KG

Portions of this software © 1996 Microsoft Corporation. All Rights Reserved.

Portions of this software © 2004 Priware Limited

Portions of this software © 2001, SIMULOG.

Portions of this software $\mathbb C$ 1995-2004 Spatial Corporation.

Portions of this software © 2003-2004, Structural Research & Analysis Corp.

Portions of this software $\ensuremath{\mathbb{C}}$ 1997-2004 Tech Soft America.

Portions of this software are copyrighted by and are the property of UGS Corp. © 2004.

Portions of this software © 1999-2004 Viewpoint Corporation.

Portions of this software $\ensuremath{\mathbb{C}}$ 1994-2004, Visual Kinematics, Inc.

This software is based in part on the work of the Independent JPEG group.

All Rights Reserved



Introduction

About this Book		xi
Moving to SolidWorks 20	005	xiii
Chapter 1 SolidWorl	ks Fundamentals	
Task Pane		
SolidWorks Resources	۶	
File Explorer		
Design Library		
Design Journal		
Design Journal		
Comments		
User Interface		
User Interface Style		
Highlighting		
Materials		
What's Wrong		
Sketch Relations		
Customize User Interf	face	1-9
Customize by Work F	low	
Toolbars		
Repeat Last Command		1-11
Selection		
Cross Select		
Select Other		
Quick Snap Selection	l	
Smart Selection		
Selection Filters		

Multi-user Environment	1-14
Reload	
Copy Settings Wizard	
Options	
File Explorer	
Collaboration	
Macro Editing	1-17
Documentation	1-18
Welcome to SolidWorks	
What's New	1-18
Online Tutorials	
Overview Topics	
2D lopics	
Chapter 2 Sketching	
General Sketch Entities	
Autodimension	
Surface Trim with 3D Sketch.	2-2
Offset Entities	
Circles	
Sketch and Quick Snaps	
Sketch Snaps	
Quick Snaps	
Splines	
Sketching a Spline	
Splines PropertyManager	
Spline Tools and Shortcut Menu Controls	
Add Relations to Splines	
Restrictions with Splines	
Inew 1001s on the Spline 1001s 1001bar	
Sprines on Surfaces	

Offset Splines2-17Infinite Lines2-18Insert Line2-18Orientation2-18Options2-19Parameters2-19Insert Line with 3D Sketches2-19

Trim
Power Trim
Corner
Trim away inside
Trim away outside
Trim to Closest
Mirror
Minimum/Maximum Dimensions with Arcs 2-27
Sketch Relations Display

Chapter 3 Features

General	-2
Smart Selection	-2
Deforms	-4
Surface Push Deform Type	-4
Curve to Curve Match Tangency Options 3	-6
Extrusions	-8
Fillets	-8
Flexes	-9
Indents	10
Lofts	12
General Enhancements	12
Curvature Continuity	13
Guide Curve Alignment	14
Guide Curve Influence	15
Individual Segment Weight Control 3-	16
Mesh Previews	17
Synchronization	17
Mirrors	19
Move/Copy Bodies	19
Split Line Curves	20
Silhouette Split Lines	20
Intersection Split Lines	20
Sweeps	21
Direction Vector References	21
PropertyManager Enhancements	21
Twist	21

Chapter 4 Parts

Custom Properties
Equations, Global Variables, and Linked Values
Dimension Status Indicator
Modifying Dimensions
Equations
Global Variables
Linked Values
Lighting
General Enhancements
Dynamic Lighting
Mass Properties
Measure Tool
Multibody Parts

Chapter 5 Mold Tools

Chapter 6 Weldments

Cut Lists	6-2
Cut List Folder	. 6-2
Automatic Cut List.	6-2
Structural Members Along Arcs	6-3
Weldment Trimming	6-4
Weldment Properties	6-6

Chapter 7 Assemblies

Assembly Performance	
Level of Detail in Dynamic Views	
Suspend Automatic Rebuilds in Assemblies	
Exploded Views	
External References	
General Enhancements	
Assignable Mass Properties.	
Managing Files in a Shared Environment	
Creation and Management of Assembly Component	Configurations
Flexible Sub-Assemblies	
Interference Detection.	
Chapter 8 Configurations	
Configurable Tolerances	
Creation and Management of Assembly Component Co	nfigurations
Configurable Materials	
Flexible Sub-Assemblies	
Chapter 9 Drawings	
Aligned Section Views	
Comparing Drawings	
Crop Views	9-2
Detached Drawings	9-2
Detail Views	
Lightweight Drawings	
OLE Objects	9-3
Options	9-3
Projected Views	9-4
Section Views	9-4
Exclude Fasteners from Section Views	9-4
Section Views and Aligned Section Views	
User Interface	
Drawing Sheets	
Drawing Views	
Edges	
FeatureManager Design Tree	
Sketches.	
10010a1S	

Chapter 10 Detailing

Annotations	
Alignment.	
Area Hatch/Fill.	
Blocks	10-3
Cosmetic Threads	10-4
Datum Target Symbols	
Dimensions.	
Geometric Tolerance Symbols	
Halos	
Hide/Show Annotations	
Highlighting	
Library Footures	
Moving Annotations and Drawing Views	
Notes	10-8
Selection.	
Surface Finish Symbols	
Weld Beads.	
Weld Symbols	
Autodimension	10-15
Bills of Materials	
Custom Properties	10-16
Equations and Formulas	
Design Library.	
Insert Model Items.	
Options	10-18
Cosmetic Threads	
Line Style	
Toolbars	10-19
Align Toolbar	
Annotation Toolbar	
Formatting Toolbar	
Table Toolbar	
Chapter 11 Library Features	

General Enhancements 1	1-2
Design Library	1-2
Library Features on a Plane	1-3

Adding Library Features	1-4
Editing Library Features 11	1-5
FeatureManager Design Tree 11	1-6
Creating a Library Feature	1-6
Library Feature Subfolders 11	1-7
PropertyManager	1-7
Library Features and Links	1-9

Chapter 12 Other Functionality

Application Programming Interfaces and Macros	12-2
Application Programming Interfaces	12-2
Macros	12-3
Import/Export	12-4
SolidWorks DWGEditor	12-4
AutoCAD DXF/DWG Files	12-5
Mechanical Desktop (MDT) Translator	12-5
eDrawings	12-5
Assemblies	12-5
ProENGINEER Translator	12-5
Unigraphics Files.	12-6
IDF Files	12-6
Installation	12-7
Administrative Images.	12-7
SolidNetWork License.	12-7

Chapter 13 SolidWorks Office Add-Ins

eDrawings	13-2
General	13-2
Application Programming Interface	13-2
Compression	13-2
Download Options	13-3
DXF/DWG XREF Paths	13-3
eDrawings Executables	13-4
Shadows	13-4
Tablet PCs	13-4
Toolbar Buttons	13-4
eDrawings Professional	13-5
Animations	13-5
Passwords	13-6
SolidNetWork License.	13-6

FeatureWorks
Hole Wizard Holes
Step-By-Step Recognition
Miter Flanges
PDMWorks
Integration with SolidWorks
Check-In Enhancements
Search Enhancements
Client Options
API Access to Vaults
Administration Enhancements
Triggers
Web Portal
PhotoWorks
General Enhancements
PhotoWorks Studio
Caustics
Global Illumination
Decal and Texture Mapping
Environment Scenes
SolidWorks Animator
Animation Tabs
User Interface
SolidWorks Animator Tools
Key Points
Component Display Animation
Limit Mates
Save Animation to File
SolidWorks Toolbox
Access Control
Configure Browser
Configure Data
Part Numbers and Descriptions
SolidWorks Utilities
Compare Features
Compare Geometry
Feature Paint
Find/Modify/Suppress/Simplify13-42
Geometry Analysis
Power Select
Reports
Thickness Analysis

About this Book

This book highlights and helps you learn the new functionality in the SolidWorks[®] 2005 software. It introduces concepts and provides step-by-step examples for many of the new functions.

This book does not cover every detail of the new functions in this software release. For complete coverage of the new functions in the SolidWorks 2005 software, refer to the *SolidWorks Online User's Guide* by clicking **Help**, **SolidWorks Help Topics**.

Intended Audience

This book is for experienced users of the SolidWorks software and assumes that you have a good working knowledge of an earlier release. If you are new to the software, you should read the *Getting Started* book, complete the *Online Tutorial* lessons, then contact your reseller for information about SolidWorks training classes.

Additional Resources

Other resources where you can learn about the new functionality of the SolidWorks software include:

- SolidWorks 2005 What's New Highlights. This book provides the highlights of the new functionality in the SolidWorks software. This book is available in printed format for subscription customers.
- Interactive What's New. Click A next to new menu items and the title of new and changed PropertyManagers to read what is new about the command. A help topic appears with the text from this manual.
- **Online Help**. The online help contains brief descriptions of the new functionality with links to the complete, related help topics.

Late Changes

Due to software deadlines, this book may not include all of the enhancements in the SolidWorks 2005 software. For enhancements that are not in this book, refer to the *SolidWorks Release Notes* by clicking **Help**, **SolidWorks Release Notes**.

Using This Book

Use this book with the part, assembly, and drawing files provided. Read this book from beginning to end, and open the proper part, assembly, or drawing document for each example.

To use the example files:

- 1 Install the SolidWorks 2005 software.
- 2 Be sure to select the option to install the **Example Files**.

The example files are placed in the *<install dir>*\samples\whatsnew folder.

3 Open the example files from the **File Explorer** is when instructed to do so.

The **File Explorer** tab in the Task Pane duplicates Windows[®] Explorer[®] on your local computer. See **File Explorer** on page 1-3.

Because some of the example files are used with more than one example, do not save changes to these files unless instructed to do so.

Conventions Used in this Book

This book uses the following conventions:

Convention	Meaning	Example
Bold	Headings or titles that are not menu items	Measure . Measure the distance between two entities.
Bold Sans Serif	Any SolidWorks tool, menu item, or example file	Click Insert, Mate References.
Italic	Refers to books and other documents, or emphasizes text	Refer to the SolidWorks <i>Read This First</i> .
*	Tip	When you create a 3D model, first make the 2D sketch, then create the extruded 3D feature.

Converting Older SolidWorks Files to SolidWorks 2005

Opening a SolidWorks document from an earlier release may take longer than you are used to experiencing. After the file is opened and saved, subsequent opening time returns to normal.

The SolidWorks Conversion Wizard automatically converts all of your SolidWorks files from an earlier version to the SolidWorks 2005 format. To access the Conversion Wizard, click the Microsoft[®] Start button, select Programs, SolidWorks 2005, SolidWorks Tools, Conversion Wizard.

When the conversion utility begins, it offers you the choice to back up all of your files before the conversion. If you choose to back up your SolidWorks files, the Conversion Wizard copies the files to a sub-folder named **Solidworks Conversion Backup**. The wizard asks you for the location of the files to convert, and leads you through the process.

At the end of the conversion process, two report files exist in the folder where you directed the conversion.

- Conversion Wizard Done.txt contains a list of files that converted.
- Conversion Wizard Failed.txt contains a list of files that did not convert.

SolidWorks Service Packs

If you are a SolidWorks subscription customer, you can take advantage of SolidWorks service packs that are regularly posted on the SolidWorks Web site. These service packs contain software updates and enhancements to the SolidWorks 2005 software. To check for a new service pack, click **Help**, **Service Packs**, and click **Check**. Select the check box if you want the software to automatically check the SolidWorks Web site for a new service pack once a week.

Introduction

SolidWorks Fundamentals

This chapter describes enhancements to fundamental topics in the following areas:

- □ Task Pane
- Design Journal
- □ User interface
- □ Toolbars
- □ Repeat Last Command
- $\hfill\square$ Selection
- □ Multi-user environment
- □ Copy Settings Wizard
- □ Options
- □ Documentation

Task Pane

A new Task Pane appears when you open SolidWorks. It contains three tabs.

- SolidWorks Resources
- 🍘 Design Library
- File Explorer

The Task Pane can be in the following states:

- Visible or hidden. Right-click in the border of the graphics area and select or clear Task Pane, or click View, Task Pane. To change tabs or open a pane, click a tab icon.
- Pinned or unpinned. Click I to pin the Task Pane. Click again I to unpin it. If the Task Pane is unpinned, it collapses when you drag an item such as a document, a library feature, or an annotation into the graphics area, or when you open a new SolidWorks document.
- Docked or floating. To float the Task Pane, drag it by the bar between the arrows. To dock it again, drag it to a window border or click in the title bar.

To resize the Task Pane, drag its edge.





SolidWorks Resources

The SolidWorks Resources 🚮 tab in the Task Pane replaces the Welcome screen from previous releases. Groups include Getting Started (New Document, Open a Document, and so on), Online Resources (Discussion Forum, Subscription Page, and so on), and Tip of the Day (at the bottom of the tab).

You can customize **SolidWorks Resources** based on your work flow. See **Customize by Work Flow** on page 1-10.

File Explorer

The **File Explorer** at tab in the Task Pane duplicates Windows Explorer on your local computer. In addition, the following directories are displayed:

- Recent documents
- Open in SolidWorks (\$)
- **Samples** (*What's New* and Online Tutorial sample files)

In Open in SolidWorks 🚳:

- Files that appear in bold have been modified since they were last saved.
- Files that appear in orange indicate read-only status.
- The icon for files open in SolidWorks is solid **%**, and the icon for referenced components that are not open in SolidWorks is transparent **%**.
- To display or hide referenced components, right-click **Open in SolidWorks** (1) and select or clear **Show hidden referenced documents**. You can also set this option in **Tools**, **Options**, **System Options**, **File Explorer**. In assemblies, selecting this option hides component files that are not open in SolidWorks.

You can:

- Drag documents from the File Explorer into the graphics area.
- Right-click to access shortcut menus.
- Display tooltips.

Tooltips display:

- File name, path, date modified, and size.
- Preview (for documents with models, such as SolidWorks and AutoCAD[®]).

You can specify whether to display the following folders:

- My Documents
- My Computer
- My Network Places
- Recent Documents
- Samples

See File Explorer on page 1-17.

Design Library

The **Design Library** at tab in the Task Pane provides a central location for:

- Design Library 🖓
- Toolbox 🖷
- 3D ContentCentral §



To access SolidWorks Toolbox contents, you must install and add in the SolidWorks Toolbox Browser.

The **Design Library** contains reusable elements and recognizes file types for parts, assemblies, annotation favorites, blocks, library features, and DXF/DWG files. It does not recognize SolidWorks drawings, text files, or other non-SolidWorks files.

/
5

Refresh

Search

The contents of the Feature Palette[™] window and Library Features have been moved from the **Tools** menu to the **Design Library**. See **Design Library** on page 11-2.

Tools available at the top of the **Design Library** window include:

Add	File	Location	

Create New Folder

Adds a shortcut to a folder on disk.

Creates a new folder on disk.

Refreshes the display of the **Design Library** pane.

Searches the **Design Library** (Search local data or Search 3D ContentCentral) for various types of files based on file or folder names or on custom properties.

The Design Library folder contains subfolders, including:

- annotations
- assemblies
- features
- forming tools
- parts

The library folders are populated automatically, but you can add your own folders and contents as described below.

You can filter the files that are displayed for assemblies or forming tools. Right-click a folder the upper pane of the **Design Library**, then select:

- **Forming tools folder** to mark a folder as a forming tools folder. The SolidWorks software handles forming tools differently than other parts.
- Assemblies folder to display only the assembly documents in the folder.

Tooltips on the folders in the upper pane display the path and folder name. Tooltips on the files in the lower pane show the file names and previews.

3D ContentCentral includes:

- Supplier Content contains links to supplier Web sites with SolidWorks models.
- User Library contains models from individuals.



You must accept a license agreement when you first open **3D ContentCentral** before you can access the contents.

You can drag copies of parts, assemblies, features, annotations, and so on from:

- The **Design Library** into the graphics area.
- The graphics area into the lower pane of the **Design Library**.
- One folder to another in the **Design Library**.
- Microsoft Internet Explorer and Windows Explorer into the Design Library.

When you drag items into the **Design Library**, the **Save As** dialog box appears with the default file type for the type of item and the selected folder as the location.

- To copy a complete assembly or part into the **Design Library**, select it in the FeatureManager design tree and drag.
- To copy annotations or blocks into the **Design Library**, hold down **Shift** and drag from the graphics area. Annotations are saved with the extensions for favorites.
- To copy features, drag from either the FeatureManager design tree or the graphics area. Features are saved as Library Feature Parts.

If you modify an item that you inserted from the **Design Library**, the item is also modified in the library.

To add an existing folder to the Design Library:

- 1 Select the **Design Library** tab **M**.
- 2 Select **Design Library** (or a subfolder in **Design Library**) and click **Add File** Location .
- 3 In the dialog box, browse to a folder, then click **OK**.
- 4 The selected folder name (or a folder named **Shortcut to** *<selected_folder>* if it is to be a subfolder) appears.

For top level folders, this procedure has the same effect as the next procedure using SolidWorks Options. If you delete the folder, you delete only the reference. For subfolders, if you delete the folder, you delete only the shortcut. In both cases, the folder remains on disk.

To reference an existing folder in the Design Library:

- 1 Click **Options [**] on the Standard toolbar, or click **Tools**, **Options**.
- 2 On the **System Options** tab, select **File Locations**.
- 3 Under Show folders for, select Design Library.

- 4 Click Add.
- 5 Browse to a *<install_dir>*\samples\whatsnew\, then click OK.
- 6 Click **OK** to close the options dialog box.

You can reference any number of folders. The folder names appear at the top level on the **Design Library** tab (that is, at the same level as **Design Library**, **Toolbox**, and **3DContentCentral**).



If you delete a referenced folder from the **Design Library**, you delete only the *reference*. The reference is removed from **File Locations**.

To create a new folder in the Design Library:

- 1 Select the **Design Library** tab **M**.
- 2 Select Design Library 🖓 and click Create New Folder 📴, or right-click Design Library 🖓 and select New Folder.
- 3 Type My Models, then press Enter.

The folder appears under **Design Library** in alphabetical order.



If you delete a folder created with **New Folder**, the folder and its contents are deleted from disk and moved to the **Recycle Bin**.

To use a model from the Design Library:

- 1 Click at the top of the Task Pane to pin the Task Pane open.
- 2 Open indent.sldprt from the \whatsnew folder on the **Design Library** tab (drag the file into the graphics area, or right-click the file and select **Open**).
- 3 In the FeatureManager design tree, delete **Revolve** and **Sketch6**.

To add a model to the Design Library:

- 1 In the upper pane of the **Design Library** tab **M**, select **My Models**.
- 2 Drag **Indent** from the FeatureManager design tree into the lower pane of the **Design Library**.
- 3 In the dialog box, type **My Part** for **Save As**, then click **Save**.

My Part appears in the lower pane of the **Design Library** and is saved on your computer in the **My Models** folder.





Design Journal

A document called **Design Journal.doc** is embedded in SolidWorks documents. The document:

- Appears in the FeatureManager design tree in a new folder, **Design Binder** .
- Is a Microsoft Word[®] document.
- Resembles an engineering journal, with headings for File Name, Description, Material, and Revision.
- Initially appears as <Empty>, a designation that disappears when you activate the journal.



- Is added to the SolidWorks file when you activate it, so the SolidWorks file size is not affected unless you activate the journal.
- Can contain both text and embedded images. When you open the journal with Microsoft Office[®] 2002, the clipboard with images from the model is displayed in the graphics area. The file name is inserted automatically.
- Can be deleted, in which case it is again listed as **<Empty>**.
- Can be printed.

You must have Microsoft Word on your computer to use the design journal.

To edit the design journal:

- 1 Open indent.sldprt from the File Explorer [23].
- 2 In the FeatureManager design tree, double-click **Design Journal.doc** in the **Design Binder** folder \bigotimes .
- 3 Type text in the journal and add images by:
 - In Microsoft Office 2002, drag images from the clipboard.
 - In other versions of Microsoft Word, use the **Paste** command to paste in the image from the active window in SolidWorks.
- 4 Close the journal.

Your changes are saved automatically.

You can attach additional documents in the **Design Binder** folder \diamondsuit and embed them in or link them to the model document.

To insert an attachment to the journal folder:

- 1 In the FeatureManager design tree, right-click **Design Binder** \bigotimes and select **Add Attachment**.
- 2 In the dialog box, browse to a file, such as a Microsoft Word or Adobe[®] Acrobat[®] file.
- 3 To link rather than embed the file, select Link.
- 4 Click **OK**.

If you drag a document into the folder, it is linked rather than embedded.

You can specify the file location folder for both SolidWorks Journal File and Design Journal Template in Tools, Options, System Options, File Locations.

Comments

You can add text and voice comments to items in the FeatureManager design tree (assemblies, components, features, sketches, and so on) in the manner of Post-It[®] notes. Text comments are displayed in tooltips, and a **Comments** $\boxed{\Box}$ folder is created in the FeatureManager design tree.

To add a text comment:

- 1 Right-click an item in the FeatureManager design tree and select **Comment**, **Add Comment**.
- 2 In the message box, type text, click **Date/Time Stamp** to add the current date and time, then click **Save and Close**.
- 3 Hold the pointer over the item in the FeatureManager design tree to view the comment, or expand the **Comments** folder **Comments** in the document.

To add a voice comment:



To record sounds, your computer must have a microphone. You can edit the sounds, add effects, and specify audio devices.

- 1 Right-click an item in the FeatureManager design tree and select **Comment**, **Add Voice Comment**.
- 2 Record sounds in the **Sound Object in** *<filename>* dialog box.
- 3 Click File, Exit & Return to *<filename>*.

To edit a comment:

- 1 Right-click an item in the FeatureManager design tree that has a comment and select **Comment, Edit Comment** or **Play / Edit Voice Comment**.
- 2 Edit the comment, then click Save and Close.

To delete a comment:

Right-click an item in the FeatureManager design tree that has a comment and select **Comment**, **Delete Comment** or **Delete Voice Comment**, then click **Yes** to confirm.

User Interface Style

Many aspects of the user interface (icons on toolbar buttons and in the FeatureManager design tree, scroll bars, check boxes, tabs, pointers, and so on) now follow the Windows XP style in Windows XP. In Windows 2000, the icons display new images.

Highlighting

If an entity is highlighted, it remains highlighted when you manipulate a view with tools such as zoom, pan, and rotate.

Materials

In part documents, the **Materials Editor** PropertyManager contains a list of the ten most recently-used materials.

This list also appears when you right-click **Material** Ξ in the FeatureManager design tree.

What's Wrong

The What's Wrong dialog box has been redesigned.

- Messages are displayed in a table with icons that indicate Error ⊗ or Warning <u>A</u>.
- When the & icon appears in the **Preview** column, select the message to highlight the geometry in the graphics area. For example, a fillet feature error is highlighted as shown.
- Click column headers to reorder messages.
- When the ? icon appears in the **Help** column, click to open help topics about the errors or the features.

Sketch Relations

To display symbols of sketch relations in sketches and drawings, click **View**, **Sketch Relations**. See **Sketch Relations Display** on page 2-28.

Customize User Interface

The SolidWorks application now recognizes toolbar customization from one release of SolidWorks to the next. Settings are saved in the registry. Other registry settings continue to be recognized from one release to the next.







Keyboard shortcut and menu customization done through **Tools**, **Customize** have been stored in **.cus** files in releases before SolidWorks 2005. If you have performed this customization in previous releases, move the **.cus** file to the corresponding folder in SolidWorks 2005 to propagate the settings for this release. From SolidWorks 2005 on, settings previously handled by **.cus** files are included in the registry and the **.cus** file is no longer needed.

To copy registry settings, use the Copy Settings Wizard. See **Copy Settings Wizard** on page 1-16.

Customize by Work Flow

You can customize the user interface (toolbars, menus, and links on the Task Pane **SolidWorks Resources** tab) by your area of expertise. For example, in part documents, the CommandManager, in addition to the Sketch and Features toolbars, contains the following toolbars for the work flow area:

- Machine Design Sheet Metal, Weldments
- Mold Design Surfaces, Molds
- Consumer Product Design Surfaces

Resources such as tutorials, **Partner Solutions**, **Manufacturing Network**, and **Print3D** are included in the Task Pane **SolidWorks Resources** for all industries. Resources specific to particular work areas include **CosmosXpress**[™] for **Machine Design**, **MoldflowXpress** for **Mold Design** and **Consumer Product Design**, and **Import File** for **Mold Design**.



Consumer Product Tutorials

To customize the user interface by work flow:

- 1 Click Tools, Customize.
- 2 On the **Options** tab, under **Work flow customization**, select one or more check boxes, then click **OK**.

Menus and shortcut menus that are generally not used in an industry are hidden. For example, when you select **Consumer product design**, the **Sheet Metal**, **Weldments**, and **Molds** items on the **Insert** menu are hidden.

To display hidden items, click **Customize Menu** on individual menus. You can also override the customization in **Tools**, **Customize**.



When you open SolidWorks 2005 for the first time on a computer, the **Welcome to SolidWorks** dialog box gives you the opportunity to customize the user interface by work flow.

Toolbars

The **Select** tool now appears on the Standard toolbar as well as the Sketch toolbar. The following new tools have been added to the Standard toolbar.

Save All		Saves all open documents
Close	1	Closes the active document
Reload		Reloads the current document from disk
Check Read-only Files	8	Checks if read-only files are out of date or available for write access
Print 3D	30	Places an online order for a rapid prototype part
Options		Accesses the SolidWorks Options dialog box
Properties		Accesses the Properties dialog box for the current selection
New Window	-	Opens another window for the active document
Tile Horizontally	=	Arranges windows as non-overlapping horizontal tiles
Tile Vertically	<u> </u>	Arranges windows as non-overlapping vertical tiles

Redraw, which redraws the active window, is a new tool on the View toolbar.

Repeat Last Command

To repeat the last command, press Enter or click Edit, Repeat Last Command.

The last ten unique commands are displayed in a command history. The list is specific to the active document and to part, assembly, and drawing documents and sketch mode. The most recent command is at the top of the list. You can select any command from the list for your next command.

To view recent commands or repeat a recent command:

Right-click in the graphics area and select **Recent Commands**.

Selection

Cross Select

When you box select from left to right, only items completely within the box are selected. Now you can cross select from right to left to select items *crossing* the box boundaries in addition to items within the box.

The system gives you feedback as which type of selection you are implementing. When you select from left to right, the box is a solid line. When you select from right to left, the box is a dotted line.

Entities that you could select with the left-to-right box selection in previous releases now are also selected with the right-to-left cross selection, including:

- Sketches sketch entities and dimensions.
- Drawings sketch entities, dimensions, and annotations.

To select sketch entities:

- 1 Open \select\cross_select_sketch.sldprt from the File Explorer 🔯.
- 2 Box select from left to right, part way across the sketch entities, and note which entities are selected.
- 3 Cross select from right to left, crossing the same entities as in step 2, and again note which entities are selected.

In the example, only the left side of the rectangle and two sides of the polygon are selected with the left-to-right box. Three sides of the rectangle, four sides of the polygon, and the ellipse are selected with the cross select.



Box select (left to right)



Cross select (right to left)

Select Other

When you right-click a face and choose **Select Other**, the face disappears and a list of items underneath the pointer is displayed. While in the **Select Other** mode, you can right-click additional faces to remove them. To toggle visibility of a face without completing the operation, hold down **Shift** and right-click the face.

When you hover over an item in the list, the geometry is highlighted. Press **Tab** to cycle through the list. You can select items from the list or in the graphics area.

To exit the command, either select an entity or click in the graphics area outside the model. Selected entities are visible through the faces.



Quick Snap Selection

When a sketch tool is active, you can specify Quick Snaps to focus the tool on a particular type of snap: **Point Snap**, **Center Point Snap**, and so on. See **Sketch and Quick Snaps** on page 2-5.

Smart Selection

A new method of selecting edges for Sweep and Loft features allows you to select continuing edges so that the result is considered to be one group of edges. See **Smart Selection** on page 3-2.

Selection Filters

Filter Weld Beads 📓 has been added to the Selection Filter toolbar.

Multi-user Environment

You can manage write access for shared documents in a multi-user environment.

- The multi-user environment provides read/write access control and tracking for two or more users working with the same files concurrently. Users share a file when they have loaded the same file from the same location.
- Tooltips in the FeatureManager design tree inform you if an assembly, subassembly, or component is read-only. If another user with write access has the document open, the tooltip names the user.
- Files that are read-only appear in orange under **Open in SolidWorks (3)** in the Task Pane **File Explorer**.
- If you start to make changes to a read-only document, a message warns you that the document is read-only.
- The system checks the document for changes in status at the interval you specify. When the system detects a change, a tooltip in the lower right of graphics area points to an icon on the status bar. Click the icon to display the **Reload** dialog box. See **Reload** on page 1-15.

To enable a multi-user environment:

- 1 Click **Options** [E] on the Standard toolbar, or click **Tools**, **Options**.
- 2 On the **System Options** tab, select **Collaboration**.
- 3 Select Enable multi-user environment.
- 4 Select Check if files opened read-only have been modified by other users and set the time interval for checking files. (You can also check the file status manually by clicking Check Read-only Files 😭 on the Standard toolbar.



You might also want to select options in **Tools**, **Options**, **System Options**, **External References**. For example, select **Open referenced documents with read-only access** so other users can work on components while you have an assembly open, and select **Don't prompt to save read-only referenced documents (discard changes)** to prevent a message box appearing whenever you make a document read-only.

To set your status for a part or assembly document:

Click File, Make Read-Only or File, Get Write Access.

To set your status for a component:

Right-click a component in the FeatureManager design tree or in the graphics area and select **Make Read-Only** or **Get Write Access**.

Two new tools on the Standard toolbar access the new dialog box for managing files in a shared environment.

Reload - displays the active document in the Reload dialog box.

Check Read-only Files - checks if files have been made available for write access or have changed on disk since the last reload. A message appears if the files did not change, and the **Reload** dialog box appears if any files changed.

You can also access the dialog box for a component from the FeatureManager design tree or the graphics area. Right-click a component and select **Reload**.

Options in the dialog box include:

- · Show full paths
- **Show references** (for assemblies and sub-assemblies). The components are indented and listed in the order they appear in the FeatureManager design tree.

The dialog box displays the following columns:

- Reload. Select to reload all components.
- Filename. Displays the name of the active document and any references (if Show references is selected).
- **Read Only**. Shows if files are read-only, and allows you to specify files to become read-only.
- User With Write Access. Displays the name of the user with write access if you have read-only status for this document.
- Needs Save? If a component has changed and needs to be saved, Yes is displayed.
- Newer Version on Disk? If the version on disk is newer than the version open in memory, Yes is displayed.
- ? A question mark appears if a context-sensitive Quick Tip message regarding potential loss of data is available.

Once the references are displayed, you cannot hide them again. With references displayed, you can sort the files by **Default** (FeatureManager design tree order), **Filename**, **User with write access**, **Needs save**, or **Newer version on disk**. The file names remain indented when sorted.

Rows displayed in green indicate changes to **Reload** or **Read Only** that will not result in a potential loss of data.

Rows displayed in red indicate that you have selected to reload a file that has changed since it was last saved, or you have selected to make a file read-only when it has changed since it was last saved. Hover the pointer over the question mark to display a Quick Tip explanation.

Copy Settings Wizard

SolidWorks 2005 automatically retains your settings from earlier releases of SolidWorks. However, to distribute your settings to other computers, you can use the Copy Settings Wizard. The wizard (previously called Copy Options Wizard) now has options to **Save** or **Restore** system settings for:

- Keyboard shortcuts
- Menu customization
- · System options
- Toolbar layout (All toolbars or Macro toolbar only)

You can restore settings as follows:

Profile	Registry
Current user	CURRENT_USER of current user
One or more network computers	LOCAL_MACHINE of selected computers
One or more roaming user profiles	CURRENT_USER of selected users



Only system administrators should copy settings to network computers or roaming user profiles. When you restore settings to network computers, the settings apply to *new* SolidWorks users on the specified computers. You can restore settings to roaming user profiles only if your company uses roaming user profiles.

To save system settings:

- 1 In Windows, click Start, Programs, SolidWorks 2005, SolidWorks Tools, Copy Settings Wizard .
- 2 In the dialog box, select Save Settings, then click Next.
- 3 Browse to a location and file name, select the settings, then click Finish.



The settings files have a default extension of .**sldreg**. If you doubleclick a file with this extension, the Copy Settings Wizard appears.

The wizard confirms that the settings have been written to the specified file.

4 Click OK.

To restore system settings:

- 1 In Windows, click Start, Programs, SolidWorks 2005, SolidWorks Tools, Copy Settings Wizard 2.
- 2 In the dialog box, select **Restore Settings**, then click **Next**.
- 3 Browse to a file from which to restore the settings, select the settings to restore, then click **Next**.

- 4 Select the destination (Current user, One or more network computers, or One or more roaming user profiles), then click Next.
- 5 If you selected:
 - One or more network computers a list of available computers is displayed.
 - One or more roaming user profiles a list of available users is displayed.

Select computers or users and click **Add** until you have specified all computers or users, then click **Next**.

6 Select or clear Create backup of current settings for <*each_computer_or_user*>, then click Finish.

The wizard confirms that the settings have been copied successfully.

7 Click OK.

Options

File Explorer

In **Tools**, **Options**, **System Options**, **File Explorer**, you can choose whether to show the following folders in the Task Pane File Explorer:

- My Documents
- My Computer
- My Network Places
- Recent Documents
- Hidden referenced documents
- Samples

If you select **Hidden referenced documents**, referenced documents that are in memory but not open in SolidWorks are not shown in the Task Pane **File Explorer**. For example, if you open an assembly, any components not open in a SolidWorks window do not appear in the list of documents under **Open in SolidWorks (30)**.

Collaboration

In **Tools**, **Options**, **System Options**, **Collaboration**, you can enable a multi-user environment and specify an interval to check if read-only files have been modified by other users. See **Multi-user Environment** on page 1-14.

Macro Editing

In **Tools**, **Options**, **System Options**, **General**, the option **Automatically edit macro after recording** specifies that the macro editor will open after you have recorded and saved a macro.

Documentation

Welcome to SolidWorks

When you open SolidWorks 2005 for the first time on a computer, the **Welcome to SolidWorks** dialog box gives you the opportunity to customize dynamic help. You can select:

- Quick Tips to aid new users in getting started.
- Interactive What's New to point out new functionality for experienced users.
- No dynamic help neither Quick Tips nor Interactive What's New.

You can also customize the visibility of toolbars and menus on the basis of work flow in this dialog box. See **Customize by Work Flow** on page 1-10.

You can change these options at any time in the SolidWorks software.

What's New

The *SolidWorks 2005 What's New* book is available both as an Adobe Acrobat file and as an online HTML file. You can view the online version and the SolidWorks software simultaneously on screen. You can also click present to new menu items and the titles of new and changed PropertyManagers to read what is new about the command.

Online Tutorials

New lessons on Molds and Weldments have been added to the online tutorial.

When you click a tool in the online tutorial, the corresponding tool in the SolidWorks software flashes. The flashing tools appear with a blue border. When you hover the pointer over the tool image, the border changes to dark blue.

Overview Topics

Overview topics on Mold Design and Machine Design have been added to the online help. The topics lead you through industry procedures and link those procedures to the SolidWorks software functionality.

2

2D Topics

Topics on sketch relations, inferencing, and 2D drawings in the SolidWorks software have been enhanced in Moving from AutoCAD and in the SolidWorks online help.

Sketching

This chapter describes enhancements to sketching in the following areas:

- General sketch entities
- □ Offset entities
- \Box Circles
- □ Sketch and Quick Snaps
- □ Splines
- □ Splines on surfaces
- □ Offset splines
- □ Infinite lines
- □ Insert line
- □ Trims
- □ Mirrors
- □ Minimum/Maximum dimensions with arcs
- □ Sketch relations displays

General Sketch Entities

Enhancements were added to the following sketch entities:

- Autodimension
- Surface trim with 3D sketches

Autodimension

The **Autodimension** it tool on the Dimensions/Relations toolbar allows you to autodimension drawings as well as sketches (see **Autodimension** on page 10-15).

Surface Trim with 3D Sketch

You can trim surfaces using 3D sketches and the Trim Surface 🔗 tool.



Offset Entities

The **Offset Entities** tool on the Sketch toolbar includes new options in the PropertyManager under **Parameters**.



You can apply these options to offset any sketch entity, including splines (see **Offset Splines** on page 2-17).

New options include:

Add dimensions

Select Add dimensions to include the Offset Distance in the sketch. This does not affect any dimensions included with the original sketch entity.

Make Base Construction

Select Make base construction to convert the original sketch entity to a construction line.



Cap Ends

Select **Cap ends** and **Bi-directional** to extend the original non-intersecting sketch entities by adding a cap. You can create **Arcs** or **Lines** as extension cap types.



Circles

You can sketch circles that originate from the perimeter with the **Perimeter Circle** O tool. Perimeter circles extend the border of the circle from the perimeter outwards. The **Circle** O tool still originates the sketch from the center.

Both circle tools allow you to make the circle tangent to other sketch entities. Both types of circles open the same PropertyManager.



Quick Snaps Quadrant Points

When you use the **Circle** tool to originate the sketch from the center, quadrant points are added at 0/360°, 90°, 180°, and 270°. These four quadrant points are Quick Snaps (see **Sketch and Quick Snaps** on page 2-5) that facilitate sketching new circles that are tangent at that point. You can also use the Quick Snaps as the center points for other circles.





Quick Snaps quadrant points also appear on arcs, fillets, parabolas, ellipses, and partial ellipses. Quadrants with second circle tangent to first at 90 degree marker.

Quick Snaps quadrant points behave as follows:

Display. When sketching multiple circles, only the current circle displays the Quick Snaps quadrant points.

Wake up. You can wake up any previously sketched circle to display the Quick Snaps quadrant points by using any sketch tool to hover over the circle. Hovering over the circle:

- Displays the Quick Snaps quadrant points.
- Highlights the circle in a different color.
- Displays the pointer with the appropriate inference information.
Sketch and Quick Snaps

You can enable sketch snaps which behave similar to O-snaps in AutoCAD. Each sketch snap allows you to automatically snap to selected entities as you create the sketch. By default, all **Sketch Snaps** except **Grid** are enabled. Access to **Sketch Snaps** is through the **Quick Snaps** toolbar, the **Quick Snaps** [] r flyout on the Sketch toolbar, or through the shortcut menu.

Sketch Snaps

To set Sketch Snaps options:

- 1 Click **Options** in the Standard toolbar, or click **Tools**, **Options**.
- 2 On the System Options tab, click Relations/Snaps.
- 3 Select or clear **Enable snapping** to affect all sketch snaps.
- 4 Under **Sketch Snaps**, select or clear the appropriate sketch snap to affect only that item.



Sketch snaps and Quick Snaps are related, but not identical. Sketch snaps are global sketch settings that apply to all sketch commands. Quick Snaps are single, independent selections (see **Quick Snaps** on page 2-7).

Sketch snaps include the following:

Sketch Snaps	Tools	Description
Endpoints and sketch points	•	Includes endpoints and sketch points. Snaps to the end of the following sketch entities: lines, polygons, rectangles, parallelograms, fillets, arcs, parabolas, partial ellipses, splines, points, chamfers, and centerlines.
Center Points	\odot	Snaps to the center of the following sketch entities: circles, arcs, fillets, parabolas, and partial ellipses.
Mid-points		Snaps to the midpoints of lines, polygons, rectangles, parallelograms, fillets, arcs, parabolas, partial ellipses, splines, points, chamfers, and centerlines.
Quadrant Points	\diamond	Snaps to the quadrants of circles, arcs, fillets, parabolas, ellipses, and partial ellipses.
Intersections	X	Snaps to the intersections of entities that meet or entities that intersect.

Sketch Snaps	Tools	Description
Nearest	\checkmark	Supports all entities. When you clear Nearest , and all snaps are enabled, your pointer does not need to be in the immediate vicinity of another sketch entity to show inference or snap to that point. When you select Nearest , snaps are enabled only when the pointer is in the vicinity of the snap point.
Tangent	8	Snaps to tangents on circles, arcs, fillets, parabolas, ellipses, partial ellipses, and splines.
Perpendicular	*	Snaps so the pointer indicates perpendicular when sketching a line to another line.
Parallel	1	Snaps to lines, arcs, and splines.
Horizontal/vertical lines		Snaps a line sketch vertically to an existing horizontal sketch line, and horizontally to an existing vertical line sketch.
Horizontal/vertical to points	•• •	Snaps a line sketch vertically or horizontally to an existing sketch point.
Length	<mark> ↔ </mark>	Snaps lines to the increments that are set by the grid, without requiring display of the grid.
Grid	#	Snaps sketch entities snap to the grid's vertical and horizontal divisions. This is the only sketch snap that is not active by default.
Angle	∠	Snaps to angles. To set the degrees, click Tools , Options , System Options , Sketch , select Relations/Snaps , and set a value for Snap angle .

All **Sketch Snaps** are available for the sketch entities listed as well as model edges in parts, assemblies, and drawings.

On sketches with multiple entities, only the current sketch entity displays snaps. You can wake up any snap points such as quadrant points, mid-points, and so on, for previously created sketch entities.

To wake up Sketch Snaps:

- 1 Create any sketch that includes multiple entities.
- 2 With the any sketch tool selected, hover over the previously sketched entity.
 - The sketch entity changes color.
 - The appropriate Quick Snaps appears on the sketch entity.
 - The pointer changes, adding the appropriate inference information.

Quick Snaps

Quick Snaps are instantaneous, single operation Sketch Snaps. For example, sketching a line from start to finish, is a single operation.

You can double-click any Quick Snaps on the toolbar to retain the snap capability for multiple instances of the same sketch entity, or until you select a different Quick Snaps.

To control Quick Snaps:

- 1 In sketch mode, with any sketch tool selected:
 - Menu. Click Tools, Relations, Quick Snaps.
 - Shortcut menu. Right-click, select Quick Snaps.

Right-click in a sketch, and you can also select **Relations/Snaps Options** to display **System Options**, **Sketch**, **Relations/Snaps**.

- **Toolbar**. Display the Quick Snaps toolbar.
- 2 Select the appropriate Quick Snaps to shift the focus.



Selecting Quick Snaps from either the toolbar or the shortcut menu filters out other Quick Snaps, enabling you to focus on a particular capability. The **Enable snapping** option under **Tools**, **Options**, **System Options**, **Relations/Snaps**, can be cleared when using Quick Snaps.

To use Quick Snaps:

- 1 Click **Circle** on the Sketch toolbar, or click **Tools**, **Sketch Entities**, **Circle** and sketch two, separate circles of any diameter.
- 2 Click Line 🔨 on the Sketch toolbar, or click **Tools**, **Sketch Entities**, Line.
- 3 Right-click, select Quick Snaps, Tangent Snap 🔊
- 4 Starting at any point along the perimeter of either circle, sketch a line and drag it along the perimeter. The line remains tangent at any point along the perimeter of the circle.



5 As you drag the line, extend it to any quadrant point along the perimeter of the second circle.

The line snaps, and is tangent to the perimeter of the second circle.

6 Close the sketch.

Splines

Enhancements to splines include the following areas:

- Sketching a spline
- Controlling the shape
- Adding relations

Sketching a Spline

When you sketch a spline, each spline point displays spline handles. The handles include vectors originating from the spline point.

When you select the spline handle:

- The handle changes color.
- The pointer changes to
 The appropriate X Coordinate
 or Y Coordinate
 highlights in the PropertyManager.

The color of the spline handle depends on its state. Handles can be one color, or the shaft and the arrowheads can be different colors. Some spline handle states include:

Colors	State of Spline Handles	Example
Gray	Spline handle is not selected.	700
Red	Hover over spline handle with the pointer.	
Green	Select the spline handle.	7
Blue	Spline handle is active, with no constraints. You can drag or rotate the spline handle.	
Black shaft with blue arrowheads	Spline handle is active, with some constraints. You cannot rotate the handle, due to the horizontal relation, but you can still drag the handle left and right.	*

Splines PropertyManager

New options to control splines are available from the PropertyManager and include the following:

Tangent Driving

When you drag an arrow on a spline handle, it selects **Tangent Driving** in the PropertyManager. With **Tangent Driving** selected, you control splines using:

- Tangent Magnitude 💉
- Tangent Radial Direction

Tangent Magnitude

Tangent Magnitude controls the tangency vector by modifying the spline's degree of curvature at the spline point.

Select one of the arrowheads and drag the handles left or right, while maintaining the same direction vector, to diminish the angle. As the angle diminishes, the entities straighten on either side of the through point (the point through which the handles pass).



Although the through point and the tangent direction remain constant, the rest of spline may change when you modify the tangent magnitude.

Tangent Radial Direction

Tangent Radial Direction > controls the tangency direction by modifying the spline's angle of inclination relative to the X, Y, or Z axis.

Select one of the arrowheads, and rotate either handle by dragging up or down while minimizing the effect on the tangent magnitude. The spline's angle of inclination increases or decreases accordingly, relative to the X, Y, or Z axis, as shown below.



Although the through point and the tangent direction remain constant, the rest the spline may change when you modify the tangent radial direction.

Flip Relation

You can flip relations in the PropertyManager for tangency and equal curvature relations between the following entities:

- Splines and lines
- Splines and arcs
- Multiple splines

To flip relations:

- 1 Open sketching\flip.sldprt from the File Explorer 👔
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Select the spline from the top sketch (spline and line), as shown.



4 In the PropertyManager, under Existing Relations, right-click Tangent0 and select Flip Relation.



- 5 Select the spline from the bottom sketch (spline and arc).
- 6 Under Existing Relations, right-click Equal Curvature1, and select Flip Relation. The curvature comb on the spline flips.
- 7 Click **OK** 🕢.



Spline Tools and Shortcut Menu Controls

Use the Spline Tools toolbar or right-click on the spline to display the following new options:

Add Tangency Control

Select **Add Tangency Control** *to* change the tangency vector by modifying the spline's degree of curvature. New tangency control handles also create a new spline point with an active spline handle.

To add tangency control:

- 1 Select a spline in the graphics area.
- 2 Select Add Tangency Control *from the Spline Tools toolbar, or right-click and select Add Tangency Control.*

An active spline handle drops on to the spline adjacent to the position of your pointer.

- 3 Drag the pointer $\frac{1}{2}$ following the shape of the spline to position the spline handle.
- 4 Click the pointer to place the spline handle.

A new spline point appears with an active tangency control handle.



To remove the tangency control handle, select the handle and press **Delete**.

Adding tangency controls at an existing spline point using the **Add Tangency Control** tool or the shortcut menu, is identical to activating an existing tangency vector control handle in the graphics area. Adding a new tangency control handle selects **Tangent Driving** in the PropertyManager, allowing you to:

- Drag the handles to change the value of **Tangent Magnitude** *I*.
- Rotate the handles to change the value of Tangent Radial Direction Y.

Add Curvature Control

Select **Add Curvature Control** to manipulate the radius of curvature at any spline point. The curvature control pointer can be on either side of the spline, depending on negative or positive curvature.

To add curvature control:

- 1 Select the spline in the graphics area.
- 2 Select Add Curvature Control K from the Spline Tools toolbar, or right-click and select Add Curvature Control.

An add curvature pointer drops on the spline. Placement is relative to the closest position of your pointer.

- 3 Drag the pointer following the shape of the spline to position the curvature control pointer.
- 4 Click in the graphics area to place the curvature control pointer.

This adds a new spline point that includes a:

- Curvature control handle
- Tangency control handle



To remove the curvature control pointer, select the handle and press **Delete**.

Modifying Curvature Control

To manipulate curvature control:

To adjust the radius of curvature select the ball of the curvature control pointer and drag it in either direction, along the vector of the handle.



Spline handles and curvature control pointers tend to snap to the nearest spline point, but you can drag them anywhere along the spline.

Using the pointers to place tangency control and curvature control: handles





Tangency at spline point



Add Curvature Control

Curvature outside Curvature at spline spline point point

Show Spline Handles

Show or hide all spline handles.

Controlling Splines

To control a spline:

1 Open sketching\spline_control_new.sldprt from the File Explorer 👔



- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Hold down **Ctrl** and select the line that starts at the origin, and the spline.
- 4 In the PropertyManager, under Add Relations, click Tangent A.



The tangent relation adds a tangent control handle, and the tangency relations is displayed.



The tangent **{** relation allows you to modify the tangency magnitude, but not the tangency radial direction.

- 5 In the PropertyManager, right-click in **Selected Entities**, select **Clear Selections**, and then in the graphics area hold down **Ctrl** and select the spline and the arc.
- 6 Under Add Relations, click Equal Curvature ^c=



The equal curvature relation adds a curvature control handle, and the equal and the tangency relations is displayed.



- 7 Click **OK** 🖌
- 8 Select the spline, right-click, and select Add Tangency Control 🥐

9 Drag the tangency control handle, and click to position it between the third and fourth spline points, as shown.



- 10 Select the handle, and in the PropertyManager under Parameters, set Tangent Radial Direction to 0.
- 11 Click **OK** \bigcirc and close the sketch.

The final spline should resemble the one below:



Add Relations to Splines

You can add relations between spline points, between spline handles, and between spline handles and external sketch entities.

For example, you can add a curvature constraint between a spline and an arc so the curvature between the two entities is equal.

In the **Spline** PropertyManager, the **Add Relations** group includes new selections that appear when the relevant geometry exists in the sketch.

Relations with Splines				
Constraints to internal spline points	Constraints to end spline points			
Coincident Concentric Perpendicular Tangent Mid-point Fix	Horizontal Vertical Tangent Coincident Concentric Mid-point Fix Merge			
Constraints to internal handles	Constraints to end handles			
Tangent	Equal Curvature Tangent			
Constraints between handles				
Parallel Horizontal Vertical Curvature				

Restrictions with Splines

The following restrictions exist when controlling splines:

- With 3D splines, curvature control is not available.
- Surface splines cannot cross multiple faces (see **Splines on Surfaces** on page 2-16).

New Tools on the Spline Tools Toolbar

The **Fit Spline [** tool is moved from the Sketch toolbar to the Spline Tools toolbar.

The **Show Curvature Combs** A tool was added to the Spline Tools toobar.

Splines on Surfaces

You can sketch splines on surfaces. Splines sketched on surfaces include standard spline attributes, as well as the following capabilities:

- Add and drag points along the surface.
- Generate preview that is automatically smoothed through the points.



All spline points are bounded to the surface on which they are sketched. Splines cannot cross multiple surfaces.

Benefits of sketching splines on surfaces include:

- In part and mold design, surface splines enable you to create more visually accurate parting lines or transition lines.
- With complex sweeps, surface splines facilitate creating guide curves that require curves bounded to surface geometry.

To sketch a spline on a surface:

- 1 Open sketching\spline-on-surface.sldprt from the File Explorer 🙆
- 2 Click Spline on Surface 🕢 on the Sketch toolbar, or click Tools, Sketch Entities, Spline on Surface.
- 3 Sketch a spline on surface that extends from one profile to the other profile.



4 Click **OK** 🕢.

You can apply any of the spline controls (see **Splines PropertyManager** on page 2-9) to splines on surfaces.

Offset Splines

You can offset splines. With offset splines, you can apply these options under **Parameters**:

- Cap ends. Adds a cap to the geometry when **Bi-directional** is selected.
- Make base construction. Converts the original geometry to construction geometry.



You cannot offset a spline from an existing offset. You cannot offset fit splines, ellipses, or parabolas. You cannot create an offset spline if the results of the offset self-intersect, or use offset with infinite lines (see **Infinite Lines** on page 2-18).

To offset a spline:

- 1 Open sketching\offset-spline.sldprt.
- 2 Right-click Sketch1 in the FeatureManager design tree, and select Edit Sketch.
- 3 Click Offset Entities 🗩 on the Sketch toolbar, or click Tools, Sketch Tools, Offset Entities.
- 4 Select the sketch in the graphics area.
- 5 In the PropertyManager, under **Parameters**:
 - a) Set **Distance** ito 5.
 - b) Select Add dimension.
 - c) Select Bi-directional.
 - d) Select Make base construction.
 - e) Select Cap ends, Arcs.
- 6 Click **OK** 🕜 and close the sketch.



Infinite Lines

When sketching lines with the Line tool, you can create lines of infinite length. This option is available in the Insert Line PropertyManager, regardless of line orientation. Capabilities include:

- Trim lines of infinite length when they intersect other sketch entities using the Trim Entities i tool (see Trim on page 2-20).
- Add relations such as Horizontal.

To create lines of infinite length:

- 1 Create a sketch using the Line \setminus tool.
- 2 In the PropertyManager, under **Options**, select **Infinite length**.
- 3 Click **OK** 🕢 and close the sketch.

Insert Line

The **Insert Line** PropertyManager enables you to sketch multiple lines. For each line you sketch, you can select different combinations of settings under **Orientation**, **Options**, or **Parameters**.

Orientation

You sketch lines using any of four orientations including:

- **As sketched**. With the click-drag method, sketch a line in any direction until you release the pointer. With the click-click method, sketch a line in any direction, and continue sketching other lines in any direction, until you double-click.
- Horizontal. Sketch a horizontal line until you release the pointer. You can also enter a value for Length under Parameters to create a horizontal line with that value. To add and display the dimension, select Add dimensions.
- Vertical. Sketch a vertical line until you release the pointer. You can also enter a value for Length under Parameters to create a vertical line with that value. To add and display the dimension, select Add dimensions.
- Angle. Sketch a line at an angle until you release the pointer. The angle is created relative to the horizontal. You can also enter values for Length and Angle under **Parameters** to create a line with those values. To add and display the dimension, select Add dimensions.

Options

All four line orientations under **Orientation** allow you to select either of the following under **Options**:

- For construction. Creates a construction line.
- Infinite length. Creates a line of infinite length which you can later trim (Trim on page 2-20).

Parameters

The **Parameters** group appears when you select all orientations except **As sketched**. With **Angle** selected, you can specify angle and length.



Some selections under **Orientation** and the **Infinite Length** selection under **Options** override settings for **Quick Snaps**.

Once you sketch a line, the **Line Properties** PropertyManager appears. It includes new groups, such as **Add Relations** or **Additional Parameters**. You can:

- Edit the line using selections from the groups in the Line Properties PropertyManager.
- Continue sketching using the same line orientation.
- Select a different line orientation by clicking **OK (v)** or by double-clicking. This returns you to the **Insert Line** PropertyManager which includes the **Orientation** group.

Insert Line with 3D Sketches

With 3D sketches, only **As sketched** is available as a line orientation. Both **For construction** and **Infinite length** are available under **Options**.

Trim

Trim Entities has moved from a dialog box to the PropertyManager. The **Trim Entities** tool includes control over what entities to trim, as well the capability to extend sketch entities.

Power Trim

Select **Power trim** in the PropertyManager 📫 to:

- Extend sketch entities.
- Trim single sketch entities to the nearest intersecting entity as you drag the pointer.
- Trim one or more sketch entities to the nearest intersecting entity as you drag the pointer, and cross the entity.

To trim using power trim:

- 1 Open sketching\trim_power_trim.sldprt from the File Explorer
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Click Trim Entities in the Sketch toolbar, or click Tools, Sketch Tools, Trim.
- 4 In the PropertyManager, under **Options**, click **Power trim**
- 5 Click in the graphics area, just below the sketch entity (1), as shown, and drag the pointer across the sketch entity.

A marker appears k_{k} as it reaches the sketch entity, and disappears as the sketch entity is trimmed.



6 Continue to drag the pointer over the remaining sketch entities (2, 3, 4, and 5), as shown.

A motion trail is created as you drag the pointer and trim the entities.



7 Click **OK** 🕢 and close the sketch.

Corner

Select **Corner** \rightarrow to modify two selected entities until they intersect at a virtual corner. A virtual corner is created if you extend one or both entities along their natural path. Factors governing the **Corner** trim option include:

- The sketch entities can be different. For example, you can select a line and an arc, a parabola and a line, and so on.
- Depending on the sketch entities, the trim operation can extend one sketch entity and shorten the other, or extend both sketch entities.
- Behavior is affected by which end of the sketch entities you select. The trim operation can take place at either end of the sketch entities you select.
- Behavior is not affected by the order in which you select the sketch entities.
- If no natural intersection is geometrically possible between the two entities selected, the trim operation is invalid.

To trim using corner:

- 1 Open sketching\trim_corner.sldprt from the File Explorer 🔯
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Click **Trim Entities** in the Sketch toolbar, or click **Tools**, **Sketch Tools**, **Trim**.
- 4 In the PropertyManager, under **Options**, click **Corner** +.
- 5 Select the arc and the vertical line, as shown below.

The arc and the vertical line extend and meet at the common vertex.





Select the arc.

Select the vertical line to extend both entities

6 Click **OK** 🕑 and close the sketch.

Trim away inside

Select **Trim away inside** in the PropertyManager to trim open entities that exist within two selected boundaries.



A closed sketch entity, such as an ellipse, creates a bounding region in the same manner as selecting two open entities as the boundaries.

Factors governing the Trim away inside option include:

- The sketch entities you select as the two bounding entities can be different.
- The sketch entities you select to trim must either intersect each bounding entity once, or not intersect the two bounding entities at all.
- The trim action removes any valid sketch entities inside the selected boundaries.
- Valid sketch entities to trim include open sketch segment (but not closed sketch entities such as circles).

To trim using trim away inside:

- 1 Open sketching\trim_inside.sldprt from the File Explorer ն
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Click **Trim Entities** on the Sketch toolbar, or click **Tools**, **Sketch Tools**, **Trim**.
- 4 In the PropertyManager, under **Options**, click **Trim away inside #**.
- 5 Select the small circle, as shown, as the bounding entities.
- 6 Select the vertical line that intersects the circle, as shown, as the segment to trim.



Because the line intersects the circle, whether you select the line segment inside the circle, or the line segments outside the circle, the inner segment is removed.



7 Click **OK** 🕑 and close the sketch.



Trim away outside

Select **Trim away outside *** in the PropertyManager to trim open entities that exist outside two selected boundaries. Factors governing the **Trim away outside** option include:

- The sketch entities you select as the two bounding entities can be different.
- Boundaries are not limited by the endpoints of the sketch entities you select. The boundaries are defined as an infinite continuation of the sketch entities.
- The trim action results removes any valid sketch entities that lie outside the selected boundaries.
- Valid sketch entities to trim include open sketch segments (but not closed sketch entities such as circles).

To trim using trim away outside:

- 1 Open sketching\trim_outside.sldprt from the File Explorer 🛜
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Click **Trim Entities** on the Sketch toolbar, or click **Tools**, **Sketch Tools**, **Trim**.
- 4 In the PropertyManager, under Options, click Trim away outside [‡]≢.
- 5 Select the angled line (1), and the spline (2) as the bounding entities, as shown.

The boundaries selected are not limited by the endpoints.

- 6 Select the arc, between the bounding entities, as shown. The segment is removed.
- 7 Click **OK** \bigcirc and close the sketch.





Trim to Closest

Select **Trim to closest** \rightarrow in the PropertyManager to trim or extend the selected sketch entities. Factors governing the **Trim to closest** trim option include:

- Remove the selected sketch entity up to the closest intersection with another sketch entity.
- Extend the selected entity. The direction in which the entity extends, depends on the direction you drag the pointer.

To trim using trim to closest:

- 1 Open sketching\sketch_trim_closest.sldprt from the File Explorer 🙆
- 2 Right-click Sketch1 and select Edit Sketch.
- 3 Click **Trim Entities** on the Sketch toolbar, or click **Tools**, **Sketch Tools**, **Trim**.
- 5 Select each of the sketch entities, as shown, so that the final sketch only includes a single, exterior contour.





Select the sketch segments that are highlighted within the ellipse.

- The resulting sketch is a single, exterior contour.
- 6 Click **OK (v)** and close the sketch.

Mirror Entities has moved from a dialog box to the PropertyManager. The **Mirror Entities** tool now includes the following capabilities:

- Mirror to only include the new entity, or both the original and the mirrored entity.
- Mirror some or all of the sketch entities.
- Mirror about any type of line, not just a construction line.
- Mirror about edges in a drawing, part, or assembly.

The Sketch toolbar also includes the **Dynamic Mirror Entities** is tool that allows you to preselect a sketch entity to mirror about, then sketch additional entities. The **Dynamic Mirror Entities** is tool requires that you use a centerline to mirror about.

To mirror selected entities:

- 1 Open sketching\mirror.sldprt from the File Explorer 2
- 2 Right-click Sketch2 and select Edit Sketch.
- 3 Click Mirror Entities 🛕 on the Sketch toolbar, or click Tools, Sketch Tools, Mirror.
- 4 In the PropertyManager, under **Options**, select the two outer circles, as shown, for **Entities to mirror A**.



5 Select Copy.

6 Click in **Mirror about** 1, and then select the horizontal edge, as shown.



Minimum/Maximum Dimensions with Arcs

When you add dimensions between an arc and any other sketch entity using the **Smart Dimensions** tool, you can create linear and ordinate dimensions to minimum, center, and maximum arc extents.

The minimum and maximum arc extents are confined to 15° zones. The minimum zone is located closest to the entity you measure from. When you move beyond the 15° zones, the dimension reverts to a linear dimension between the center of the arc and the other sketch entity.

The dimension between two arcs provides two 15° zones where you can dimension to the perimeter of the arc as opposed to the center of the arc. The 15° zones are based on an imaginary line between the centers of the arcs. When you dimension between another sketch entity and an arc, the imaginary line is from the initial position on the sketch entity to the center of the arc.



To dimension to the arc:

- 1 Sketch a circle and an arc.
- 2 Click Smart Dimensions 🐼 on the Dimensions and Relations toolbar, or click Tools, Dimensions, Smart.
- 3 Select the center of the arc, and move the pointer on a straight line towards the center of the circle until you reach the closest perimeter of the circle (minimum).



- 4 Move the pointer up and down along the perimeter, staying within the 15° zone. Move the pointer across to the other side of the circle (maximum). Note that an equivalent 15° zone exists.
- 5 Move outside the 15° zone on either side of the perimeter of the circle, and the dimension changes to linear between the two arc centers.

Sketch Relations Display

You can now simultaneously display multiple relations between multiple sketch entities. Display enhancements are available when you select:

- Edit Sketch. Display symbols representing relations for all sketch entities in the graphics area.
- **Display/Delete Relations** Display and highlight symbols in the graphics area by selecting the item under **Relations** in the PropertyManager.

To automatically display sketch relations:

Click View, Sketch Relations.

When appropriate, the symbols in the graphics area include numerical subscripts to indicate relations between two corresponding entities. The subscript also identifies the incidence (starting with **0**) of that relation, as listed in the **Display/Delete** PropertyManager under **Relations**.

Edit Sketch mode

The sketch on the right includes various symbols that represent relations.



Vertical entities

Midpoint of line entities

Equal to corresponding symbol with same subscript

Perpendicular entities



When you display relations symbols with the **Display/Delete** PropertyManager, you can select any item under **Relations** to highlight the relevant sketch entities and relation symbols.



Chapter 2 Sketching

Features

This chapter describes enhancements to features in the following areas:

- □ General
- □ Deforms
- □ Extrusions
- □ Fillets
- □ Flexes
- $\hfill \square$ Indents
- □ Lofts
- □ Mirrors
- □ Move/Copy Bodies
- □ Split Line curves
- □ Sweeps

General

Smart Selection

Smart Selection is a new shortcut menu item that enhances edge or guide curve selection when you create lofts or sweeps. Smart selection can propagate edge selection along these edge types:

- Chains
- Tangents
- Open loops

To use smart selection to create a lofted surface:

- 1 Open SmartSelection.sldprt from the File Explorer
- 2 Click Lofted Surface U on the Surfaces toolbar, or click Insert, Surface, Loft.
- In the PropertyManager, under Profiles,
 right-click the edge shown in the graphics area for
 Profile ¹⁰ and select Start Smart Selection.



You must select exactly on the edge or the item does not appear in the menu.



A Chain a callout appears, indicating smart selection has started for a chain. In the PropertyManager, Smart Selection<1> appears for Profile 2^{0} .

- 4 Move the pointer over a non-contiguous edge and note that the edge does not highlight because it is not an acceptable selection to chain. Only valid smart selection edges highlight when you move the pointer over them.
- 5 Select the next two edges to the left of the selected edge to add them to the chain.

A **Tangent** C callout appears, indicating the next smart selection edges are tangent.

6 Click the **Tangent** Click the **Tangent**

The chain extends to select all tangent edges. The **Tangent C** callout changes color to indicate it is selected.

7 Right-click anywhere in the graphics area and select **End Smart Selection**.



8 Use smart selection to select the five opposing edges for **Profile** ¹⁰, starting from the top edge.

Smart Selection <2> is listed for the new profile name. A preview of the surface loft appears.



If you have trouble creating the surface loft or activating smart selection, zoom to the area to make sure you pick the correct edges.

9 Click **OK** (), then close the file without saving changes.





To use smart selection to trim surface lofts:

- 1 Open SmartSelection.sldprt from the File Explorer
- 2 Click Lofted Surface U on the Surfaces toolbar, or click Insert, Surface, Loft.
- 3 In the PropertyManager, under **Profiles**, right-click the top edge shown in the graphics area for **Profile** □⁰ and select **Start Smart Selection**.
- 4 Drag the black circular handle on the right end of the edge to extend it approximately as shown.



You can extend or shorten the edge length to adjust its size.

- 5 Right-click anywhere in the graphics area and select **End Smart Selection**.
- 6 Right-click the bottom edge in the graphics area and select **Start Smart Selection**.

A preview of the surface loft appears.







7 Drag the black circular handle on the right end to extend it approximately as shown.

The loft preview adjusts as you trim the profile line.

- 8 Right-click anywhere in the graphics area and select **End Smart Selection**.
- 9 Click **OK** 🖌

The surface loft is trimmed to the adjusted smart selection profile.



Deforms

Enhancements to the deform feature include:

- A new Surface Push deform type
- New Curve to curve match tangency options

Surface Push Deform Type

The new **Surface Push** deform type deforms a target body by pushing a tool body through it. You select a customizable pre-built tool body, such as a polygon or sphere, or use your own tool body. Use the triad callout in the graphics area to size the tool body.

Wherever the triad is in the graphics area, it controls the tool body movement. Drag the triad to push the tool body into the target body to deform the target body.





If the triad is positioned outside the model body, when you drag starting from the triad, only the tool body moves; the triad does not move.

To restrict the tool body axis of movement to a specific axis, drag a triad handle: red X axis, green Y axis, or blue Z axis. To rotate the tool body around a specific axis, right-click a triad handle and drag. The pointer $\frac{\text{end} \cdot \text{P}}{\text{end} \cdot \text{P}}$ guides your action: left-click pans the tool body, while right-click rotates it. To move the tool body on a specific plane, drag the triad in the area between the axes handles.

To set a specific tool body location, use the **Delta X**, **Delta Y**, or **Delta Z** settings under **Tool Body Position** in the PropertyManager. You can align the triad to the target body or return it to the original position with shortcut menu options.

To create a surface push deform:

- 1 Open **Deform_Push.sldprt** from the **File Explorer**
- 2 Click **Deform (o**n the Features toolbar, or click **Insert**, **Features**, **Deform**.
- 3 In the PropertyManager, under Deform Type, select Surface push.
- 4 Under **Push Direction**:
 - a) Select the top of the body in the graphics area for **Deform direction**.

A handle points upwards, indicating that the tool body pushes normal to the selected face.

- b) Select Show preview.
- 5 Under Deform Region:
 - a) Select anywhere on the body in the graphics area for **Bodies to be deformed** \bigotimes .
 - b) Select Sphere in Tool Body 1.
 - c) Set **Deform deviation** The to **5** to shape the transition area between the tool body and the target body.

A preview appears of the tool body deforming the target body.

6 In the graphics area, drag the white area of the callout so the entire triad is visible, then set the callout radius to **75** to set the size of the sphere.

Now use the triad to shape the deform feature.

1 Select the triad's red handle and drag the sphere along the X axis.

The sphere moves along the X axis, deforming the target body.



If only the top face seems to deform in the preview, under **Deform Region**, make sure you have not selected a face under **Additional** faces to be deformed



- 2 Drag the triad from between the green and red arrows to deform the body along the X-Y plane.
- 3 In the PropertyManager, under Tool Body Position, set Delta Y AY to 60.

The tool body repositions itself to 60mm above the Y axis starting position.

4 Right-click the triad center and select Align to component.



The triad returns to the start position, which is the origin of the body being deformed.

5 Click **OK** 🖌

Curve to Curve Match Tangency Options

When you create a deform feature with the **Curve to curve** option, you can match tangency between surfaces. The new blue arrows indicate the direction of tangency matching. You can use a **Curve direction** or **Surface tangent** match.

For a **Curve direction** match, the body is deformed by rotating the tangent direction vector of the initial curve to match the tangent direction vector of the target curve. The body is deformed normal to the curve, so the body thickness is maintained.



Tangency matching arrow

For a **Surface tangent** match, the body is deformed by rotating and matching the surface tangent of the initial curve to the surface tangent of the target curve.

To use the Curve direction option:

- 1 Open Deform_CurveDirection.sldprt from the File Explorer
- 2 Click **Deform** on the Features toolbar, or click **Insert**, **Features**, **Deform**.
- 3 In the PropertyManager, under **Deform Type**, select **Curve to curve**.

- 4 Under Deform Curves, select the lines shown for Initial curves and Target curves 2.
- 5 Under **Deform Region**:
 - Select Fixed edges and Uniform.
 - Select the body for **Bodies to be deformed** 😭.
- 6 Under Shape Options, select Curve direction for Match.
- 7 Click **OK** 🖌

The body is deformed normal to the curve while the body thickness is maintained.

To use the Surface tangent option:

- 1 Open **Deform_SurfaceTangent.sldprt** from the **File Explorer**
- 2 Click **Deform** on the Features toolbar, or click **Insert**, **Features**, **Deform**.
- 3 In the PropertyManager, under **Deform Type**, select **Curve to curve**.
- 4 Under **Deform Curves**, select the lines in the graphics area as shown for **Initial curves** and **Target curves** \checkmark .
- 5 Under Deform Region:
 - Select Fixed edges and Uniform.
 - Click in **Fixed curves/edges/faces \u0065** and select the fixed edge as shown.
- 6 Under Shape Options, select Surface tangent for Match.

The preview shows the tangent surface approaching the edge from the opposite direction from what is desired.

- 7 Select **Reverse tangent** so both blue tangency matching arrows point towards the left as shown.
- 8 Click **OK** 🖌





Deformation using Curve direction option



Extrusions

You can specify the start plane of an extrusion to be a surface, face, plane, vertex, or an offset plane parallel to the sketch plane. Previously, extrusions always started from the sketch plane.

To create an extrusion that starts from an offset plane:

- 1 Open a new part document and click **Extruded Boss/Base on the Features** toolbar, or click **Insert**, **Boss/Base**, **Extrude**.
- 2 Sketch a rectangle on the **Front** plane, then exit the sketch.
- 3 In the PropertyManager, under the new **From** box:
 - a) Select Offset in Start Condition.
 - b) Set Enter Offset Value to 20.

The preview shows the extrusion starting on a plane that is offset from the **Front** plane by 20mm.

4 Click **OK** 🖌

Fillets

You can create face fillets with a constant width by selecting the new **Constant width** option in the **Fillet** PropertyManager.

To create a face fillet with a constant width:

- 1 Open ConstantWidthFillet.sldprt from the File Explorer 🎑.
- 2 Click Fillet 🙆 on the Features toolbar, or click Insert, Features, Fillet/Round.
- 3 In the PropertyManager, under Fillet Type, select Face fillet.
- 4 Under Items To Fillet:
 - Set Radius 🏹 to 3.
 - Select one cylinder for Face Set 1 , and the other for Face Set 2 .
- 5 Click **OK** 🖌.

The fillet has a variable width.

6 Right-click Fillet1 in the FeatureManager design tree and select Edit Feature.

- 7 In the PropertyManager, under Fillet Options, select Constant width.
- 8 Click **OK** 🖌

The fillet has a constant width.

Flexes

The new flex feature bends, twists, tapers, or stretches a solid or surface body to a set value around an area specified by two user-defined planes. Areas outside the specified area retain their geometry. Use the triad to position the flex feature's central point. The triad start position is the model's center of gravity. With the shortcut menu, you can align the triad to one of the bounding planes or reset the flex feature.

Only one type of flex is permitted per flex feature. To apply more than one type of flex, create separate flex features.

To bend and twist a solid body using flex features:

- 1 Open Flex.sldprt from the File Explorer
- 2 Click **Flex** [3] on the Features toolbar, or click **Insert**, **Features**, **Flex**.
- 3 In the PropertyManager, under **Flex Input**:
 - Select the body in the graphics area for **Bodies for Flex G**. a)
 - You can add flex features to multiple bodies.
 - b) Select **Bending** for the flex type.
 - c) Select **Hard edges** to create the feature using analytical geometry.
- 4 Under Trim Plane 1 and Trim Plane 2, set the Plane 1 and Plane 2 trimming distance to **20** so the bend area starts 20mm from each edge.
- 5 Under Flex Input, set Angle M to 60 to bend the body 60 degrees.

A preview of the bend appears.

6 Click **OK** 🕢.

Add another flex feature to twist the body.

- 1 Click Flex 👔 on the Features toolbar, or click Insert, Features, Flex.
- 2 Select the body for **Bodies for Flex** \mathcal{A} .
- 3 Select **Twisting** for the flex type.
- 4 Leave the Trim Plane 1 and Trim Plane 2 trimming distance at **0** so the entire body twists.
- 5 Under Flex Input, set Angle 📉 to 100 to twist the body 100 degrees.
- 6 Drag the triad in the graphics area back and forth along the body to see how this affects the twist.

To restrict movement to a specific axis, drag one of the colored triad handles. See Surface Push Deform Type on page 3-4 for more information about the triad.

7 Click OK 🖌





Indents

The new indent feature creates a pocket inside a target body that closely matches the contour of a selected tool body. You specify the clearance between the target body and the tool body, and the thickness of the area deformed by the indent feature. The indent feature can deform or cut material from the target body.



If the tool body is a surface, and you are cutting material, a manipulator appears to control the cut direction.

The indent feature uses the form of the tool body to create a pocket in the target body, so more faces, edges, and vertices appear in the final body than in the original body. This differs from the deform feature, where the number of faces, edges, and vertices remains unchanged in the final body.

The indent feature shape updates if you change the shape of the original tool body used to create the pocket.

Note these requirements:

- To deform material, the target body must be in contact with the tool body. To cut material, the target and tool bodies do not have to be in contact with each other.
- The target body or the tool body must be a solid body.

To create a indent feature:

- 1 Open Indent.sldprt from the File Explorer
- 2 Click Indent 💿 on the Features toolbar, or click Insert, Features, Indent.
- 3 In the PropertyManager, under Selections:
 - a) Select the body shown in the graphics area for **Target Body**
 - b) Select **Keep Selections** to retain the selected target body material.
 - c) Select anywhere on the extruded feature in the middle of the target body, as shown, for Tool Body Region .


- 4 Under Parameters:
 - Set Thickness \swarrow_1 to 2 to set the indent feature thickness.
 - Set **Clearance** to **4** to create a 4mm clearance between the tool body and the target body.



Lofts

Enhancements to the loft feature include:

- General enhancements
- Curvature continuity
- Guide curve alignment
- Guide curve influence
- Individual segment weight control
- Mesh previews
- Synchronization

General Enhancements

Centerlines

Centerlines can co-exist with guide curves. Previously, you could not use centerlines with guide curves.

PropertyManager Design

In addition to changes to the **Loft** PropertyManager indicated in the Lofts section, note these changes:

Under Start/End Constraints:

- The Start/End Tangency box has been renamed to Start/End Constraints to reflect the new Curvature to Face option.
- Start tangency type and End tangency type have been renamed to Start Constraint and End Constraint.

Under Options:

- The **Maintain tangency** option has been renamed to **Merge tangent faces** to better reflect its functionality, which is unchanged.
- Advanced smoothing has been removed because this functionality is now automatically applied.

Curvature Continuity

A new **Curvature to Face** constraint is available for the start and end profiles. This curvature creates a smoother, more visually appealing loft than was previously possible.

To create a loft using Curvature to Face:

- Open Loft_CurvatureContinuous.sldprt from the File Explorer <a>[]
- 2 Click Lofted Surface 🔱 on the Surfaces toolbar, or click Insert, Surface, Loft.
- 3 In the PropertyManager, under **Profiles**, select the two edges shown in the graphics area for **Profile** ^{□0}.



Select the profiles in locations directly across from one another so the loft geometry is not self-intersecting.

The preview shows abrupt changes at the start and end of the loft as it meets the surfaces

- 4 In the PropertyManager, under Start/End Constraints, select Curvature To Face in Start constraint and End constraint.
- 5 Click **OK** 🖌

The loft is smoother and more visually appealing because a continuous curvature (C2 continuity) is applied to the loft and surfaces.



Profile edges



Guide Curve Alignment

You can specify the alignment vector and an angle to apply to the loft at guide curves. This lets you maintain a draft angle along the sides of a loft or ensure that the highest point of a loft remains tangent to a guide curve.

To specify the alignment vector and apply an angle to the loft at a guide curve:

- 1 Open Loft_GuideCurveAlign.sldprt from the File Explorer 🎑.
- 2 Click **Draft Analysis** on the Mold Tools toolbar, or click **Tools**, **Draft Analysis**.
- 3 In the PropertyManager, under Analysis Parameters:
 - a) Select Top Plane in the FeatureManager design tree for Direction of Pull.
 - b) Set Draft Angle 📉 to 15.
 - c) Click Calculate.
- 4 In the graphics area, move the pointer along the edge defined by the guide curve.

The pointer reports the draft angle as approximately 20 degrees.

5 Click Cancel 🚺.

Now set the draft angle at the guide curve.

- 1 Right-click **Surface-Loft1** in the FeatureManager design tree and select **Edit Feature**.
- 2 In the PropertyManager, under Guide Curves:
 - a) Select GuideCurve1 in Guide Curves 🔊.
 - b) Select Direction Vector in GuideCurve1-Tangency for Type.
 - c) Select **Top Plane** in the FeatureManager design tree for **Direction Vector** *▶* so the draft is applied normal to that plane.
 - d) Set Draft angle to 15.
- 3 Click OK 🕢.
- 4 Use the draft analysis tool again with the same AnalysisParameters to check the draft along the guide curve edge.

The draft angle is approximately 15 degrees whenever geometrically possible.



Draft angle -20.426



Guide Curve Influence

You have more control of guide curve influence than was previously possible, which allows you to create specific geometry with a minimal number of guide curves.

In the Loft PropertyManager, under Guide Curves:

- **Guide influence** has been renamed to **Guide curves influence** to reflect enhanced control of guide curves.
- The options **Default** and **Local** have been removed. New options, **To next guide**, **To next sharp**, and **To next edge** provide more control than was previously possible.

To control guide curve influence:

- 1 Open Loft_GuideCurveInfluence.sldprt from the File Explorer
- 2 Click Lofted Boss/Base [3] on the Features toolbar, or click Insert, Boss/Base, Loft.
- 3 In the PropertyManager, under Profiles, select the sketches Profile1 and Profile2 in the FeatureManager design tree for Profile ⁰.

The preview shows that the entire loft is influenced by the guide curve.

5 Under Guide Curves, select To Next Sharp in Guide curves Influence.

The guide curve region of influence extends to only the next sharp in the profile. Only one side of the loft is influenced by the guide curve.

6 Click **OK** 🖌





Individual Segment Weight Control

When you apply start or end constraints, you can apply a weight to the constraints for individual segments within the profile, or to the entire profile. The new **Draft angle** option lets you add draft to a loft at the start and end constraint profile.

To apply individual segment weight control:

- Open Loft_WeightControl.sldprt from the File Explorer 2.
- 2 Click Lofted Surface U on the Surfaces toolbar, or click Insert, Surface, Loft.
- 3 In the PropertyManager, under **Profiles**, select the three edges in the graphics area in the approximate locations as shown for **Profile** [□]0.
- 4 Under Start/End Constraints:
 - a) Select Curvature To Face in Start constraint.
 - b) Clear Apply to all.
 - c) Select Direction Vector in End constraint.
 - d) Select the two vertices shown for **Direction Vector 7**.
 - e) Set **Draft angle** to **2** to draft the loft at the end constraint.
 - f) Clear Apply to all.

If necessary, click **Reverse Tangent Direction** dunder **Start** or **End Constraint** so the handles point toward each other.

5 Drag individual handles on either the start or end profiles to change the weight for that profile segment.

The **Start** or **End Tangent Length** values update in the PropertyManager.

6 Under both Start constraint and End constraint, select Apply to all.

The individual handles for each constraint profile are replaced by one handle that controls each entire constraint profile. The tangent lengths adjust to the last setting in the PropertyManager.

- 7 Drag the two handles to adjust the constraints.
- 8 Click **OK** 🖌



Mesh Previews

You can apply a preview mesh on the B-spline (non-analytic) surfaces of lofts to better visualize the loft surface. You can apply mesh to selected faces or to all faces.

To use mesh previews in lofts:

- 1 Open Loft_Mesh.sldprt from the File Explorer in the Second S
- 2 Click Lofted Boss/Base 3 on the Features toolbar, or click Insert, Boss/Base, Loft.
- 3 In the PropertyManager, under **Profiles**, select the upper-right corner of **Sketch1** and **Sketch2** in the graphics area for **Profile** □⁰
- 4 Right-click anywhere in the graphics area and select **Mesh Preview**, **Mesh All Faces**.

No preview mesh appears because the loft uses analytic geometry.

5 Drag the connector handle at the top-right corner of the near face to the lower-right corner.

The mesh appears because the loft uses B-spline geometry.

6 Right-click the face of the preview as shown and select **Mesh Preview**, **Clear Meshed Faces**.

The mesh disappears from the selected face only.

- 7 Right-click in the graphics area and select Mesh Preview, Clear all Meshed Faces to clear the mesh preview from all faces.
- 8 Click **OK** 🖌

Synchronization

Synchronization enhancements using the shortcut menu include:

- Undo. You can undo up to six of the last delete, add, or drag connector commands.
- Delete. You can delete a connector.
- Show a Connector. This new option shows the nearest connector to the selected point. The Add Connector command, which previously only showed the nearest connector, now adds a connector where you select on the profile sketch.





- **Persistent Connectors**. Connector points that you reposition retain the new position when you add profiles to the loft. Previously, repositioned points reverted to their previous position when you added profiles.
- Handle color in chains. Handles within the same chain highlight so you can more easily see the connections. You can also set the color of the starting chain. Click Tools, Options, System Options, Colors. In System colors, Dynamic highlight sets the color of the chain when you hover over it, and Selected Item 4 sets the color for the starting chain.

To test the loft synchronization enhancements:

- 1 Open Loft_Synchronize.sldprt from the File Explorer 2.
- 2 Click Lofted Boss/Base [3] on the Features toolbar, or click Insert, Boss/Base, Loft.
- 3 In the PropertyManager, under Profiles, select sketches 1 and 2 in the graphics area in the approximate locations as shown for Profile 20.
- 4 Right-click near the lower-right corner of the square sketch and select **Show Connector**.

The nearest connector appears.

- 5 Drag the upper connector handle on the ellipse as shown to reposition it.
- 6 Right-click in the graphics area and select **Undo** connector edit.

The handle returns to its original position.

- 7 Drag the same handle to reposition it again.
- 8 Under Profiles, select the large ellipse in the graphics area in the approximate location as shown for Profile 20.

The middle profile handle retains its new position when you add a profile to the loft.

- 9 Right-click and select Show All Connectors.
- 10 Hover over the various connectors' handles.

All handles within the same connector chain highlight.



Mirrors

You can mirror the following individual sheet metal features:

- Closed corners
- Edge flanges
- Hems
- Mitered flanges

Previously, you could mirror only entire sheet metal bodies, not individual sheet metal features.

To mirror individual sheet metal features:

1 Open Mirror_SheetMetal.sldprt from the File Explorer a.

The sheet metal part has an edge flange and a hem feature.

- 2 Click Mirror e on the Features toolbar, or click Insert, Pattern/Mirror, Mirror.
- 3 In the FeatureManager design tree, select:
 - a) Right Plane for Mirror Face/Plane 💋.
 - b) Edge-Flange1 and Hem1 for Features to Mirror 4.
- 4 Click **OK** 🖌





Move/Copy Bodies

The **Move/Copy Bodies** feature has a new triad that lets you drag to move or copy bodies. The triad has the same functionality as the triad in assemblies or the deform-surface push feature. For more information on using the triad, see **Surface Push Deform Type** on page 3-4.

Previously, you had to type exact **Delta X**, **Delta Y**, or **Delta Z** values to move or copy bodies. This functionality remains available.

Split Line Curves

Silhouette Split Lines

Two new options in the **Split Line** PropertyManager help you create a silhouette split line:

- Reverse direction. Flips the Direction of pull in the opposite direction.
- Angle 📉 . Creates a draft angle for manufacturing considerations. This is commonly used in thermoform packaging.

Intersection Split Lines

The **Split Line** tool can now split multiple faces with an intersecting solid, surface, face, plane, or surface spline. Split lines can be created at all intersections or selected faces of the splitting tool and the target body. You can create multiple split lines if the splitting tool intersects the target body in more than one place.



You can use the **Spline on Surface** tool to create a spline for the intersection split line. This is the only sketch entity supported by the intersection split line. See **Splines on Surfaces** on page 2-16.

To split multiple faces with an intersecting solid:

- 1 Open rocket.sldprt from the File Explorer
- 2 Click Split Line 2 on the Curves toolbar, or click Insert, Curve, Split Line.
- 3 In the PropertyManager, under **Type of Split**, select the new **Intersection** option.
- 4 Under Selections, for Splitting Bodies/Faces/ Planes , in the FeatureManager design tree:
 - a) Select Surface-Plane1.
 - b) Expand the Surface-Bodies folder image and select all six Body-Move/Copy surface bodies.
- 5 Under Selections, click in Faces/Bodies to Split , then select the face in the graphics area as shown.
- 6 Under Surface Split Options, select Natural.
- 7 Click OK 🕢.

The face is split into six faces.



Select this face



Direction Vector References

More references for the direction vector are now available, such as pairs of vertices, planes, edges, cylinders, axes, and so on. This applies to sweeps you create using **Follow Path** in **Orientation option/twist type** with **Direction Vector** in **Path alignment type**.

PropertyManager Enhancements

Under Options:

- The **Maintain tangency** option has been renamed to **Merge tangent faces** to better reflect its functionality.
- Advanced smoothing has been removed because this functionality is now automatically applied.

Twist

You can create sweeps that twist along a path. You control the twist by setting the number of degrees, radians, or turns. You can also create sweeps that twist along a path while keeping the normal constant so the start and end profiles remain parallel to each other. You cannot twist sweeps that use guide curves.

To create a sweep that twists along a path:

- Open SweepTwist.sldprt from the File Explorer 2, which shows a sweep along a path.
- 2 In the FeatureManager design tree, right-click **Sweep1** and select **Edit Feature**.



- 3 In the PropertyManager, under **Options**:
 - a) Select the new Twist Along Path option in Orientation/twist type.
 - b) Select Turns in Define angle by degree, radian or number of turns.
 - c) Set Angle defined in number of turns to 2.
- 4 Click **OK** 🖌.



Chapter 3 Features

Parts

This chapter describes enhancements to parts in the following areas:

- □ Custom properties
- □ Equations, global variables, and linked values
- □ Lighting
- □ Mass properties
- □ Measure tool
- □ Multibody parts

Custom Properties

The **Custom Properties** and **Configuration Specific Properties** dialog boxes have been redesigned. Properties, values, and so on, are now displayed in a grid.

To add custom properties:

- 1 Open \parts\well.sldprt.
- 2 Click File, Properties.
- 3 On the Custom tab, click in the cell under Property Name, and select PartNo.The property type Text appears under Type.
- 4 Under Value / Text Expression, type J0726, then press Enter.

J0726 appears for Evaluated Value.

- 5 Click in the second cell under **Property Name**, and type **Diameter**.
- 6 Under **Type**, select **Text**.
- 7 For Value / Text Expression, click the diameter dimension, 20, in the graphics area."D1@Sketch4@well.SLDPRT" appears for Value / Text Expression.
- 8 Place the pointer at the end of the dimension name, type mm, then press Enter.20mm appears for Evaluated Value.
- 9 Click OK.

New custom properties **PartNo** and **Diameter** are created.

- For Value / Text Expression, you can also select values from the
- list, which contains:
 - SolidWorks parameters (Mass, Density, and so on).
 - Global variables.
 - Linked dimension names.
 - (See Global Variables on page 4-5 and Linked Values on page 4-7.)

Equations, Global Variables, and Linked Values

Dimension Status Indicator

If a dimension is driven by an equation or linked to another dimension, a symbol appears with the dimension in the graphics area.

- Σ dimension driven by an equation
- ∞ dimension linked to another dimension through a shared value

Modifying Dimensions

When you double-click a dimension that is driven by an equation, the **Modify** dialog box appears, just as it has previously for linked dimensions. You make selections and changes based on the dimension status.

If the dimension is *not* driven by an equation and is *not* linked to another dimension, you can click \checkmark in the **Modify** dialog box and select:

- Add Equation
- · Link value

If the dimension is driven by an equation, the dimension is unavailable and \sum appears in the **Modify** dialog box. You can click \checkmark in the dialog box and select:

- Edit Equation
- Delete Equation

If the dimension is linked to other dimensions, m appears in the **Modify** dialog box. You can:

- Change the dimension. All instances of the shared value update.
- Click 💽 in the **Modify** dialog box and select **Unlink value** to change only that dimension.

Equations

The user interface for **Equations** has been enhanced.

In the **Equations** dialog box:

- Select **Degrees** or **Radians** for **Angular Equation Units** for use with trigonometric functions in equations. This setting is saved as a document setting.
- View comments in a separate **Comment** column.
- View global variables. See Global Variables on page 4-5.
- View linked dimension variables. See Linked Values on page 4-7.
- View the name of the model being edited.

The user interface for adding and editing equations has been enhanced. The Add Equation and Edit Equation dialog boxes include:

- Buttons for all previously supported mathematical functions (sine, cosine, and so on).
- New mathematical functions (secant, cosecant, and so on).
- A **Comment** button to add a comment to the equation.
- The ability to switch the keypad visibility on and off.

Also, you can access the **Equations** dialog box from the **Modify** dialog box by doubleclicking a dimension driven by an equation.

To add an equation:

- 1 Open \parts\well.sldprt.
- 2 Click Equations \sum on the Tools toolbar, or click Tools, Equations.
- 3 In the dialog box, click **Add**.
- 4 Populate the equation box:
 - a) Select **25**, the outside diameter of the tube (**D1@Sketch1**).
 - b) Click =.
 - c) Select 20, the inside diameter of the tube (D1@Sketch4).
 - d) Click +, then 8.
 - e) Click **Comment** and type **tube OD**.

The following appears in the equation box:

"D1@Sketch1" = "D1@Sketch4" + 8'tube OD

5 Click **OK** twice.



The value for the outside diameter updates in the graphics area. Σ appears with the dimension to indicate that it is driven by an equation.

6 Keep **well.sldprt** open for the procedures that follow.



To edit an equation:

1 Double-click the dimension, **28**.

In the **Modify** dialog box, note that the dimension is unavailable.

- 2 Click 🚽 and select Edit Equation.
- 3 In the Edit Equation dialog box, change 8 to 10, and click OK twice.The value for the outside diameter updates to 30.

To delete an equation:

- 1 Double-click the dimension, **30**.
- 2 In the dialog box, click 🔽 and select **Delete Equation**.

The **Equations** dialog box appears, with the equation that drives **D1@Sketch1** highlighted.

3 Click **Delete**, then click **OK**.

The equation is deleted, and Σ no longer appears with the dimension in the graphics area.



Global Variables

You can create global variables to use in equations. You define global variables in the **Equations** dialog box (example: **Well_Volume = 20000**). You can:

- Define global variables using other global variables, dimensions, and linked dimension names (example: Height = "Well_Volume"/(pi*("D1@Sketch4"/2)^2)).
- Drive dimensions using global variables (example: D1@Extrude1 = "Height").
- Use a part's global variables within an assembly.

Global variables and their current values appear:

- In the **Equations** folder **D** in the FeatureManager design tree.
- Under Value / Text Expression on the Custom tab in the Summary Information dialog box (accessed by clicking File, Properties).
- Under Value / Text Expression in the Weldment dialog box.

To create a global variable:

- 1 Open \parts\well.sldprt, if it is not already open.
- 2 Click Equations \sum on the Tools toolbar, or click Tools, Equations.

The **Equations** dialog box appears, and the **Equations** folder **E** in the FeatureManager design tree expands to show a previously created global variable and its value, **"Well_Volume"=20000**.

- 3 In the dialog box, click **Add**.
- 4 Populate the equation box:
 - a) Type Height.
 - b) Click =, then (.
 - c) In the Equations folder in the FeatureManager design tree, click "Well_Volume"=20000.
 - d) Click /, (, pi, *, (
 - e) Click **20**, the inside diameter of the tube (**D1@Sketch4**).
 - f) Click [1, 2,], ^, 2,],], +
 - g) Click 10, the thickness at the bottom of the tube (D1@Cut-Extrude1).

The following appears in the equation box:

Height = ("Well_Volume" / (pi * ("D1@Sketch4" / 2) ^ 2)) + "D1@Cut-Extrude1"

5 Click OK.

In the **Equations** dialog box, the new equation and its evaluate value, **73.662mm**, appear.

6 Click **OK** again.

"Height"=73.662mm appears in the Equations folder **E** in the FeatureManager design tree, where you can select it for use in other equations.

7 Keep well.sldprt open for the procedure that follows.

To drive a dimension using a global variable:

- 1 Click Equations \sum on the Tools toolbar, or click Tools, Equations.
- 2 In the dialog box, click Add.
- 3 Populate the equation box:
 - a) Click **60**, the length of the tube (**D1@Extrude1**).
 - b) Click = .

c) In the **Equations** folder **i** in the FeatureManager design tree, click **"Height"=73.662mm**.

The following appears in the equation box:

"D1@Extrude1" = "Height"

4 Click OK twice.

The value for the length updates in the graphics area. Σ appears with the dimension to indicate that it is driven by an equation.



Linked Values

The user interface for linked dimension values has been enhanced. You can now:

- Link dimension values from the **Modify** dialog box.
- Use the names of linked dimensions in equations.

Linked dimension names and their current values appear:

- In the **Equations** folder **i** in the FeatureManager design tree.
- In the **Equations** dialog box.
- Under Value / Text Expression on the Custom tab in the Summary Information dialog box (accessed by clicking File, Properties).
- Under Value / Text Expression in the Weldment dialog box.

To link a dimension:

- 1 Open \parts\well.sldprt, if it is not already open.
- 2 Show the dimension names:
 - a) Click **Options** [5] on the Standard toolbar, or click **Tools**, **Options**.
 - b) On the System Options tab, click General.
 - c) Select Show dimension names.
 - d) Click OK.

- 3 In the graphics area, double-click the dimension for the width of the top flange, **10**.
- 4 In the **Modify** dialog box, click **▼** and select **Link Value**.
- 5 In the Shared Values dialog box, type width in Name, then click OK.

In the graphics area, ∞ appears with the dimension, and the dimension name changes to width. The linked dimension name width appears in the **Equations** folder $\boxed{12}$ in the FeatureManager design tree.

- 6 Double-click the dimension for the width of the stepped diameter, **10**.
- 7 In the **Modify** dialog box, click 🔽 and select Link Value.
- 8 In the Shared Value dialog box, select width in Name, then click OK.

In the graphics area, ∞ appears with the dimension.







9 Keep well.sldprt open for the procedure that follows.

To unlink a value:

- 1 In the graphics area, double-click one of the linked dimensions.
- 2 In the dialog box, click 🖬 and select Unlink Value.

The dimension is no longer linked, and ∞ no longer appears with the dimension.

3 Close the part.

General Enhancements

With **RealView Graphics**, when a model is viewed in **Shaded With Edges** mode, the edges do not change to white when the model is rotated. Previously, the edges sometimes changed to white when adjacent faces were white, resulting in a loss of visibility.

Dynamic Lighting

You can position lights (point, spot, and directional) in a model by dragging manipulators, which eliminates the need to type their coordinates. Additionally, the **Ambient Properties**, **Directional Properties**, **Point Properties**, and **Spot Properties** dialog boxes have moved to the **Ambient**, **Directional**, **Point**, and **Spot** PropertyManagers. All previous dialog box functionality is retained in the PropertyManagers.

To position a Directional light:

- 1 Open \parts\Sprinkler_Body.sldprt.
- 2 Expand the Lighting folder 🔜 in the FeatureManager design tree.
- 3 Double-click Directional1.

The **Directional** PropertyManager appears, and a manipulator appears in the graphics area.



The appearance of the manipulator varies, depending on the zoom scale of the graphics area and the position of the light.

- 4 Move the pointer over the yellow dot on the manipulator. The pointer changes to $\sqrt{2}$.
- 5 Drag the manipulator, and note the changes in lighting.
- 6 Drop the manipulator in the approximate location shown.



7 Click **OK** 🕢.

To add and position a point light:

- 1 Right-click the Lighting folder 🙀 in the FeatureManager design tree, and select Add Point Light.
- 2 Double-click **Point1**.

The **Point** PropertyManager appears, and a manipulator **()** appears in the graphics area.

- 3 In the PropertyManager, under **Basic**, click **Edit Color**, select blue **__**, then click **OK**.
- 5 Drag the manipulator around the graphics area, and note the changes in lighting.
- 6 In the PropertyManager, under Light Position, set:
 - X coordinate 🔀 to 0.
 - Y coordinate 🔀 to 0.
 - Z coordinate /z to 45.
- 7 Click **OK** 🕢.



To add and position a spot light:

- 1 Right-click the Lighting folder 🖗 in the FeatureManager design tree, and select Add Spot Light.
- 2 Double-click **Spot1**.

The **Spot** PropertyManager appears, and a manipulator **manipulator** appears in the graphics area.



The appearance of the manipulator varies, depending on the zoom scale of the graphics area and the position of the light.

3 Move the pointer over the center of the manipulator. The pointer changes to 3.

4 Drag the manipulator to the approximate location shown.



The target \bigcirc appears on the model. The target is the point on the model at which the spot light is aimed.

5 Move the pointer over the target.

The pointer changes to R_{\oplus} .

6 Drag the target to the upper right corner of the part, as shown.



The target snaps to the vertex.

- 7 In the PropertyManager:
 - Under **Basic**, click **Edit Color**, select red **__**, then click **OK**.
 - Under Light Position, set Z coordinate V_z to 75.

- 8 In the graphics area, drag the green circle to change the cone angle to the approximate size shown.
- 9 Click OK 🕢.



Mass Properties

You can now assign mass properties to a part or assembly. This is useful when you create a simplified representation of a component (for example, a purchased component such as a gearbox or valve) and want to assign the correct mass and center of gravity to the model. The mass properties can also be configured in the **Mass Properties** dialog box.

To assign mass properties to a part:

- 1 Open \parts\pressure_switch.sldprt.
- 2 Click Mass Properties 💇 on the Tools toolbar, or click Tools, Mass Properties.

A 3D triad appears at the centroid of the part. The calculated values for the mass properties appear in the dialog box.

3 Select Assigned Mass Properties.

The Mass Properties in the Component's Coordinate System appear.

- 4 Set Mass to 1500.
- 5 For Center of gravity, set:
 - X to 0.
 - Y to -5.
 - Z to 23.



You can also select any vertex, sketch entity, or reference point in the graphics area for **Center of gravity**.



- 6 Under Apply To, select This configuration.
- 7 Click OK.



Calculated Center of Gravity Assigned Center of Gravity

In a design table, you can assign mass with the keyword **\$SW-MASS**. You can assign center of gravity using the keyword **\$SW-COG** (with a value of **x**, **y**, **z**). If these fields are left blank for a configuration, then the calculated mass properties are used. If you assign values in the design table, then later clear **Assigned Mass Properties** in the **Mass Properties** dialog box, the fields clear in the design table.

Measure Tool

The **Measure 1** tool includes enhanced functionality and user interface:

- Displays measurement results in the graphics area, on or near the entities measured.
- Displays coordinates in the graphics area.



When the **Measure** tool is not active, commonly-used measurements for selected entities appear in the status bar; in many cases you do not need the **Measure** tool.

The **Measure** dialog box has been reduced to the size of a small toolbar, which you can expand as needed.



Additionally, the **Measure Units/Precision** dialog box replaces the **Measurement Options** dialog box. Options from the old dialog box which do not belong to the **Measure** tool do not appear in the new dialog box. You can select **Use document settings**, or select **Use custom settings** to set various options such as **Length unit**, **Decimal places**, and so on.

To display coordinates:

- 1 Open \parts\bracket_b.sldprt.
- 2 Select the vertex on the top left corner of the part, as shown.



The X, Y, and Z coordinates of the point appear in the status bar.

- 3 Click Measure 🙍 on the Tools toolbar, or click Tools, Measure.
- 4 In the dialog box:
 - Click Show XYZ Measurements $\boxed{X_2}$ if it is not already selected.
 - Click 😻 to expand the dialog box, if it is not already expanded.

The **X**, **Y**, and **Z** coordinates of the point appear in the dialog box and in the graphics area.



5 Keep bracket_b.sldprt open for the procedure that follows.

To measure between entities:

- 1 Click a blank area of the graphics area to clear your selection from the previous procedure.
- 2 Click Left 👩 on the Standard Views toolbar.
- 3 Select the edge of the hole shown.



A callout displays the diameter of the circle and the coordinates of the center of the circle.

4 Select the edge of the hole in the lower right corner.

A callout displays the distance between the centers of the two holes. Callouts also show the difference in coordinates between the two holes.





When Show XYZ Measurements $\frac{1}{2}$ is selected in the Measure dialog box, the dY, dZ, and center distance callouts appear.

When Show XYZ Measurements $\boxed{X_2}$ is cleared, only the center distance callout appears.

5 Click Arc/Circle Measurements of and select Minimum Distance 35.

The callouts update to show information based on the minimum distance between the two circles.

Multibody Parts

The organization of solid bodies for multibody parts was improved in the FeatureManager design tree. You can:

- Group bodies into folders in the **Solid Bodies** folder **D**.
- Select commands to apply to all bodies within a folder.
- List the features that belong to each body.

To group bodies into folders:

- 1 Expand the **Solid Bodies** folder **n** in the FeatureManager design tree.
- 2 Right-click a solid body name, select Add to New Folder, and name the folder.

The selected solid body is listed in the new folder. You can drag other bodies into the same folder, and create other new folders and subfolders.

To apply commands to all bodies within a folder:

- 1 Right-click the folder.
- 2 Select a command such as **Hide Solid Body**, **Delete Body**, **Appearance**, and so on. The command is applied to all bodies in the folder.

To list the features that belong to each solid body:

- 1 Right-click the **Solid Bodies** folder **a** in the FeatureManager design tree.
- 2 Select Show Feature History.
- 3 Expand the solid body to see the features that belong to that body.
- 4 To hide the feature history, right-click the Solid Bodies folder **b** and clear Show Feature History.

Mold Tools

This chapter describes enhancements to mold tools in the following areas:

- □ Cores
- □ Heal edges
- □ MoldflowXpress
- $\hfill\square$ Mold folders
- □ Move face
- □ Parting lines
- □ Parting surfaces
- □ Planar surface from co-planar loops
- □ Tooling splits
- □ Shut-off surfaces
- □ Undercut detection

Cores

With the new **Core** tool, you can extract geometry from the tooling solid to create a core feature. You can also create lifters and trimmed ejector pins.

To add a core:

1 Open \mold_tools\power_strip.sldprt.

The main core and cavity for this plastic part were previously created, but are hidden for clarity. The recessed feature on the front of the part is a trapped molding area that requires a core. A core sketch was previously created, but is hidden for clarity.



- 2 In the FeatureManager design tree, expand the **Solid Bodies** folder **b**, then:
 - Right-click Cavity Body, and select Show Solid Body.
 - Right-click Plastic Part Body, and select Hide Solid Body.

The cavity appears and the plastic part disappears.

3 In the FeatureManager design tree, right-click Side Core Sketch and select Show.





The plane on which you create a core sketch does not need to be parallel to the direction that the side core travels. **Side Core Sketch** was created on the inside face of the cavity body, which is drafted 5° from the direction the core travels.

- 4 Click **Core** on the Mold Tools toolbar, or click **Insert**, **Molds**, **Core**.
- 5 Select Side Core Sketch in the flyout FeatureManager design tree.

The Core PropertyManager appears, with the following selected:

- Side Core Sketch for bounding sketch for core 📝 .
- Face <1> (the sketch plane) for extraction direction.

6 In the PropertyManager, under **Selections**, click in **extraction direction**, then select the front face of the cavity body as shown.



- 7 Click **Reverse direction A** if necessary, so the single-headed arrow (extraction direction) appears as shown.
- 8 Under Parameters, set:
 - End Condition to Blind.
 - Depth along extraction direction 💦 to 50.
 - End Condition to Blind.
 - Depth away from extraction direction to 25.
- 9 Click **OK** 🕢.



- A new body is created for the core, and is subtracted from the cavity body.
- In the FeatureManager design tree, in the **Solid Bodies** folder , a new folder named **Core bodies** , Additional core bodies you create are stored in this folder.
- 10 In the graphics area, right-click the cavity body, and select Hide.

The core is complete.



Heal Edges

You can merge multiple edges into a single edge with **Heal Edges**. This is useful on imported parts, where edges sometimes import as multiple short edges.

To heal edges:

- 1 Open \mold_tools\heal_edges.sldprt.
- 2 Move the pointer over the edges of the part. Note that the edges of the part are actually made up of many small edges.
- 3 Click Heal Edges *M* on the Features toolbar, or click **Insert**, Face, Heal Edges.
- 4 In the PropertyManager, under Faces:
 - Select the large face in the graphics area.
 - Set Angular Tolerance to 2.
 - Set Edge Length Tolerance to 5.
- 5 Click Heal Edges.

Edges less than 5mm long, with angles less than 2° at the vertex between the edges, merge into one edge. Under **Edge Information**, **Before** and **After** display the number of edges in the part before and after the **Heal Edges** operation.

- 6 Click **OK** 🕢.
- 7 Move the pointer over the edge of the part as shown. Note that long edges replace the multiple short edges.





MoldflowXpress

With MoldflowXpress, you can analyze plastic parts and their molds based on geometry, material, temperature, and injection gate location. The analysis produces an animated plot of the time it takes to fill the mold. This enables you to:

- Verify that the mold will fill in the allowed time.
- Assess the quality of the resulting part.
- Optimize the location of the injection gate.

To access MoldflowXpress, click **MoldflowXpress Analysis Wizard m** on the Mold Tools toolbar, or click **Tools**, **MoldflowXpress**.

For more information, click Help, MoldflowXpress Help.

Mold Folders

As in previous releases, the **Cavity Surface Bodies** folder **(a)**, **Core Surface Bodies** folder **(a)**, and **Parting Surface Bodies** folder **(c)** are created automatically when you use various mold tools, and the appropriate surfaces are added automatically to the folders. Now, if you want to define a mold using surfaces that were not created with mold tools, you can create the mold folders manually, then add the surfaces to the folders. To create the mold folders manually, click **Insert Mold Folders (c)** on the Mold Tools toolbar, or click **Insert, Molds, Insert Mold Folders**.

Move Face

With the new **Move Face** tool, you can offset, translate, and rotate faces and features directly on solid or surface models.

To offset a face:

- 1 Open \mold_tools\boss.sldprt.
- 2 Click Move Face 🔊 on the Mold Tools toolbar, or click Insert, Face, Move.
- 3 In the PropertyManager, under Move Face:
 - a) Select Offset.
 - b) Select the curved face of one of the bosses for **Face(s) to move**
 - c) Set **Distance** ito 5.
- 4 Click **OK** 🕢.

The selected face is offset the specified distance. The radius of the curved face increases.



Original boss



Offset face



To translate a face:

- 1 Click Move Face 🐚 on the Mold Tools toolbar, or click Insert, Face, Move.
- 2 In the PropertyManager, under **Move Face**:
 - a) Select Translate.
 - b) Select the curved face of another boss for Face(s) to move 🐚.
 - c) Set **Distance** \checkmark to **5**.
- 3 Under Parameters, for Direction **reference** >, select the long edges of the boss, as shown.
- 4 Under Move Face, select Flip direction.
- 5 Click **OK** 🕢.

The selected face is translated the specified distance. The radius of the curve of the face remains the same.



To rotate a face:

- 1 Click Move Face in on the Mold Tools toolbar, or click Insert, Face, Move.
- 2 In the PropertyManager, under **Move Face**:
 - a) Select **Rotate**.
 - b) Select the curved face of another boss for Face(s) to move 🐚.
 - c) Set Draft Angle M to 20.
- 3 Under Parameters, for Axis reference 🔪, select the back edge of the boss.



Direction reference



4 Click OK 🕢

The selected face is rotated by the specified angle.





You can also select features (such as **Extrudes** and **Cut-Extrudes**) to offset, translate, and rotate with **Move Face**.

Parting Lines

Parting line functionality has been enhanced, so you can create:

- Multiple parting line features in a single part.
- Partial parting line features.
- Parting line features that contain errors, reported as warnings.

To make parting lines easier to define, you can automatically split straddle faces found during draft analysis, either along the +/- boundary or at a specified draft angle. You can also split a face by selecting a:

- Sketch segment.
- Pair of vertices.
- Spline on a surface (see Splines on Surfaces on page 2-16).

Additionally, parting line features are always visible, even when they are not selected.

To automatically split straddle faces:

- 1 Open \mold_tools\parting_line.sldprt.
- 2 Click **Parting Lines** on the Mold Tools toolbar, or click **Insert**, **Molds**, **Parting Line**.
- 3 In the PropertyManager, under Mold Parameters:
 - a) Select **Top Plane** in the flyout FeatureManager design tree for **Direction of Pull** .
 - b) Set Draft Angle 📉 to 1.
 - c) Click Draft Analysis.

Note that the spherical surface is identified as a straddle face (it has both positive and negative draft).



4 Under Mold Parameters, select Split faces.

The spherical face is split.

5 Select the new edge in the graphics area.



In the PropertyManager, the edge appears under Parting Lines.

6 Click OK 🕢

To split a face by selecting a sketch segment:

- 1 Click View, Sketches to make sketches visible.
- 2 In the FeatureManager design tree, right-click **Parting Line1** and select **Edit Feature**.
- 3 In the PropertyManager, click in **Entities To Split**, and select the sketch segments on the front face of the part.

The new edges appear under Parting Lines.

- 4 Under **Parting Lines**, select each of the three redundant edges from the list, and press **Delete** for each edge.
- 5 Click OK 🕢.

To split a face by selecting a pair of vertices:

- 1 In the FeatureManager design tree, right-click **Parting Line1** and select **Edit Feature**.
- 2 In the PropertyManager, click in Entities To Split.
- 3 Rotate the part so you can see the back face.
- 4 Select the two vertices as shown.

A parting line segment appears.

5 Under **Parting Lines**, select each of the three redundant edges from the list, and press **Delete** for each edge.



6 Click **OK** 🕢.


Parting Surfaces

The parting surface functionality has been enhanced so you can:

- Display a callout to show the minimum radius of curvature.
- Use advanced selection tools, previously available only in the **Parting Line** PropertyManager.

To create a parting surface manually:

- 1 Open \mold_tools\box02.sldprt.
- 2 Click Parting Surfaces (on the Mold Tools toolbar, or click Insert, Molds, Parting Surface.
- 3 In the PropertyManager, under Mold Parameters, select **Top Plane** in the flyout FeatureManager design tree for **Direction of Pull** *▶*.
- 4 Under **Parting Line**, select the edge shown for **Edges S**

In the PropertyManager, the selection tools appear under **Parting Line**. In the graphics area, the edge highlights and a red handle appears.

5 In the PropertyManager, under Parting Line, click Select next edge if necessary, to change the direction of the red handle, as shown.





- 6 Click **Add selected edge** to add the next edge.
- 7 Continue the parting line. Click **Select next edge** as needed, to choose edges along the outer perimeter of the part; click **Add selected edge** to add the edges.



If you select **Zoom to the selected edge** $\boxed{6d}$, the image crops to the relevant area each time you click **Add selected edge** $\boxed{1}$.

The callout indicates the minimum radius on the parting surface.



8 Click OK 🕢

Planar Surface from Co-planar Loops

You can construct a planar surface from two or more co-planar loops. Select parting line features or edges of other features to define the loops.

To construct a planar surface from co-planar loops:

1 Open \mold_tools\cups.sldprt.

The rectangle (Sketch6) and the top faces of the four cups are in the same plane.



- 2 Click Planar Surface 🙆 on the Surfaces toolbar, or click Insert, Surface, Planar.
- 3 In the PropertyManager, for **Bounding Entities** \bigcirc , select the following in the flyout FeatureManager design tree:
 - Parting Line1 through Parting Line4.
 - Sketch6 (the rectangle).
- 4 Click **OK** 🕢.

A planar surface is created, bounded by the rectangle and the edges of the four cups.



Tooling Splits

You can create a tooling split for multiple bodies.

To create a tooling split for a multibody part:

- 1 Open \mold_tools\cups2.sldprt.
- 2 Click Tooling Split on the Mold Tools toolbar, or click Insert, Molds, Tooling Split.

In the graphics area, for the sketch plane, select the flat surface.



3 Sketch a rectangle approximately as shown.



- 4 Close the sketch.
- 5 Click **Isometric** on the Standard Views toolbar.
- 6 In the PropertyManager, under Block Size, set Depth in Direction 2 \downarrow to 40.

7 Under **Parting Surface**, click in **Parting Surface Bodies**, then select the flat surface shown.



8 Click OK 🕢.

The tooling split is complete. **ToolingSplit1[1]** and **Tooling Split1[2]** appear in the **Solid Bodies** folder **(b)** in the FeatureManager design tree.





You can use **Move/Copy Bodies** on the Features toolbar to separate the tooling split bodies to facilitate viewing them.



Shut-Off Surfaces

Shut-off surfaces have been enhanced so you can now fill telescopic shut-off areas. You can also:

- Specify a parting line feature as a selection.
- Use advanced selection tools, previously available only in the **Parting Line** PropertyManager.
- Select Show Preview.

To create a shut-off surface:

- 1 Open \mold_tools\box01.sldprt.
- 2 Click Shut-off Surfaces and on the Mold Tools toolbar, or click Insert, Molds, Shut-Off Surfaces.

The edges of the area requiring shut-off are highlighted, and a callout for the shut-off surface type appears. In the PropertyManager, the selected edges appear in **Edges**



3 In the PropertyManager, under Edges ô, select Show Preview.

4 Click **Contact** in the callout to change it to **Tangent**, and if necessary, click the red arrow to change the preview as shown.



5 Click **OK** 🕢.

The shut-off surface appears.



Undercut Detection

For parts with non-planar parting lines, you can specify to use the parting line during **Undercut Detection**, which produces more accurate results.

Weldments

This chapter describes enhancements to weldments in the following areas:

- **u** Cut lists
- □ Structural members along arcs
- □ Weldment trimming
- □ Weldment properties

Cut Lists

Cut List Folder

In the Feature Manager design tree, the **Solid Bodies** folder b is renamed to **Cut list** b when the first weldment feature is inserted.

Automatic Cut List

You can generate a cut list automatically.

To generate a cut list automatically:

- 1 Open \weldments\welded_frame.sldprt.
- 2 Click Structural Member i on the Weldments toolbar, or click Insert, Weldments, Structural Member.
- 3 In the PropertyManager, under Selections, select:
 - Iso in Standard.
 - Square tube in Type.
 - 30 x 30 x 2.6 in Size.
 - Each line in the sketch for **Path segments**.
- 4 Under Settings, select Apply corner treatment and click End Miter F.
- 5 Click **OK** 🕢.

The **Cut list** folder \mathbb{E} appears in the FeatureManager design tree. The **(4)** indicates the number of items in the cut list. The icon \mathbb{E} indicates that the cut list needs to be updated.



6 Expand the **Cut list** folder $\overline{\mathbb{R}}$.

The four segments of Structural Member1 are listed.

7 Right-click the **Cut list** folder **R**, and select **Update**.

The segments sort into two sub-folders. The two identical side segments are grouped in one **Cut-List-Item** folder, and the identical top and bottom segments are grouped in the other **Cut-List-Item** folder. The icon \mathbf{E} indicates that the cut list is up-to-date.



Although you generate the cut list automatically, you manually specify when to update it. This enables you to make many changes, then update the cut list once. However, the cut list updates automatically when you open a drawing that references the cut list.

Automatic is on by default for cut lists in new weldment parts. To turn it off, right-click the **Cut list** folder **B** and clear **Automatic**.

Structural Members Along Arcs

You can create structural member features along arc segments. Previously, only straight lines were supported. You can create the arc segment body as a separate body, or you can merge it with adjacent segment bodies to create one continuous segment.

To create structural members along arc segments:

- 1 Open \weldments\welded_arc.sldprt.
- 2 Click Structural Member i on the Weldments toolbar, or click Insert, Weldments, Structural Member.
- 3 In the PropertyManager, click **Keep** Visible (a).
- 4 Under Selections, select:
 - · Iso in Standard.
 - Square tube in Type.
 - 30 x 30 x 2.6 in Size.
 - Each sketch segment shown for **Path** segments.
 - Merge arc segment bodies.
- 5 Click **OK** 🕢.
- 6 For the next structural member, select each sketch segment shown for **Path** segments.
- 7 Clear Merge arc segment bodies.
- 8 Click **OK** 🕢.
- 9 Click **Cancel** (x) to close the PropertyManager.
- 10 In the FeatureManager design tree, expand the **Cut list** folder ₩.

For **Structural Member1**, because **Merge arc segment bodies** was selected, one segment appears. For **Structural Member2**, because **Merge arc segment bodies** was cleared, five individual segments appear. Select these sketch segments for the first structural member:



Select these sketch segments for the second structural member:



Weldment Trimming

The Trim/Extend feature is improved so you can:

- Trim both ends of a structural member at once by selecting more than one trimming boundary.
- Create more accurate trims with round pipes.
- Preview trimmed features before accepting them in the PropertyManager.

To trim with more than one planar face:

- 1 Open \weldments\weld_trim_01.sldprt.
- 2 Click Structural Member in on the Weldments toolbar, or click Insert, Weldments, Structural Member.
- 3 In the PropertyManager, under Selections, select:
 - Iso in Standard.
 - Square tube in Type.
 - 40 x 40 x 4 in Size.
 - Each line shown for **Path segments**.
- 4 Click **OK** 🕢.

Three cross members appear.

- 5 Click Trim/Extend p on the Weldments toolbar, or click Insert, Weldments, Trim/Extend.
- 6 In the PropertyManager, under Corner Type, select End Trim F.
- 7 Under Bodies to be Trimmed, select the three cross members you just created.
- 8 Under Trimming Boundary, select:
 - Planar face.
 - The two faces shown for Faces/Bodies.
 - Preview.



Trimming Boundaries

9 Click OK (2).

The three cross members are trimmed at both ends.



Select these lines:

To trim with round pipe segments:

- 1 Open \weldments\weld_trim_02.sldprt.
- 2 Click Structural Member i on the Weldments toolbar, or click Insert, Weldments, Structural Member.
- 3 In the PropertyManager, under Selections, select:
 - Iso in Standard.
 - Pipe in Type.
 - 33.7 x 4.0 in Size.
 - Each sketch segment shown for **Path segments**.
- 4 Click OK 🕢.
- 5 Click Trim/Extend p on the Weldments toolbar, or click Insert, Weldments, Trim/Extend.
- 6 In the PropertyManager, under **Bodies to be Trimmed**, select the front pipe segment in the structural member that you just created.





Note that the segment intersects two segments of Structural Member1.



- 7 Under Trimming Boundary, select:
 - · Bodies.
 - The two bodies shown for Faces/Bodies.
 - Preview.



Trimming Boundaries

8 Click **OK** 🕢.

The end of the selected pipe segment is trimmed to fit up to the two segments of **Structural Member1**.

9 Hide Structural Member1, then rotate the part so you can see the trimmed shape.



Weldment Properties

The user interface for weldment properties (the **Weldment** dialog box) was updated in the same manner as the **Custom Properties** user interface. See **Custom Properties** on page 4-2. Additionally, global variables and linked dimension names now appear under **Value / Text Expression** in the **Weldment** properties dialog box. See **Global Variables** on page 4-5 and **Linked Values** on page 4-7. Access the **Weldment** dialog box in the same way as in SolidWorks 2004 (right-click the **Weldment** feature **K** in the FeatureManager design tree).

Assemblies

This chapter describes enhancements to assemblies in the following areas:

- □ Assembly performance
- □ Exploded views
- □ External references
- □ General enhancements
- □ Flexible sub-assemblies
- □ Interference detection

Assembly Performance

Level of Detail in Dynamic Views

In **Performance** options and **Large Assembly Mode** options, the **Remove detail during zoom/pan/rotate** option has been replaced by the **Level of detail** slider.

To change the level of detail shown in views during zoom, pan, and rotate:

- 1 Click **Options** [5] on the Standard toolbar, or click **Tools**, **Options**.
- 2 On the **System Options** tab, select one of the following:
 - Performance. Sets options for all assemblies.
 - Large Assembly Mode. Sets options for only large assemblies.
- 3 For Level of detail:
 - Move the slider along the scale from More (slower) to Less (faster).
 - or -
 - Move the slider to **Off** (which is the equivalent of selecting the old **Remove detail** during zoom/pan/rotate option).
- 4 Click OK.

Suspend Automatic Rebuilds in Assemblies

You can defer the update of assemblies until you are ready to rebuild the assembly. By deferring the update, you can make many changes, then rebuild the assembly once. The assembly still rebuilds automatically, if necessary, for internal updates and to protect the integrity of the model.

To defer the update of assemblies:

Right-click the assembly name at the top of the FeatureManager design tree, and select **Suspend Automatic Rebuild**.

(Rebuild Suspended) appears in the status bar.



To manually update when in **Suspend Automatic Rebuild** mode, click **Rebuild** on the Standard toolbar.

To turn off the option, right-click the assembly name at the top of the FeatureManager design tree, and clear **Suspend Automatic Rebuild**.

You must reset the option every time you load the assembly document.

Exploded Views

The **Explode** dialog has been moved to the PropertyManager.

You now create exploded views by selecting and dragging parts in the graphics area instead of defining the explode steps in a dialog box.

You can evenly space exploded stacks of components (hardware, washers, and so on) with the new **Auto-space** option.

You can add a new component to existing explode steps. This is useful if you add a new part to an assembly which already has an exploded view.

If a sub-assembly already has an exploded view, you can reuse that view in the top level assembly.

To create an exploded view:

- 1 Open \assemblies\Oil Pump\Oil Pump.sldasm.
- 2 Click **Exploded View** gr on the Assembly toolbar, or click **Insert**, **Exploded View**.
- 3 In the graphics area, select the retaining ring.

A manipulator appears in the graphics area. **Retaining Ring<1>** appears under **Settings** in the PropertyManager.



You can drag the yellow sphere in the center of the manipulator to move the manipulator to a different location. If you drop the manipulator on a feature, an axis of the manipulator aligns with the feature.

4 Move the pointer over the head of the vertical green arrow of the manipulator.





The pointer changes to k_{R} .

5 Drag the green arrow of the manipulator down to explode the retaining ring in the vertical direction, and position as shown.



SolidWorks 2005 What's New

To auto-space components:

- 1 In the flyout FeatureManager design tree, select Cover<1> and Gear<1>.
- 2 In the PropertyManager, under **Options**, select **Auto-space components after drag**.
- 3 Move the pointer over the head of the blue arrow of the manipulator, and drag to position the components as shown.

When you drop the components in the position shown, **Cover** remains where you drop it, and the software automatically spaces **Gear** a distance further along the same axis.





You can change the autospace distance. In the PropertyManager, under **Options**, move the **Adjust the spacing between chain** components \ddagger slider.

- 4 In the flyout FeatureManager design tree, select Housing<1>, Outer Rotor<1>, and Inner Rotor<1>.
- 5 Move the pointer over the head of the blue arrow of the manipulator, and drag back to position the components.

The components are spaced automatically.



You can attach a component to existing explode steps. For example, you can add the retaining ring to the explode step with the gear and cover.

To attach a component to an existing explode step:

1 In the PropertyManager, under **Explode Steps**, right-click **Chain1** and select **Edit Step**.

Under Settings, the components or Chain1 are listed in Component(s) of the explode step **1**.

2 Select the retaining ring.

Retaining Ring<1> is added to Component(s) of the explode step 9.

3 Click **Apply** to preview the change, then click **Done**.

The retaining ring maintains its downward explode direction, but now also follows the forward explode direction of **Chain1**.

4 Click **OK** 🕢.





In SolidWorks 2005, collapse and explode the view in the same way as in previous releases. Right-click in the graphics area and select **Collapse**, or see the *SolidWorks Online User's Guide* for information on **Explode**, **Animate Explode** and **Animate Collapse**.

External References

You now have the ability to *not* create external references when designing in the context of an assembly. If you select **Do not create external references**, no in-place mate is created when you create a new component. Also, external references are not created when you reference the geometry of other components, such as when you use **Convert Entities** or **Offset Entities**, or extrude **Up to Vertex** of another component.

To specify that external references not be created:

Click **Do not create external references (a)** on the Assembly toolbar.

- or -

Click Tools, Options, System Options, External References, and select Do not create references external to the model.



You can switch **Do not create external references** off and on as you work in an assembly, to create external references for some components, but not for others.

General Enhancements

Assignable Mass Properties

You can now assign mass properties to a part or assembly. This is useful when you create a simplified representation of a component, and want to assign the correct mass to the component. See **Mass Properties** on page 4-12.

Managing Files in a Shared Environment

The **Reload** it tool on the Standard toolbar brings up a new dialog box for managing files in a shared environment. You can reload specific components of an assembly, and you can determine if read-only files in your session have been modified on disk or are available for write. See **Reload** on page 1-15.

Creation and Management of Assembly Component Configurations

You can now create and manage configurations for components (sub-assemblies and parts) from the FeatureManager design tree of the top level assembly. See **Creation and Management of Assembly Component Configurations** on page 8-4.

Flexible Sub-Assemblies

You can create flexible sub-assemblies without having to create separate configurations in the sub-assembly file. Previously, for each instance of the sub-assembly where you wanted a different position of components, you had to create a separate configuration. Now, you can change a sub-assembly from **Rigid** to **Flexible** from the parent assembly without creating configurations in the sub-assembly. You can insert more than one instance of the sub-assembly in the same configuration of the parent assembly. You can make some instances rigid and others flexible, and the different instances can have different positions of the sub-assembly components.

To create flexible sub-assemblies:

1 Open \assemblies\Control Panel\control_panel.sldasm.

The assembly contains three instances of sub-assembly **knob_and_base.sldasm**. Note that you cannot rotate the knobs on the sub-assemblies.



- 2 In the FeatureManager design tree, right-click the second instance of the sub-assembly (knob_and_base<2>), and select Properties.
- 3 In the dialog box, under **Solve as**, select **Flexible**, then click **OK**.

The sub-assembly is now flexible. In the FeatureManager design tree, the icon for the assembly changes to \mathbf{A}^2 .

4 In the graphics area, rotate the knob of knob_and_base<2>.



Interference Detection

Interference detection has been enhanced so you can:

- Display the true volume of interference as a shaded volume.
- Change the display settings of the interfering and non-interfering components to see the interference better.
- Select to ignore interferences that you want to exclude, such as press fits, interferences of threaded fasteners, on so on.
- Choose to include interferences between bodies within a multibody part.
- Choose to treat a sub-assembly as a single component, so that interferences between the sub-assembly's components are not reported.
- Distinguish between coincidence interferences and standard interferences.



Previously, multiple interferences between a pair of parts were sometimes reported as one interference. In SolidWorks 2005, each interference volume is reported separately. This can result in more interferences being reported.

To check for interferences in an assembly:

- 1 Open lens_frame.sldasm.
- 2 Click Interference Detection 🕅 on the Assembly toolbar, or click Tools, Interference Detection.
- 3 In the PropertyManager:
 - Under Selected components, leave lens_frame.sldasm in Components to Check.
 - Under Options, select Make interfering parts transparent.
 - Under Non-interfering Components, select Use current.
- 4 Under Selected Components, click Calculate.

Four interferences are detected, and are listed under **Results**. The volume of each interference appears to the right of each listing.



When you select an interference under **Results**, it highlights in red in the graphics area.

To examine the results:

1 Under **Results**, select the long horizontal interference, then click \boxdot to expand.

The interference is between the bottom corner of **frontplate** and a fillet on **baseplate**. This is a valid interference, which can be fixed later by adding a chamfer to the edge of **frontplate**.



- 2 Under Results:
 - Select another interference, and click \boxdot to expand.
 - Right-click the interference and select **Zoom to selection**.
- 3 Under Non-interfering Components, select Wireframe.

The interference is between a countersunk bolt and a hex nut. Examination of the interference reveals that the interference is between the threads of the two components. The bolt and nut are specified correctly, so you want to ignore this interference.



4 Under **Results**, with the interference still selected, click **Ignore**.

The interference disappears from the **Results** list.

5 Repeat steps 2 and 4 for the remaining interferences between a bolt and a nut.



If you want to show ignored interferences in the **Results** list, select **Show ignored interferences** under **Options**.

6 Click **OK** (v) to close the PropertyManager.

Chapter 7 Assemblies

Configurations

This chapter describes enhancements to configurations in the following areas:

- □ Configurable tolerances
- □ Creation and management of assembly component configurations
- □ Configurable materials
- □ Flexible sub-assemblies

Configurable Tolerances

Tolerances assigned to dimensions are now configurable in the **Dimension** PropertyManager and design tables.

To configure a tolerance in the Dimension PropertyManager:

1 Open \configurations\bracket_plate.sldprt.

The part has two configurations, **rough** and **machined**, that have identical dimensions. **Rough** is the active configuration.



- 2 In the graphics area, select the diameter dimension, 25.
- 3 In the PropertyManager, under Tolerance/Precision:
 - Select Symmetric in Tolerance Type 151-111
 - Enter **5** for **Maximum Variation +**.

• Click Configurations, select This configuration, then click OK.

4 Click **OK** 🕢.

5 In the graphics area, select the width dimension **50**.

- 6 In the PropertyManager, under **Tolerance/Precision**:
 - Select Bilateral in Tolerance Type
 - Enter **10** for **Maximum Variation +**.
 - Enter 5 for Minimum Variation —.
 - Click Configurations, select This configuration, then click OK.
- 7 Click OK 🕢.

The tolerances appear in the **rough** configuration, but not in the **machined** configuration.





To configure tolerances in a design table:

- 1 Click **Design Table** on the Tables toolbar, or click **Insert**, **Design Table**.
- 2 Under Source, select Auto-create.
- 3 Click **OK** 🕢.

A **Design Table** is created that includes the following tolerances for the **rough** configuration:

- For the width dimension: **\$TOLERANCE@D1@Extrude2**, with a value of **BILATERAL;10.000000;-5.000000**.
- For the diameter dimension: **\$TOLERANCE@D1@Sketch4**, with a value of **SYMMETRIC;5.000000**.

The values for the **machined** configuration are **NONE**.

- 4 Type values for **machined**:
 - For \$TOLERANCE@D1@Extrude2, type Symmetric;5.
 - For \$TOLERANCE@D1@Sketch4, type Symmetric;2.
- 5 In the design table, click in cell E2.
- 6 In the graphics area, double-click the diameter dimension, 25.

A column is added to the design table for parameter **D1@Sketch4**, with a value of **25** for **rough**.

- 7 For machined, type 35.
- 8 Click in the graphics area to close the design table.

The dimension and tolerance values for the two configurations update in the graphics area.



rough configuration



machined configuration

Creation and Management of Assembly Component Configurations

You can create configurations of assembly components from the FeatureManager design tree, without opening the assembly component in its own window. The configurations are still stored in the file of the component for which the configuration was created.

You can also switch configurations of a component from the FeatureManager design tree of the assembly. You can switch configurations for more than one component at a time if they have configurations with the same name.

To create or switch configurations, you must be editing the top-level assembly. The component can be at any level in the FeatureManager design tree.

To switch a component to another configuration:

- 1 Open \configurations\vise\vise.sldasm.
- 2 If the **Open External Referenced documents** dialog box appears, select **Open any documents which have changed**, then click **OK**.



- 3 In the FeatureManager design tree, hold down Ctrl and select jaw1 and jaw2.
- 4 Right-click and select Properties.
- 5 In the dialog box, under **Referenced configuration**, select **Use named configuration**.
- 6 Select Small.
- 7 Click OK.

The configurations of **jaw1** and **jaw2** change to **Small** in the graphics area and in the FeatureManager design tree.



To add configurations to components:

- 1 In the FeatureManager design tree:
 - a) Expand rest handle.
 - b) Right-click connector, and select Add Configuration.
- 2 In the PropertyManager:
 - a) Under Configuration Properties, type Long in Configuration name.
 - b) Under Advanced Options, select Use configuration specific color.
 - c) Click Color.
- 3 In the dialog box, select red **[**, then click **OK**.
- 4 Expand Parent/Child Options.

A simplified tree displays **connector** and all related components from the same branch of the FeatureManager design tree.

- 5 Select vise, rest handle, and connector.
- 6 Click OK (2).

New configurations named **Long** are created in **connector.sldprt**, **rest handle.sldasm**, and **vise.sldasm**, and become the active configurations in the FeatureManager design tree. The connector changes to red in the graphics area. You can edit **connector.sldprt** later to define different dimensions and properties in the new configuration.



Configurable Materials

You can specify a different material for each configuration of a part. When you specify a material for a part, you can select whether the material applies to **All configurations**, **This configuration**, or **Specified configurations**.

Flexible Sub-Assemblies

In assemblies, you can create flexible sub-assemblies without creating separate configurations in the sub-assembly file. See **Flexible Sub-Assemblies** on page 7-7.

Chapter 8 Configurations

Drawings

This chapter describes enhancements to drawings in the following areas:

- □ Aligned section views
- □ Comparing drawings
- **C**rop views
- □ Detached drawings
- Detail views
- □ Lightweight drawings
- □ OLE objects
- □ Options
- □ Projected views
- □ Section views
- □ User interface

Aligned Section Views

You can use more than two lines to create an aligned section view. The lines must be connected at an angle and cannot form multiple contours.

To create an aligned section view with more than two lines, you must sketch the lines first, then click **Aligned Section View**.



Comparing Drawings

Use **DrawCompare** to compare all entities between two drawing documents. The differences between the drawings are displayed in color codes. Click **Tools**, **DrawCompare** to access the tool.

Crop Views

The **Crop View** menu item has been removed from the **Tools** menu, but it is still available at **Insert**, **Drawing View**, **Crop**.

Detached Drawings

When you load a model in a detached drawing view, all unsuppressed models in the drawing document are loaded (including models on different sheets), regardless of whether the models are related. This ensures that all models are updated when you make a change.

Detail Views

You can create a detail view of a detail view or of a crop view. The second detail view uses the scale relative to the original model, not relative to the first detail or crop view.



Lightweight Drawings

When you select a lightweight component in a drawing, it is no longer set to resolved. In previous versions of the SolidWorks software, the component became fully resolved.

OLE Objects

When you insert an OLE object into a drawing, the object is placed:

- On top of geometry
- Beneath annotations, tables, and sketches

In previous versions, OLE objects were placed on top of geometry, annotations, and so on.



SolidWorks 2004: Image covers the model and a dimension



SolidWorks 2005: Image covers the model, not the dimension

Options

In Tools, Options, System Options, Drawings, new and deleted options include:

Option	Status	Notes
Keyboard movement increment	New	Specifies the unit value of movement when you use the arrow keys to move (nudge) drawing views, annotations, or dimensions.
Display drawing view borders	Deleted	See Drawing Views on page 9-6.
Dynamic drawing view activation	Deleted	The view closest to the pointer is activated automatically when you create entities such as sketches, annotations, or dimensions.

Projected Views

You can create an isometric projected view by moving the pointer to a corner of the parent view before placing the view.

Section Views

Exclude Fasteners from Section Views

When you create a section view of an assembly drawing, you can exclude fasteners from being sectioned. Fasteners include any item inserted from SolidWorks Toolbox (nuts, bolts, washers, and so on). You can also designate any component as a fastener so it will not be sectioned.

To exclude fasteners from a section view:

- 1 Open \drawings\testAssem1.slddrw from the File Explorer
- 2 In Drawing View2, select the sketch line.
- 3 Click Section View 🕽 on the Drawing toolbar, or click Insert, Drawing View, Section.
- 4 In the dialog box, select **Exclude fasteners**.

Note that you can also select **Flip direction** to change the orientation of the view.

- 5 Click OK.
- 6 Click in the drawing sheet to place the section view.

The view shows a section view of the part but not of the fasteners.

To designate any component as a fastener, open the component and click File, Properties. In the dialog box on the Custom tab, select IsFastener in Property Name, and type 1 for Value / Text Expression.

Section Views and Aligned Section Views

You can pre-select sketch entities that belong to the drawing sheet to create section views and aligned section views. The sketch entities do not have to belong to an existing drawing view.

Additionally, you can create section views or aligned section views from:

- Crop views
- Detail views
- Exploded views (the exploded view must be an orthographic view)



Drawing Sheets

Adding Drawing Sheets

When you add a new drawing sheet to an existing drawing, the **Sheet Properties** dialog box no longer appears. Instead, the new sheet properties are based on the active sheet.

Delete

To delete a drawing sheet, right-click a sheet tab or sheet icon in the FeatureManager design tree and select **Delete**. You can also right-click anywhere on the sheet (except in a drawing view) and select **Delete**.

To prevent accidentally deleting a drawing sheet, you can no longer delete a sheet by clicking an empty area of the sheet and pressing **Delete**.

Lock Sheet Focus

Double-click anywhere in a drawing sheet (except in a drawing view) to toggle between Lock Sheet Focus and Unlock Sheet Focus.

Re-order

You can re-order drawing sheets by dragging:

- Sheet names in the FeatureManager design tree.
- Sheet tabs at the bottom left corner of the drawing document. Drag a tab (the pointer changes to 12) to another tab. To re-order multiple sheets, hold down Ctrl to select the tabs, then release Ctrl before you drag.

Drawing Views

Borders

Border colors. New border colors indicate the different states of a drawing view. Detached drawings no longer have blue borders.





Green dotted line with solid corners indicates the view is selected and locked.

Empty views and predefined views have a dotted black line border when no model geometry is present. After a model is inserted into the view, the borders disappear.

Dynamic border activation. When you create a sketch, dimension, or annotation that belongs to a drawing view, the border highlights in a pink dotted line with solid corners.



Parent and child view borders. When you click any of the following, the parent view borders are highlighted:

- · Child views
- Section lines
- Detail circles

Resizing borders. You can no longer resize a drawing view border. The borders are tightly fitted around the view by default. If you add sketch entities to a drawing view, the border automatically resizes to include these items. The border does not resize to include dimensions or annotations.



Drawing view borders from previous releases of the SolidWorks software do not automatically resize.

Component and View Commands

When you right-click model geometry in a drawing view, the shortcut menu shows component and view information. Previously, only component information was shown.

Creating Child Views

If you create a child view in a drawing with only one drawing view, the SolidWorks software automatically creates the child view from the existing view, regardless of whether it was selected.

Additionally, when you create any type of child view (section view, detail view, and so on), you do not have to pre-select an existing view before you click the drawing view tool.

Deleting Views

To delete a drawing view, you can:

- Select model geometry in a drawing view and press Delete.
- Right-click model geometry in a drawing view and select Delete.

With either method, you are asked to confirm the deletion.

Lock View Focus

Double-click a drawing view to toggle between Lock View Focus and Unlock View Focus.

Lock View Position

After you position a drawing view, right-click anywhere in the drawing view and select **Lock View Position** to fix the drawing view in place. To release the drawing view, right-click the drawing view and select **Unlock View Position**.

Moving Drawing Views

You can click and drag many entities (including edges, vertices, cosmetic threads, and so on) in a drawing view to move the view. The pointer includes the pan icon, [k], to indicate that you can use the selected entity to move the view. You can also select a drawing view, then move (nudge) it with the arrow keys. See **Options** on page 9-3.

Names

You can rename drawing views. In the FeatureManager design tree, click-pause-click the drawing view name and then type the new text.

Overlapping Drawing Views

If you select a drawing view that overlaps another drawing view, the view whose center is closest to the pointer is selected.

PropertyManagers

Click anywhere in a drawing view (including model geometry) to display the drawing view PropertyManager. Previously, you had to click within the drawing view, but outside the model geometry to activate the drawing view PropertyManager.

In drawing view PropertyManagers, you can select a predefined scale and assign it to the view.

Selection

When you box-select one or more drawing views that do not have dimensions or annotations, the drawing views are selected. Otherwise, the dimensions and annotations are selected, not the drawing views.

Edges

When you select an edge in a drawing, the entire line is highlighted if all of the line segments are collinear. This behavior does not apply to components in an assembly drawing that are mated to form a collinear edge.




FeatureManager Design Tree

New icons in the FeatureManager design tree identify the drawing item:

Aligned Section View 1	Empty View 🛄	
Alternate Position View 📳	Horizontal Break 嶜	
Auxiliary View 💣	Model View 🔇	
Blocks 🖻	Predefined View 🖻	
Broken-out Section View 🛃	Projected View 🗄	
Crop View 🔊	Section View 🚦	
Detail View 🕼	Vertical Break 🕼	

Sketches

Selection

You can select a sketch anywhere in the drawing - the sketch does not need to belong to a drawing view. The drawing view does not need to be active or have locked focus.

Snapping and Inferencing

When you drag a sketch point in a drawing, you can snap or infer to all visible sketch points on the sheet.

Toolbars

Two new buttons have been added to the Drawing toolbar:

- Horizontal Break 😽
- Vertical Break 🖏

Previously, these tools were available from the Insert menu only.

Chapter 9 Drawings

10

Detailing

This chapter describes enhancements to detailing in the following areas:

- $\hfill\square$ Annotations
- □ Autodimension
- □ Bills of materials
- Design Library
- □ Insert model items
- □ Options
- □ Tables
- □ Toolbars

Annotations

Alignment

Annotations are aligned based on the baseline of the text. Previously, leaders and text boxes were used to align annotations.

When you select **Space Evenly Across** and **Space Evenly Down**, annotations are spread evenly across based on the first and last selected annotation in the group. Previously, annotations were spread based on the distance between the first and second entities in the group.



SolidWorks 2004: Alignment based on the top of bounding boxes

SolidWorks 2005: Alignment based on the baseline of the text

Area Hatch/Fill

The **Area Hatch/Fill** dialog box has moved to the PropertyManager. All previous functionality is retained. Additionally:

- You do not have to select an area to fill before using the Area Hatch/Fill Z tool.
- You can click in a closed region bounded by model edges or sketch entities to create an area hatch or fill that covers the entire region. Previously, you had to select individual boundaries and you could not apply an area hatch or fill to a region bounded by a combination of model edges and sketch entities.
- If you change the region boundaries, (for example, if you add a sketched rectangle that you want to exclude from the area hatch or fill), you can right-click and select **Recreate Area Hatch** to update the area.
- When you select an area hatch or fill pattern, the **Area Hatch/Fill** PropertyManager appears. A new option, **Apply changes immediately**, updates the drawing view immediately with your changes to the pattern. Otherwise, click **Apply** to update the drawing view when you want. This improves performance time.



To add an area hatch pattern to a drawing:

- 1 Open \detailing\crosshatch.slddrw from the File Explorer
- 2 Click Area Hatch/Fill on the Annotations toolbar, or click Insert, Annotations, Area Hatch/ Fill.
- 3 In the drawing, select the area as shown.
- 4 Click **OK** 🖌





Blocks

You can define leader attachment points for all instances of a block. Additionally, the **Definition** section of the **Block Instance** PropertyManager contains the following functionality:

- Edit. Accesses the Block Definition PropertyManager.
- Select a block definition. Allows you to change the selected block to a different block definition. You do not have to delete a block, then insert a new block to change the definition.

To define a leader attachment point in a block:

- 1 Open \detailing\block_with_leader.slddrw from the File Explorer 🎑
- 2 Select the block in the graphics area.
- 3 In the PropertyManager, under **Definition**, click **Edit**.

The **Block Definition** PropertyManager appears.

4 In the PropertyManager, under Leader Point, set X coordinate ■x to 62 and set Y coordinate ■y to 34. The leader point is indicated by





Cosmetic Threads

Cosmetic threads are indicated by the \bigcup icon in the FeatureManager design tree. If the cosmetic thread is hidden, it appears as \bigcup .

You can use the option, **Display precise threads**, to check all cosmetic threads to determine if they should be visible or hidden. See **Cosmetic Threads** on page 10-18.

Datum Target Symbols

When you select **No target symbol M** in the **Datum Target** PropertyManager, you place the symbol in the graphics area with one click. Previously, two clicks were required to place the symbol.

Dimensions

Alignment

You can now use the tools on the Align toolbar to align dimensions.

Configurable Tolerances

When you apply a tolerance to a dimension, you can apply the tolerance to specific configurations. See **Configurable Tolerances** on page 8-2.

Display

When you insert or edit a dimension in a drawing, you can select display options (**Parenthesis**, **Dual dimension**, or **Inspection dimension**) directly from the PropertyManager.

Modifying Dimensions

You can use the **Modify** dialog box to access the **Add Equation** or **Shared Values** dialog boxes. See **Modifying Dimensions** on page 4-3.

Overrides

You can add tolerances to a dimension that you have overridden. In previous releases, you could not override a dimension value and add a tolerance.

To add a tolerance to an overridden dimension:

- 1 Open \detailing \hole_callouts.slddrw from the File Explorer
- 2 Select the dimension, **96**.
- 3 In the PropertyManager, under **Primary Value**:
 - a) Select Override value.
 - b) Type **95** for the dimension value.

- 4 Under Tolerance/Precision:
 - a) Select Symmetric in Tolerance Type 150^{+.01}
 - b) Type 0.02 for Maximum Variation +.
- 5 Click **OK** 🖌

The dimension is overridden and includes a tolerance value. If you clear **Override value**, the dimension returns to its original value but retains the tolerance.

(95 ±0.02)

Geometric Tolerance Symbols

The dialog box for geometric tolerance symbols offers selections based on the symbol you choose. Only the attributes that are appropriate for the selected symbol are available. For example, if you select the concentric symbol, only the diameter attribute is available. Additionally, symbol selection is easier because you can choose from symbol images rather than their names.

To insert a geometric tolerance symbol:

- 1 Open a new drawing.
- 2 Click Geometric Tolerance 🔟 on the Annotation toolbar, or click Insert, Annotations, Geometric Tolerance.
- 3 In the dialog box:
 - a) Select **Position** \oplus in **Symbol**.
 - b) Type **0.25** for **Tolerance 1**.
 - c) Click Diameter \emptyset .
- 4 In the PropertyManager, select favorites, leaders, formatting, or layer properties as necessary.
- 5 Click in the graphics area to place the symbol.
- 6 Click **OK** in either the dialog box or the PropertyManager.



Halos

When you insert an annotation that is on top of a crosshatch or area hatch pattern, a halo of space appears around the annotation so it is easier to read. The halo also surrounds leaders, dimensions, and dimension lines.



Hide/Show Annotations

You can use the **Hide/Show Annotations** 🐼 tool to hide or show the following annotation types:

- Auto Balloons
- Balloons
- Bill of Materials
- Blocks
- Center Marks
- Centerlines

- Datum Features
- Datum Targets
- Dowel Pin Symbols
- Geometric Tolerances
- Hole Tables
- Multi-jog Leaders
- Cosmetic Threads
- Notes

- Revision Symbols
- Revision Tables
- Stacked Balloons
- Surface Finish Symbols
- Weld Symbols
- Weldment Cut Lists

Highlighting

When you drag the pointer over an annotation, it dynamically highlights. Previously, annotations did not highlight.





SolidWorks 2004

Hole Callouts

You can modify hole callouts to include tolerances.

To add tolerances to hole callouts:

- 1 Open \detailing\hole_callouts.slddrw from the File Explorer in the file is a standard from the file is a stan
- 2 Select the hole callout.
- 3 In the PropertyManager, under Tolerance/Precision:
 - a) Select Diameter (1.78) in Callout value.
 - b) Type **0.02** for **Maximum Variation +**.
 - c) Select Depth (25.4) in Callout value.
 - d) Select Symmetric in Tolerance Type 151-01.
 - e) Type 0.03 for Maximum Variation +.
 - f) Select CounterSink Angle (100°) in Callout value.
 - g) Select Symmetric in Tolerance Type 150⁺⁰¹/₋₀₁.
 - h) Type **2** for Maximum Variation **+**.
- 4 Click **OK** 🖌

The annotation is updated with the new tolerances.

+0.02 Ø1.78 -0.25 ⊽25.40 ±0.03 ✓ Ø3.02 X100° ±2.00°

Library Features

If you insert an annotation into a library feature, the annotation is saved with that feature. For example, a surface finish symbol attached to a face remains attached to the same face and at the same relative location when you insert the feature.



When you insert the annotation into a library feature, either the annotation itself or its leader must touch the feature to be saved with the feature.

Moving Annotations and Drawing Views

You can use the arrow keys to move (nudge) annotations or drawing views. See **Options** on page 9-3.

Notes

PropertyManager

The following functionality has been added to the Note PropertyManager:

- Annotations. You can insert the following annotations in a note: Geometric Tolerance
 , Surface Finish √, and Datum Feature ▲. See Annotations in Notes on page 10-10.
- Leader display. New display options are available when you attach a leader to a multi-line note:

ĸ≣	Attach Leader Top
ĸ≣	Attach Leader Center
ĸ≡	Attach Leader Bottom
	Attach Leader Nearest

If you move the note to either side of the leader, the leader remains in the same justification, except if you select **Attach Leader Nearest**. This option attaches the leader to the top when the text is to the left of the leader, and attaches the leader to the bottom when the text is to the right of the leader.

Change width -Change width Change width to to to 10mm. 10mm. 10mm. Attach Leader Top Attach Leader Center Attach Leader Bottom

Rich Text Formatting

Notes use rich text formatting so you can format each item in the note independently. Notes also support stacked text, bulleted and numbered lists, and so on.

To apply rich text formatting to a note:

1 Open \detailing\rich_text.slddrw from the File Explorer 🎑.

The note appears without rich text formatting.

2 Double-click the note.

The note is active and the Formatting pop-up toolbar appears.

- 3 In the note:
 - a) Double-click the word **Notes**, then click **Bold B** on the **Formatting** pop-up toolbar.
 - b) Highlight 1/32, then click Stack 💥 on the Formatting pop-up toolbar.
 - c) In the dialog box, under **Stack**, type **1** for **Upper** and type **32** for **Lower**.
 - d) Click OK.
- 4 To create a numbered list, select the two lines under **Notes**, then click **Number** is on the **Formatting** pop-up toolbar.
- 5 Click an empty area of the drawing sheet to close the note.

NOTES:

1. GRIND SHARP CORNERS.

2. ALL CAST FILLETS AND CORNER RADII 0 TO $\frac{1}{32}$.

Annotations in Notes

When you insert an annotation into a note, you can either select an existing annotation in the drawing or create a new one in the **Note** PropertyManager.

To insert an annotation from the Note PropertyManager:

- 1 Open \detailing\note_symbols.slddrw from the File Explorer 🎑.
- 2 Double-click the first note in the drawing.
- 3 Select ZZZ.
- 4 In the PropertyManager, under Text Format, click Surface Finish \checkmark .
- 5 In the Surface Finish PropertyManager, type **125** for Minimum Roughness.
- 6 Click **OK** 🖌
- 7 Click **OK** 🕜 again to close the **Note** PropertyManager.
- 8 Keep note_symbols.slddrw open for the next procedure.

125

All machined surfaces to be - arsigma .

unless otherwise specified.

- 🍾

To edit the annotation, double-click the annotation and edit it in the **Surface Finish** PropertyManager.

To insert an annotation from a drawing:

- 1 Open \detailing\note_symbols.slddrw from the File Explorer if you do not have it open from the previous procedure.
- 2 Double-click the second note in the drawing.
- 3 Select ZZZ.
- 4 Select the note $|/|_{0.05}$ $|_{A}$ in the drawing sheet.
- 5 Click **OK**

Tolerance zone: [/ 0.05



To edit the annotation, you must edit the existing annotation in the drawing sheet. You cannot edit annotations in notes if they were inserted from an existing annotation. When you edit the existing annotation, all instances of the annotation are updated in the drawing and the drawing sheets.

Variables in Notes

When you edit a note that contains a variable, you can either show the variable name or show the contents of the variable. Click **View**, **Annotation Link Variables** to see the variable name.

Selection

All annotation tools are available whether you pre- or post-select an entity in the drawing.

Surface Finish Symbols

When you insert a surface finish symbol, the PropertyManager lists all symbols regardless of the dimensioning standard. Additionally, improvements to surface finish symbols make it easier to place the symbols exactly:

Û

- You can rotate the symbols to any degree.
- Surface finish symbols are placed normal to an edge.





SolidWorks 2004: Surface finish symbol upright and rotated 90°

SolidWorks 2005: Surface finish symbol normal to edge

To rotate a surface finish symbol:

- 1 Open \detailing\surface_finish_symbol.slddrw from the File Explorer in the State of the State
- 2 Select the surface finish symbol in the drawing sheet.
- 3 In the PropertyManager, under Angle, set Angle 📉 to 45°.
- 4 Click **OK** 🕢.



Weld Beads

Two types of weld beads are now available: Caterpillar and End Treatment.

- $\mathbf{V}_{\mathbf{V}}$ The button for Weld Symbol has changed to \mathbf{M} . The End
 - Treatment L tool uses the old Weld Symbol button.

To add weld beads to a weldment:

- 1 Open \detailing\tree_gate.slddrw from the File Explorer 2.
- 2 Zoom in to the lower left corner of the view as shown.
- 3 Click Caterpillar)))) on the Annotation toolbar, or click Insert, Annotations, Caterpillar.
- 4 In the drawing, select the edge as shown.
- 5 In the PropertyManager, under Caterpillar:
 - a) Select Full length in Bead type.
 - b) Set **Bead size** \checkmark to 5.
- 6 In the graphics area, select the two edges as shown for **Trimming edges**. These edges define the boundaries for the weld bead.
- 7 Click $OK \bigcirc$ to accept the trimming edges.
- 8 Click **OK** 🕢 again to close the PropertyManager.

The caterpillar edges are trimmed at the corner and the weld bead is applied.



To add an end treatment to the weldment:

- 1 Click End Treatment is on the Annotations toolbar, or click Insert, Annotations, End Treatment.
- 2 In the PropertyManager:
 - a) Select the two edges as shown for **Edges** (7).
 - b) Click ISO type
 - c) Click **Bead throat thickness** and set the value to **5**.
- 3 Click **OK** \checkmark to accept the edges.
- 4 Click **OK** v again to close the PropertyManager.

The end treatment is applied to the drawing.

5 Keep **tree_gate.slddrw** open for the next procedure.





If you create end treatments or intermittent or partial caterpillar symbols, you can display and change the dimensions of the welded and non-welded areas. If you change the dimensions, the symbol updates.

Weld Symbols

When you insert a weld symbol, you can create multiple symbols and change them while the dialog box is open. You can also move the weld symbol within the model and place the leader and symbol as necessary.

To insert a weld symbol:

- 1 Open \detailing\tree_gate.slddrw from the File Explorer if you do not have it open from the previous procedure.
- 2 Click Weld Symbol 🖂 on the Annotations toolbar, or click Insert, Annotations, Weld Symbol.
- 3 In the dialog box:
 - a) Click the **Weld symbol** underneath the leader line. In the **Symbols** dialog box, select **Fillet** in the symbols list, then click **OK**.
 - b) Type **5** in the box to the left of the **Weld symbol** button to define the size.
- 4 In the graphics area, select the lower right edge as shown to attach the leader. Notice that the weld symbol is attached to the pointer.
- 5 Click again to place the weld symbol.
- 6 Click OK.



Autodimension

You can use the **Autodimension** tool to insert reference dimensions into drawing views as baseline, chain, and ordinate dimensions.

To autodimension a drawing:

- 1 Open \detailing\bushing.slddrw from the File Explorer 🎑.
- 2 Click **Autodimension** in the Dimensions/Relations toolbar.
- 3 In the PropertyManager:
 - a) Under Entities to Dimension, select All entities in view.
 - b) Under Horizontal Dimensions, select Baseline in Scheme and set Dimension placement to Above view.
 - c) Under Vertical Dimensions, select Ordinate in Scheme and set Dimension placement to Right of view.
- 4 Click **OK** 🕢.



Bills of Materials

Custom Properties

The **Column** PropertyManager now uses the term **Custom Property** instead of **User Defined** to insert a custom property into a BOM.

Equations and Formulas

Table-based bills of materials now support equations and formulas that were previously available in Microsoft Excel-based bills of materials only.

To add an equation to a table-based bill of materials:

1 Open \detailing\casting.slddrw from the File Explorer 2.

The drawing has a bill of materials with a column labeled, COST.

- 2 Select the **COST** column by clicking when the pointer changes to **F**.
- 3 In the Column PropertyManager, under Column Properties:
 - a) Select Equation.
 - b) Click Equation Editor.
- 4 In the dialog box:
 - a) Under Columns, double-click QTY.
 - b) Click * for multiply.
 - c) Under **Custom properties**, double-click **Price**. The value for **Price** is included in each part's custom properties.
 - d) Select Allow extra characters in column and custom property value to allow non-numeric text in each cell.
 - e) Click at the beginning of the equation. The pointer should be before the equation, 'QTY.'*`Price`.
 - f) Type \$ for Text, then click OK to add "\$" to the equation. The equation appears as "\$""QTY.'*`Price`.
 - g) Click OK.

Each cell in the column lists the quantity multiplied by the price per part.

- 5 Select the last cell in the **COST** column.
- 6 In the Cell PropertyManager, select Sum/Total Cell and:
 - a) Type **\$** for the box before **Sum**.
 - b) Click **OK** 🖌.

The sum of the **COST** column is displayed as **\$80**.



If you insert a component below the **Sum** row, the sum does not

update. You must insert a component above the **Sum** row for it to be included in the calculation.

Design Library

Use the **Design Library** to see previews of saved annotations. You can also drag-and-drop annotations to and from the **Design Library**. DXF/DWG files are supported in the **Design Library**, but previews are available for DWG files only. See **Design Library** on page 1-4.

Insert Model Items

The **Insert Model Items** dialog box has been replaced with the **Model Items** PropertyManager, which includes the following new functionality:

- Dimension placement. Select **Use dimension placement in sketch** to place model dimensions from the part in the same locations in the drawing.
- Feature selection. Insert model items for selected features.
- · Layers. Insert model items for different layers of the drawing.
- Hide/show. Use the hide/show pointer while the PropertyManager is active. The left mouse button moves items, and the right mouse button hides/shows items. When the **Model Items** PropertyManager is displayed, hidden model items are gray.

Additionally, when the **Model Items** PropertyManager and the hide/show pointer are active, the following options are available:

- Delete. Use the **Delete** key to delete model items.
- Drag. Use the Shift key to drag model items to another drawing view.
- Copy. Use the Ctrl key to copy model items to another drawing view.

To insert model items:

- 1 Open \detailing\tool_post.slddrw from the File Explorer 🎑.
- 2 Click Model Items is on the Annotation toolbar, or click Insert, Model Items.
- 3 In the PropertyManager:
 - a) Under Dimensions, select Eliminate duplicates.
 - b) Under Import from, click Selected feature.
 - c) Under Options, select Use dimension placement in sketch.
- 4 In **Drawing View1**, select the two edges as shown.
- 5 Hover over any of the dimensions. The pointer changes to the
- 6 Hold down the **Shift** key and drag the dimension **74.61** to **Drawing View3**, located to the right of **Drawing View1**.
- Select these

edaes

7 Click **OK** 🖌

Options

Cosmetic Threads

A new option, **Cosmetic thread display**, is available in **Tools**, **Options**, **Document Properties**, **Detailing**. When you select **High quality**, this option checks all cosmetic threads to determine if they should be visible or hidden. For example, if a hole (not a through hole) is on the back of a model and the model is in a front view, the cosmetic thread is hidden.

System performance is slower with this option selected. It is recommended that you clear this option until you finish placing all annotations.

Line Style

You can define custom line styles, then apply them with the Line Style or Layer **Properties** tools. In previous versions of the SolidWorks software, line styles were a system-wide property. Now they are document-based properties.



You can also set a location to save line styles in **Tools**, **Options**, **System Options**, **File Locations**. Select **Line Style Definitions** in **Show folders for** and set a file location.

To create a line style:

- 1 Open a new drawing.
- 2 Click **Options [**] on the Standard toolbar, or click **Tools**, **Options**.
- 3 On the Document Properties tab, click Line Style.
- 4 In the dialog box:
 - a) Click New.
 - b) Type **whatsnew** for the line style name, then press **Enter**. The name is not case sensitive.
 - c) Under Line length and spacing values, clear the default text.
 - d) Type **A,2,-2**, where **A** indicates a normal line, **2** creates a 2mm line width, and **-2** creates a 2mm gap between segments.

The line style units are based on the units used in the document. \Box

- 5 Click Save.
- 6 In the dialog box:
 - a) Select **Save to the default user line style file**. This ensures that the line style is available for all documents, not just the current document.
 - b) Select the name of the new line style in the list, then click **OK**.
- 7 Click **OK** to close the **Document Properties Line Style** dialog box.
- 8 Click **Line Style m** on the Line Format toolbar.

The new line style is available.

Toolbars

Align Toolbar

Align Between Lines

The **Align Between Lines** tool allows you to align annotations evenly between horizontal or vertical lines. Unlike the **Space Evenly Across** and **Space Evenly Down** tools, which require that you select at least three annotations, the **Align Between Lines** tool requires that you select only one annotation and two horizontal or vertical lines.

To align annotations between lines:

- 1 Open \detailing \align_between_lines.slddrw from the File Explorer 2.
- 2 Select all entities in the graphics area.
- 3 Click Align Between Lines 🔤 on the Align toolbar, or click Tools, Align, Align Between Lines.

The annotations are aligned within each rectangle.



Grouping

You can select multiple annotations and group them so they move together when you drag them. Similarly, you can ungroup annotations so they move independently. Limitations of grouping include:

- If you hold down **Shift** and drag a dimension in a group, you are asked if you want to dissolve the group so the annotations move independently.
- If you hold down **Alt** and drag an annotation in a group, the annotation moves independently.
- If you select an annotation within a group, then create a block, only the selected annotation is included in the block. Grouped annotations are automatically ungrouped when you create a block. You must hold down **Ctrl** and select individual annotations (even if they are grouped) to include them in a block.
- When you edit the definition of a block, you cannot create a group of entities within the block.

To group annotations:

- Open \detailing\axle_support.slddrw from the File Explorer <a>[]
- 2 Hold down **Ctrl** and select the two dimensions and note.
- 3 Click Group [] on the Align toolbar, or click Tools, Align, Group, Group.
- 4 Click an empty area of the drawing to clear all of the selections.
- 5 Drag any annotation in the group.

The annotations move together as a single entity.

- 6 Again, click an empty area of the drawing to clear all of the selections.
- 7 Hold down **Alt** and drag the dimension **79**.

The dimension moves independently of the group.

8 Release **Alt**, then drag any of the annotations in the group.

The annotations move together as a single entity.



To ungroup the annotations, select an annotation in the group and click **Ungroup** on the Align toolbar, or click **Tools**, **Align**, **Group**, **Ungroup**.

Moved Tools

The following tools have moved from the Drawing toolbar to the Align toolbar:

- Align Collinear/Radial X.

Name Changes

The following tools on the Align toolbar have changed names:

Old Tool Name	New Tool Name
Uppermost	Align Top
Leftmost	Align Left
Rightmost	Align Right
Lowermost	Align Bottom
Center Horizontally	Align Horizontal
Center Vertically	Align Vertical
Compact Horizontally	Space Tightly Across
Compact Vertically	Space Tightly Down

To access these tools on the menu, click **Tools**, **Align**, and select the tool.

Annotation Toolbar

The **Revision Symbol** \triangle tool has been added to the Annotation toolbar.

The table buttons (**Hole Table**, **Bill of Materials**, and so on) have moved from the Annotation toolbar to the Table toolbar.

Formatting Toolbar

The Font toolbar has been renamed to the Formatting toolbar.

Table Toolbar

The Table toolbar includes the Hole Table, Bill of Materials, Excel based Bill of Materials, Revision Table, Design Table, and Weldment Cut List tools. These were moved from the Annotations toolbar.

Library Features

This chapter describes enhancements to library features in the following areas:

- General enhancements
- Design Library
- □ Adding library features
- □ FeatureManager design tree
- □ PropertyManager
- □ Library features and links
- □ Library features for machine design

General Enhancements

Enhancements include the following capabilities:

- Select a configuration while inserting the library feature into a part.
- Link to parent part.
- Edit by changing configurations, selecting a different position, and so on.
- Add descriptions to references when saving the library feature.
- Add annotations to a library feature, and have the annotations to the feature inserted into the part with the library feature.
- Store a helix as a library feature.
- Flip the sketch orientation during insertion of a library feature by clicking the direction arrow in the graphics area.
- Transfer visual properties such as textures specified in the library feature to the inserted features.

Design Library

The **Design Library** has replaced the **Palette Features** window and the menu option (**Insert, Features, Library Features**). The **Design Library** now controls all library feature functions including:

- Display of the library features and subfolders that contain library features.
- Preview of the library feature parts.
- Insertion of the library features on the face of a part or on a plane in the graphics area.

The **Design Library** includes multiple top-level folders, such as **annotations**, **assemblies**, and **forming tools**.

Library Features on a Plane

You can drag library features to a plane, or anywhere in the graphics area. If you drag a library feature to the graphics area, you are prompted to select a plane. To place a library feature on a plane, select the edges or the label.

Drag a Library Feature to a Plane



Adding Library Features

To add a library feature:

- 1 Open sheet_metal_cover.sldprt from the File Explorer _____.
- 2 Click **Design Library M** to display the **Design Library** Task pane.
- 3 Click H to pin down the **Design Library**.
- 4 Click features, metric, slots.

Slots appear in the bottom panel of the Task Pane.

5 Select the **straight slot**, and drag the slot to the bottom area of the flat **Base-Flange1**.



6 Position the slot just over the cut, between the second and third hems, as shown.



- 7 In the PropertyManager:
 - Select 12.2 X 61 in Configuration.

? Locating edge1 highlights in References, and a popup window highlighting the reference to select appears, with the reference edge highlighted.

• Select the left edge of the **Base-Flange1**, as shown.



In the popup window, the top edge is highlighted, and **?** Locating edge2 is highlighted in **References**.

• Select the top edge of the **Base-Flange1**, just below the fillet, as shown.



This positions the slot and allows you to modify the Locating Dimensions.

- 8 In the PropertyManager, under Locating Dimensions:
 - a) Select Value, and type 135 for Locating dim1.
 - b) Select Value, and type 32 for Locating dim2.
- 9 Click **OK** 🕢.



Editing Library Features

Once you insert a library feature, you can change configurations, regardless of whether the inserted feature is linked to the parent part in the library. You can also change the references (see **References** on page 11-7).

FeatureManager Design Tree

You can create library features by selecting some or all features from the FeatureManager design tree.

- Hold down **Ctrl** and select multiple features from a previously saved part, and drag the features from the FeatureManager design tree into a folder in the **Design Library**.
- Drag a folder with features from a previously saved part into the Design Library.
 - When you create a part that includes multiple extruded features that

you want to save as a library feature, make sure that **Merge result** is selected. This ensures that all features are included when you drag the library feature to a model.

Creating a Library Feature

To save features as a library feature:

- 1 Open library_feature_save.sldprt from the File Explorer 🙆
- 2 Click **Design Library** ito display the **Design Library** Task pane.
- 3 Click to pin down the Design Library.
- 4 Select parts, hardware.

The bottom panel displays samples from the hardware folder.

- 5 In the FeatureManager design tree, hold down **Ctrl** and select the following:
 - Extrude1
 - Fillet1
 - CutExtrude2
- 6 Hold down **Ctrl** and drag the features to the lower pane of the Task Pane.

This opens the Save As dialog box, with the .sldlfp extension already selected.

- 7 Save the library feature as model1.sldlfp.
- 8 Click **Yes** in the dialog box.

This saves **model1.sldlfp** in the **hardware** folder of the **Design Library**, where you can see a preview of the library feature.

You can save a library feature by selecting the features and clicking File, Save As. Select Lib Feat Part (*.sldlfp) in Save as type.

Library Feature Subfolders

When you open a part saved as a library feature, the SolidWorks application adds two subfolders in the FeatureManager design tree under the library feature.

References

Lists the references that need to be specified when inserting a library feature.

To rename any reference, click-pause-click the reference name (see Library Features and Links on page 11-9).

Dimensions

Lists the dimensions that belong to features marked as library features. The **Dimensions** folder includes two subfolders: **Locating Dimensions** and **Internal Dimensions**.

You can specify a dimension as a **Locating Dimension** by dragging the dimension from the **Dimensions** folder to the **Locating Dimensions** subfolder. You can edit the **Locating Dimension** when you insert a library feature.

If you do not want other users to change a dimension value while inserting a library feature, mark the dimension as an **Internal Dimension**, and drag the dimension to the **Internal Dimensions** folder.

To edit a dimension name, click-pause-click the dimension name (for example **D1** in **D1@Extrude2**).

PropertyManager

When you insert a library feature, the PropertyManager includes the following groups:

Placement Plane

Prompts you to select a face or a plane.



If you drag a library feature to a reference plane, the drop point defaults to the center of the selected reference plane.

Configuration

Prompts you to select a configuration for the library feature. **Default** is selected if no configurations exist.

Link to library part. This is cleared by default.

If selected, the library feature you insert remains linked to the parent library feature part, and if updated, the library feature in the parent part changes. You cannot edit the inserted library feature (see **Library Features and Links** on page 11-9).

Location and References

Depending on the library feature, either **Location** or **References** appears after you select a configuration (or automatically if only a default configuration exists).

Location. If you do not have references, click **Edit**. This enables you to position the library feature by editing the sketch.

References. Lists the references you need to specify to insert the library feature. The **Locating Dimensions** (see **Dimensions** on page 11-7) allow you to specify values to position the library feature.



Library features with face references such as fillets do not need reference dimensions.

The popup window in the graphics area indicates the references you must select on the model to position the library feature.

Size Dimensions

Select **Override dimension values** to change the size of the library feature. This option is only available if you have not linked the library feature to the parent part.



Since Link to Library part (see Library Features and Links on page 11-9) is cleared, you are informed when a library feature is linked to the parent and **Override dimension values** is checked.

Library Features and Links

Selecting or clearing **Link to library part** determines the behavior of the library feature and its relation to the parent part.

Capability	Available with Link to library part <i>selected</i>	Available with Link to library part <i>cleared</i>
Select a face or a plane for the Placement Plane .	٧	¥
Select Edit Sketch from the FeatureManager design tree after the library feature is inserted.	×	~
Select Edit Definition from the FeatureManager design tree after the library feature is inserted.	×	~
Change the values of Locating Dimensions in the References group.	~	~
Select Override dimension values in the Size Dimensions group to edit the dimensions of the library feature sketch after the library feature is inserted.	×	~
Change configuration of the feature.	~	✓
Select Edit Sketch in the PropertyManager when the library feature includes no references.	×	~

Library features specific to machine design are now included under Library Features in the SolidWorks application. These library features are generated using design tables to facilitate design modifications. Examples, with configuration names, are listed on the next page.

Library feature	Configuration naming convention
Slots	
Straight slot	Width x length. For example, 0.250 x 1.025.
Curved slot	Slot width x outer radius x angle (the slot angle, is currently a constant at 90 degrees). For example, 0.125 x 1.25 x 90.
Keyways	
• Square	Width x height (for the shaft) and (for the hub). For example, 0.8125 x 0.8175.
• Rectangular	Width x height (for the shaft) and (for the hub). For example, 2.5 x 0.625.
O-ring grooves	bs 4518 - Pneumatic seal 0036-24.
Retaining ring grooves	Configuration names for Internal and External retaining ring grooves are available.
Internal	basic internal - ANSI b27-7. For example, diameter = 10.
External	basic external - ANSI b27-7. For example, diameter = 24.
Hole patterns	
Linear hole pattern	Configuration names use the formula diameter a x b , where diameter size is the hole diameter, and the values a and b represent the rows and columns, respectively. For example: 0.188 2 x 2. Linear hole patterns use standard hole sizes $1/8 - 3$ (inches) in increments of $1/16$. Spacing is based on twice the diameter, with patterns ranging from $2x^2$ to $8x^8$
Radial hole pattern	Configuration names use the formula D x L x A
	For example: 0.188 x 0.500 x 30. Radial hole patterns use standard diameter hole sizes, with diameter represented by the value D , range from 1/8 - 3 (inches) in increments of 1/16. The diameter of the pattern, represented by the value L , is fixed at 4 times the diameter. The angle, represented by the value A , varies from 0 to 90 degrees in increments of 15 degrees.

Other Functionality

This chapter describes enhancements in the following areas:

- □ Application Programming Interface and macros
- □ Import/Export
- □ Installation

Application Programming Interfaces and Macros

Application Programming Interfaces

Click **Help**, **SolidWorks API and Add-Ins Help Topics** to access the SolidWorks, eDrawings, FeatureWorks[®], PDMWorks, SolidWorks Toolbox Browser, and SolidWorks Utilities Application Programming Interfaces (API) Help systems.

SolidWorks API

The major enhancements made to the SolidWorks API in SolidWorks 2005 are:

- **Quick Tips and Bubble ToolTips**. You can create Quick Tips and Bubble ToolTips for any add-in.
- **Manipulator and TriadManipulator**. You can create a generic manipulator and use it to create a triad manipulator, which is similar to the triad in the SolidWorks user interface.
- **Custom properties column in a revision table**. You can get the custom properties for a custom properties column in a revision table.
- Layers. You can set the color, name, style, and line width of layers.
- **Display dimensions of drawing sheets and views**. You can get the display dimensions from the current drawing sheet or the current drawing view.
- **Pre-notification of new drawing view**. An event can pre-notify your application when a new drawing view is about to be created.
- Arrays of annotations. You can return arrays of annotations.
- **Dynamically highlighted object selection**. You can select dynamically highlighted objects.
- FeatureData. Seventeen new FeatureData APIs are included in this release.
- **Texture**. You can access textures on bodies, components, faces, features, and documents.
- User-specified type libraries. You can add and remove references to user-specified type libraries.
- Add-ins and swAppFileOpenNotify2. Because it is now possible to have a NULL active document when an add-in is notified by swAppFileOpenNotify2, use SldWorks::IGetOpenDocumentByName2 instead of SldWorks::IActiveDoc2.
- **Examples**. Hundreds of new Visual Basic code examples are included in this release.

eDrawings API

This release includes an eDrawings[™] API. This API is an OLE programming interface to eDrawings and is implemented as a Microsoft ActiveX[®] control. You can use the eDrawings API to customize the eDrawings Viewer, create interactive web pages, and translate files.

PDMWorks API

The PDMWorks API is now enabled for both PDMWorks client (add-in and standalone) and PDMWorks advanced server installations. Other enhancements in this release of the PDMWorks API include:

- Document check-ins. You can check in documents.
- **Documents and projects**. You can move a document to a different project. You can also create sub-projects.
- Document ownership. You can change ownership of a document.
- Lifecyle statuses. You can get the vault's lifecycle statuses and the status of a document.
- Revision labels. You can get the next suggested revisions for a document.
- SolidWorks version. You can get the SolidWorks version of a document.

SolidWorks Utilities API

Support for the Power Select tool is included in the SolidWorks Utilities 2005 API.

Macros

You can automatically edit macros after recording them. See **Macro Editing** on page 1-17 for details.

Import/Export

SolidWorks DWGEditor

The new SolidWorks DWGEditor[™] software allows you to edit DWG and DXF files and save them in their native format. Because the documents are maintained in the DXF/DWG formats, they can be opened again in AutoCAD.

This upgraded environment for supporting DWG and DXF legacy files includes interaction with tools such as PDMWorks and eDrawings in addition to functionality such as cutting and pasting geometry from the editor into SolidWorks.

You can access the SolidWorks DWGEditor in several ways.

- Click Start, SolidWorks 2005, SolidWorks DWGEditor.
- In the SolidWorks Open dialog box, select DXF(*.dxf) or DWG (*.dwg) for Files of type. In the DXF/DWG Import Wizard, select Edit/view in the SolidWorks DWGEditor, then click Finish.
- During the installation of SolidWorks, choose to associate DXF/DWG files with the SolidWorks DWGEditor. The editor appears when you doubleclick .dxf and .dwg files in a file explorer or Design Library or when you check files out of a PDMWorks Vault.

To edit a file in SolidWorks DWGEditor:

- 1 Click **Open** *(Chick File, Open)* on the Standard toolbar, or click **File**, **Open**.
- In the dialog box, select DWG(*.dwg) for Files of type, browse to \import\7550-021.dwg, and click Open.
- 3 In the DXF/DWG Import dialog box, select Edit / view in SolidWorks DWGEditor, then click Finish.





- 4 In the DWGEditor, edit the drawing; for example, change the pattern of the holes in the view on the left from 6 holes to 4 holes.
- 5 Click File, Save As and save the drawing as 7550-021A.dwg.
AutoCAD DXF/DWG Files

Import of solids and surfaces in AutoCAD DXF and DWG files has been enhanced. Import and export have been extended to AutoCAD R2004 in DWGDirect format.

Custom line styles are supported for export. On import, custom line styles in AutoCAD are not recognized.

Mechanical Desktop (MDT) Translator

You can now create associative SolidWorks drawings when importing Mechanical Desktop[®] (MDT) files. An option, **Create linked drawing document**, has been added to the DXF/DWG Import Wizard dialog box. Mechanical Desktop must be installed on your system.

eDrawings

You can add passwords when publishing eDrawings files from SolidWorks if you have eDrawings Professional.

You can also export animations in models to eDrawings files.

For more about eDrawings, see eDrawings on page 13-2.

Assemblies

Components are no longer suppressed when importing large assemblies.

ProENGINEER Translator

The following new ProENGINEER[®] features are supported for import into SolidWorks:

- Imported features (non-native to ProENGINEER)
- Copy geometry feature
- Thin revolve features

Import of the following features has been enhanced:

- Lofts with multiple sketches
- Reference patterns
- Ambiguities between circular and linear patterns
- Holes (more types recognized)
- Protrusions (values for depth improved)
- Sweep features with open loops
- Cuts with open sketches
- Cut lofts

Unigraphics Files

The SolidWorks software supports import of Unigraphics® NX files.

Assembly transforms and configurations have been enhanced.

An option, **Import tool bodies**, has been added to the **Import Options** for Unigraphics files. Tool bodies are used to construct the final bodies. Clear the option to import only the final bodies.

IDF Files

You can now import Intermediate Data Format (IDF) circuit board files (*.emn, *.brd, *.bdf, *.idb) and create solid models of the circuit board and its components. The model is a single part with each component an extruded feature.

- Each IDF file has two parts: the board file and the library file; for example ***.emn** and ***.emp**. Other possible combinations include ***.brd/*.lib**, ***.brd/*.pro**, ***.bdf/*.ldf**, and ***.idb/*.idl**. The software looks for a library file with the same name and extension corresponding to the board file. If it does not find the library, it prompts you to browse for the file.
- The name of each extruded feature in the FeatureManager design tree is based on the component name.
- Components of the same type appear in the same color.
- If the board thickness is not defined in the IDF file, you are prompted to specify a value and units.

To import an IDF file:

- 2 In the dialog box, for Files of type, select IDF(*.emn,*.brd,*.bdf,*.idb).
- 3 Click **Options**, clear the IDF options described below, then click **OK**.
 - Add board drilled holes. If holes have been drilled in the circuit board, the holes appear in the SolidWorks part.



- **Reverse underside components**. In the rare cases where import data causes the components to be rotated incorrectly, selecting this option compensates for the misplacement and allows proper location of the component features.
- 4 Browse to \import\circuit_board.emn, then click Open.

A status bar displays the progress and the number of components.

Installation

Administrative Images

Use the **SolidWorks Administrative Director** to create an administrative image for use in multi-seat installations of the SolidWorks software. In the **SolidWorks Master Setup** dialog box, click **Administrative Tools** to create an administrative image. Previously, you had to use the command line to create an administrative image.

The administrative image wizard creates an initialization (.ini) file that contains information about how to install the SolidWorks software to clients, how to migrate registry settings to clients, various options, and so on. When you complete the wizard, an .html file is generated that you can send to each client. A user clicks the link in the .html file and the SolidWorks software is installed automatically with all of the options you specified.

SolidNetWork License

Borrowing Licenses

If you use SolidNetWork License (SNL) to access a floating license of the SolidWorks software, you can now use that license from a remote location. Previously, you could not access an SNL license if your computer was not connected to the license server.

For instance, you may use a laptop computer that is connected to the license server while you are at work, and then you take the computer home. You can now "borrow" a license so that you can use the SolidWorks software from both home and work, regardless of whether you are connected to the license server. The license is lent for a specified period of time, up to 10 days, (or as defined by your system administrator), and the license is removed from the available pool of licenses.

There are additional options that a system administrator can use to customize the borrowing of SolidWorks licenses. For example, a system administrator can:

- Define users or groups that are allowed to borrow licenses
- Set the number of licenses that cannot be borrowed

See the <u>SolidNetWork License Installation and Administration Guide</u> for more information about borrowing licenses.

eDrawings Professional

SNL now supports eDrawings Professional.

Chapter 12 Other Functionality

SolidWorks Office Add-Ins

This chapter describes enhancements to the following SolidWorks Office add-ins:

- □ eDrawings
- eDrawings Professional
- □ FeatureWorks
- D PDMWorks
- □ PhotoWorks
- □ SolidWorks Animator
- □ SolidWorks Toolbox
- □ SolidWorks Utilities

eDrawings

General

eDrawings Logo

An eDrawings logo is displayed in the corner of the HTML file if the HTML file does not show the eDrawings application frame and menus when you display it on a web page.

Email Messages

The instructions in the email sent with eDrawings files include more detailed instructions to the recipient about how to use eDrawings than were previously sent.

Unshaded Mode Line Color

When you switch the **Shaded** tool off, the model lines are shown in black to make the model more visible. This functionality is supported by all versions of eDrawings files.

Application Programming Interface

The eDrawings Application Programming Interface (API) is an OLE programming interface to eDrawings and is implemented as a Microsoft ActiveX control. You can use the eDrawings API to customize the eDrawings Viewer, create interactive web pages, and translate files. The API contains functions that you can call from Visual Basic (VB), Visual Basic for Applications (VBA), VB.NET, C++, and C#. These functions provide direct access to the eDrawings environment.

To obtain the eDrawings API Software Development Kit (SDK), which contains sample code and the eDrawings API Help, contact API Support at apisupport@solidworks.com.

Compression

eDrawings files are now saved using a new compression algorithm that automatically maximizes file compression and maintains high visual quality. The following options have been removed:

- Compress file (In the eDrawings Viewer, Save As dialog box)
- Compress this eDrawing (In the SolidWorks application, Export Options dialog box)

Download Options

When you download the eDrawings application from the solidworks.com web site, you have the option to download the DXF/DWG translator. The DXF/DWG translator lets you open DXF/DWG files in eDrawings. If you do not intend to view DXF/DWG files in eDrawings, do not download the translator, which reduces download time.

Previously the translator was downloaded automatically.

DXF/DWG XREF Paths

When you import DXF or DWG files that reference XREF, shape, or font files, you can specify the paths used to find these referenced files. You can specify multiple search paths and the search order. Previously you could not specify the path.

The eDrawings application still tries to resolve the paths automatically if none are specified. If eDrawings cannot resolve the path, it prompts you to resolve the path.

To set the XREF path:

1 Open eDrawings\HomeOffice-v3.dwg.

The **Resolve Xref** dialog box appears because eDrawings is unable to find the XREF file named **bsize**.

2 Click Skip file to skip resolving the XREF.

The DWG file opens with the XREF unresolved.

3 Select the **Layout1** tab beneath the graphics area.

Note that the sheet format, containing the title block and border, is missing because the XREF is unresolved.

- 4 Close the DWG file.
- 5 Click Tools, Options.
- 6 On the **Import** tab, under **DXF/DWG Import**, click **Add**.
- 7 Browse to **eDrawings\New_XREF_Folder\User**, then click **OK** twice to specify the path to the XREF file.
- 8 Open HomeOffice-v3.dwg and select the Layout1 tab.

The sheet format appears because you set the correct path to the XREF.





eDrawings Executables

When you close the eDrawings application launched from an eDrawings executable file, a message prompts you to install eDrawings if it is not installed on that computer. The prompt appears every fifth time you exit the eDrawings application launched from the executable file.

Shadows

The View, Shadows option has been replaced with the Tools, Options, General, Display shadows option. The shadows functionality is unchanged.

Tablet PCs

The eDrawings application is supported on Tablet PCs. You can use the pen to do electronic markups.

Toolbar Buttons

Toolbar buttons are now available for these functions:

roorbar buttons are now available for these functions.		. 121
Toolbar Button	Menu Item	And the second
🛵 Save Markup	File, Save Markup	
🛺 Mass Properties	Tools, Mass Properties	
? Help	Help, eDrawings Help Topics	

The functionality remains unchanged.

Animations

When you publish eDrawings files from SolidWorks files that contain SolidWorks Animator animations (including physical simulations imported into animations), you can view these SolidWorks Animator animations in the eDrawings Viewer. Previously, SolidWorks Animator animations were not saved in eDrawings files.



Animation creation has changed in SolidWorks 2005. See **SolidWorks Animator** on page 13-24.

To publish animations from the SolidWorks application:

1 Click Tools, Add-Ins, select SolidWorks Animator, then click OK.

You must have the SolidWorks Animator add-in enabled to publish animations in eDrawings files.

- 2 Open eDrawings/speaker.sldasm from the File Explorer 🎑
- 3 Click File, Save As.
- 4 Select eDrawings (*.easm) in Save as type.
- 5 Click Options.
- 6 Select **Save Animator Animations to eDrawings file** so you can view the animations in the eDrawings Viewer.
- 7 Click **OK**, then click **Save** to save the file as **speaker.easm** to the same folder.

To view animations in the eDrawings Viewer:

- 1 Open eDrawings/speaker.easm.
- 2 Select the **Animations** tab in the eDrawings Manager.

Animation1 is listed as an available animation. The **Time** column shows the animation runs for 5 seconds.

- 3 Click **Normal** \Rightarrow so the animation plays once and stops.
- 4 Click Play >.



Passwords

When you publish an eDrawings file from the SolidWorks application, you can assign a password to protect the eDrawings file.

You must have eDrawings Professional installed to be able to protect eDrawings files with passwords. You can add a password to new or existing eDrawings files. You can open password-protected eDrawings files using the complimentary eDrawings Viewer, provided you have the correct password.

Once protected, the password cannot be removed from the eDrawings file. The password is carried over when you save a protected eDrawings file as another file name.



Passwords do not guarantee security of the eDrawings file. They provide only a moderate level of security.

To add a password to an eDrawings file:

- In the SolidWorks application, open eDrawings/Password.sldprt from the File Explorer 2.
- 2 Click File, Save As.
- 3 Select eDrawings (*.eprt) in Save as type.
- 4 Click Password.
- 5 In the dialog box, select **Password Required to Open Document**, then type a password.
- 6 Type the same password for **Confirm Password**, then click **OK**.
- 7 Click Save.

Now open the eDrawings file to test the password.

- 1 In the eDrawings Viewer, open eDrawings/Password.eprt.
- 2 In the **Password** dialog box, type an incorrect password for **Enter Password**, then click **OK**.

A message prompts you to enter the password again.

3 Click **OK**, enter the correct password, then click **OK** to open the eDrawings file.

SolidNetWork License

SolidNetWork License (SNL) now supports eDrawings Professional. SNL allows users to install more seats of the eDrawings Professional software than they have licenses for, by floating the use of those seats without exceeding the number of licenses purchased.

For more information about purchasing SNL, contact your reseller.

Hole Wizard Holes

FeatureWorks can now recognize hole features as Hole Wizard holes using automatic or interactive recognition. You can also use step-by-step recognition to recognize Hole Wizard features in parts that contain imported bodies and Hole Wizard holes.

During the recognition process, you can re-recognize cut extrudes, cut revolves, and simple holes as Hole Wizard holes. FeatureWorks cannot re-recognize legacy holes as Hole Wizard holes.



FeatureWorks supports recognition of **ANSI Metric** standard **Counterbore** and generic **Hole** type Hole Wizard features. All other types of Hole Wizard holes are recognized as Hole Wizard **Legacy** type holes. Simple holes are recognized as generic **Hole** type Hole Wizard holes.

To set the FeatureWorks options:

- 1 Click **Open** on the Standard toolbar, or click **File**, **Open**.
- 2 In the dialog box, select Parasolid (*.x_t,*.x_b,*.xmt_txt,*.xmt_bin) in Files of type, browse to Fwks_HoleWizard.x_t, and click Open.
- 3 Click **No** to the feature recognition prompt.
- 4 Click FeatureWorks Options 😰 on the FeatureWorks toolbar, or click FeatureWorks, Options.
- 5 In the dialog box, under Advanced, clear Recognize holes as wizard holes.

When the **Recognize holes as wizard holes** option is cleared, FeatureWorks recognizes all holes as Hole Wizard **Legacy** type holes.

6 Click OK.

Proceed with feature recognition. All three holes on the imported body are Hole Wizard holes in the original part.

To recognize Hole Wizard holes using interactive recognition:

- 1 Click **Recognize Features** on the FeatureWorks toolbar, or click **FeatureWorks**, **Recognize Features**.
- 2 In the PropertyManager:
 - Under Recognition Mode, select Interactive.
 - Under Feature Group, select Standard features.



- 3 Under Interactive Features:
 - Select Cut Revolve in Feature type.
 - Select all three faces of the right-most hole in the graphics area for Selected entities ?.
- 4 Click Recognize.

The hole disappears from the model.

5 Click **Show** in the PropertyManager.

The **FeatureWorks - Feature Manager** dialog box appears. In the **Recognized Features Manager**, note that FeatureWorks recognized the hole as a cut revolve feature.

6 Right-click the cut revolve feature in the **Recognized Features Manager** and select **Re-Recognize As**, **Hole**.

The cut revolve feature is re-recognized as a Hole Wizard **Legacy** type hole because the option to recognize it as a Hole Wizard hole is cleared.



With the **Recognize holes as wizard holes** enabled, FeatureWorks would re-recognize that hole as a Hole Wizard **Counterbore** type hole.

7 In the FeatureWorks - Feature Manager, click Map Features.

To recognize the remaining holes as Hole Wizard holes using automatic recognition:

- 1 Click FeatureWorks Options 🖭 on the FeatureWorks toolbar, or click FeatureWorks, Options.
- 2 In the dialog box, under Advanced, select Recognize holes as wizard holes.
- 3 Click **OK**.
- 4 Click **Recognize Features** on the FeatureWorks toolbar, or click **FeatureWorks**, **Recognize Features**.
- 5 Under **Recognition Mode**, select **Automatic**.
- 6 Under Automatic Features, select Holes and clear all other options.
- 7 Click **Recognize**, then in the dialog box, click **Map Features**.

FeatureWorks recognizes the two remaining holes as **Counterbore** type (**CBORE for M2 Hex Head Machine Screw 1**) and generic Hole type (**M6.0(6) Diameter Hole1**) Hole Wizard holes, as shown in the FeatureManager design tree.

Step-By-Step Recognition

FeatureWorks has enhanced step-by-step recognition so you can recognize more features than was previously possible. If a part contains an imported body and any of the following features, FeatureWorks can now recognize these features:

- Base sweeps (without guide curves)
- Sketched bends
- Hem flanges
- Edge flanges
- Miter flanges
- Face fillets
- Face chamfers
- Revolves without a centerline
- Full round fillets

Except for sheet metal features, FeatureWorks also recognizes all these features if they are in multibody parts.

Miter Flanges

FeatureWorks can recognize miter flange features using interactive recognition only. FeatureWorks does not recognize miter flanges with offset or those on multiple edges.

To recognize miter flanges:

- 1 Click **Open [27**] on the Standard toolbar, or click **File**, **Open**.
- 2 In the dialog box, select Parasolid (*.x_t,*.x_b,*.xmt_txt,*.xmt_bin) in Files of type, browse to Fwks_MiterFlange.x_t, and click Open.
- 3 Click **Yes** to the feature recognition prompt.
- 4 In the PropertyManager:
 - Under Recognition Mode, select Interactive.
 - Under Feature Group, select Sheet metal features.
- 5 Under Interactive Features:
 - a) Select Miter Flange in Feature type.
 - b) Select the face shown in the graphics area for **Selected entities** \bigcirc .
 - c) Click in **Fixed face** , then select the face shown.
- 6 Click **Recognize**, then click **Map**.

FeatureWorks recognizes the miter flange, as shown in the FeatureManager design tree.



PDMWorks

Integration with SolidWorks

Task Pane

The PDMWorks[®] local view and vault view are integrated into the SolidWorks Task Pane. You can now view the Vault when no documents are open.

The local view of the Task Pane File Explorer includes My PDMWorks Documents (displaying documents in the folder specified in Client Options). In the Open in SolidWorks specified, visual cues include:

- Solid icon. A document open in its own window (an assembly, for example).
- **Transparent icon**. A document open only in memory (a component of the assembly, for example).
- Name in orange. The document is read-only.
- Name in bold. The document has been modified but not saved.

Tools for **Find/Search**, **Reporting**, **Select Labels**, and **Refresh** appear at the top of the vault view. Project folders in the PDMWorks vault view appear with the ricon.

Toolbar and Menus

A PDMWorks toolbar appears in SolidWorks with the **PDMWorks** Login, **PDMWorks Logout**, Check In (active), and **PDMWorks** Options tools.



Save and PDMWorks Check In has been added to the SolidWorks File menu; it saves the active files and opens the PDMWorks Check In dialog box.

PDMWorks has been added to the **Tools** menu; it replaces **File**, **PDMWorks Open** and opens the PDMWorks Standalone Client Window.

SolidWorks Open

You can now open documents in the PDMWorks Vault with the SolidWorks **Open** dialog box. The left panel in the dialog box contains items for **My PDMWorks Documents** and **PDMWorks Vault**.

When you select a document in the Vault that is *not* owned (checked out) by another user, the button to execute the action displays **Check Out**. If another user has checked out the selected document, the button displays **Open**, which opens the document without checking it out.

To open (rather than check out) a document that is not owned by another user, clear the **Check Out** check box so the button changes to **Open**.

The **Check Out Advanced** or **Open Advanced** button opens a dialog box so you can specify reference handling, revision, working directory, note, and so on.

Compare Documents

The **DrawCompare** utility can access drawings in a PDMWorks Vault. When you browse to a drawing, the SolidWorks **Open** dialog box appears with **My PDMWorks Documents** and **PDMWorks Vault** in the left panel. See **Comparing Drawings** on page 9-2. You can access models in a similar way with the **Compare Documents**, **Compare Features**, and **Compare Geometry** tools in SolidWorks Utilities. This allows you to browse the vault to compare different revisions of documents.

Revision Tables

PDMWorks Revision Scheme is integrated with the SolidWorks Revision Table.

- A new tab in the VaultAdmin, **Revision Table**, enables handling revision tables from PDMWorks and specifies rules for revision, number of rows, and revision order.
- When revision tables are enabled in PDMWorks, the SolidWorks Alpha/Numerical Control options are not available for Revision Table in Tools, Options, Document Properties, Tables.
- If revision tables are enabled in PDMWorks, and the drawing includes a Revision Table, then the table is updated automatically.
- You can sort tables in ascending or descending order.
- When you check in a drawing, the dialog box displays the revision in the table, and the table is updated with the current revision information. The first time the document is checked into the Vault, the revision is validated at the initial level.



Revision schemes are case-sensitive, and only uppercase letters are allowed.

Parts Not Revision-Managed

The PDMWorks Vault displays items that are not revision-managed, such as external Toolbox parts and standard parts, as references. You can specify folders for libraries of standard parts, in addition to SolidWorks Toolbox parts, on the VaultAdmin **Toolbox** tab. When you disable check-in of non-revision-managed documents, you can select an option to view referenced files in a system-controlled separate project.

A project folder is created in the vault view for each library (**Toolbox References**, for example). The name of the folder appears in blue with the number of parts in the folder displayed. Users cannot create, rename, delete, or assign ownership to the blue folders, but they can generate reports, search the project, and so on.

Chapter 13 SolidWorks Office Add-Ins

Parts that are not revision-managed also appear in blue in both the separate library project and in the projects where they are referenced. A shortcut menu with limited choices is available. You can right-click a document and select **Document Information** to determine where the document is used, for example.

SolidWorks Task Scheduler (Update and Print)

Update PDMWorks Files and **Print PDMWorks Files** are now available in SolidWorks Task Scheduler. You must have a PDMWorks client license installed on the computer using the Task Scheduler. You log in separately for each type of operation.

Update PDMWorks Files converts PDMWorks Vault files that were created at an earlier SolidWorks release to the current release. You can update the complete Vault or specify a project. You can specify whether all revisions or only the latest revision are updated. A log file lists any documents that do not convert. The vault is locked automatically during the upgrade process.

Print PDMWorks Files schedules PDMWorks batch printing. You can select the complete Vault or just one project, filter for file type (*.drw,*.slddrw, for example), and schedule a single job or recurring jobs (daily, weekly, or monthly). The documents are copied to a temporary folder on your local drive that you can specify.

PDMWorks with SolidWorks DWGEditor

You can now launch a PDMWorks Standalone client from the SolidWorks DWGEditor. You can also open DXF and DWG files from a PDMWorks Vault into the DWGEditor. For more information about the editor, see **SolidWorks DWGEditor** on page 12-4.

Check-In Enhancements

The PDMWorks **Check In** dialog box has been redesigned. Documents and references are displayed in a grid where you can edit fields (including custom properties) individually, in a group, or a whole column (click the header and enter text in the box that appears). You can apply options such as **Retain ownership** and **Delete local copy** to individual documents. Notes can be multi-line.

A VaultAdmin Lifecycle option allows clients to specify lifecycle status during check-in.

When you check in assembly and part documents, you can also check in their related drawing documents. A client option specifies whether to include drawings in check-in, check-out, and open operations. If the drawings are not in the same folders as their models, you can specify the folders for **Referenced Documents** in SolidWorks **File Locations** options.

You can now check in lightweight components, suppressed components, base parts, and externally referenced components (except externally referenced assemblies. Parts can be checked in without their assembly document. You can more easily specify the revision of references during check-in.

You are prompted if documents need to be saved before check-in.

Search Enhancements

The dialog box for searching the Vault has been enhanced with a new **Advanced Search** dialog box. To access the previous **Search** dialog box, click **Simplified**.

The **Advanced Search** dialog box includes use of logical operators to create a list of search criteria, and you can now search for configuration-specific properties and search in hidden projects.



When you generate a report of the search results, you can right-click a document in the report and select operations such as **Open Document**, **Document Information**, and so on.

To search the vault view:

- 1 Click Find/Search in the Task Pane, or right-click in the vault view and select Find/Search.
- 2 In the dialog box, define search criteria (as described in the next procedure) and select **Options** and **Direction**.
- 3 Click **Find** to find the next document in the Vault that meets the criteria, or click **Generate Report** to view a report of all documents that meet the criteria.

When you select a document in the report, the document highlights in the vault view.

To specify search criteria:

- 1 Create a search criterion in the **Advanced Search** dialog box:
 - a) Select a **Property (All Properties**, **Revision**, a custom property, and so on) to be searched.
 - b) Select a **Condition** (a text string condition such as **is (exactly)**, **is not**, and so on, or a numeric condition such as =, **not** =, and so on).
 - c) Type a Value of the property to be met.
 - d) Click **Add** to add the criterion to the list.
- 2 For subsequent criteria, select **And** or **Or** and repeat step 1.
- **3** To save the list of criteria, click **Save Criteria**. In the dialog box, browse to a folder, type a file name (default file name extension **.sqy**), and click **Save**.



To load a list of criteria saved previously, click **Load Criteria**, browse to a file, and click **Open**.

Client Options

Under **Defaults**, **Check in / Check out / Open**, you can select **Include drawings**. All related drawings are selected when you execute one of these operations.

Under **Defaults**, **Check out / Open**, you can choose **Select all references**. Then when you check out or open an assembly with the SolidWorks **Open** command, for example, the reference files are checked out or opened without clicking the **Check Out Advanced** or **Open Advanced** button to specify references. See **SolidWorks Open** on page 13-10.

Under Editing Files, you can select Edit .dwg/.dxf files using default program instead of DWGEditor. For more information on the DWGEditor, see SolidWorks DWGEditor on page 12-4.

Under My PDMWorks Documents, you can select Use most recently used SolidWorks or PDMWorks folder or browse to specify a folder. The folder is displayed in the local view in the Task Pane File Explorer.

The folder specified in **Temporary viewing files** is displayed in the local view.

API Access to Vaults

Client licenses now include API access to a Vault even if the Vault does not include the Advanced Server. In PDMWorks 2004, the Advanced Server was required for API access. The files necessary for the API operations, including operations involving SolidWorks Task Scheduler (see **SolidWorks Task Scheduler (Update and Print)** on page 13-12), are installed automatically with the client.

PDMWorks Triggers and Web Portal clients still require the PDMWorks Advanced Server. Check-in APIs require client licenses.

Administration Enhancements

Vault passwords are now encrypted.

Shortcut menus now include standard Windows commands in addition to PDMWorks items.

The Vault locks automatically during file updating operations. See **SolidWorks Task Scheduler (Update and Print)** on page 13-12. In addition, you can specify in the VaultAdmin **Vault Settings** for the Vault to be unlocked for one user, typically the vault administrator.

Delete Documents

When deleting documents from the Vault, you can specify:

- Scope (children)
- Roll back to a specified revision (You are warned if a revision is referenced.)

Copy Projects

You can copy projects. On the VaultAdmin **Projects** tab, select a project and click **Copy Project**.

A grid displays the documents in the project so you can specify which documents to copy.

You must create new names so the document names are unique. You can append a prefix or suffix to all the document names in a single operation.

You can also change the columns of data (**Document**, **Number**, **Description**, **Owner**, **Status**) by selecting and editing individual cells, or by clicking a column header to edit all items in the column.

With **Advanced Select / Replace**, you can edit the fields. Specify text to search for, add or replace text, and select or clear documents for copying based on specified criteria.

You can specify the name of the new project folder, its description, and its parent. Only the latest revision of the documents is copied to the new project.

Any information that appears in red is not valid because it duplicates information already in the Vault.

Bulk Check-In

The Bulk Check In dialog box includes a filter for document types (SolidWorks Files (*.sldprt, *.sldasm, *.slddrw), eDrawings Files (*.eprt, *.easm, *.edrw), and so on). For file types not in the list, you can select Other Types of files As Specified Below and enter a file type.

You can double-click headers to sort the documents.

Bulk check-in now allows you to specify lifecycle status and create new subproject folders. Lifecycle status is validated.

Triggers

The following Triggers have been added:

- Bump Revision
- Modify Custom Property
- Detailed Modify Project
- Open Document
- Rename Document

Web Portal

Each time you open a new Web Portal, a separate browser window is launched so you can view multiple documents simultaneously.

PhotoWorks

General Enhancements

Some enhancements to the PhotoWorks[™] add-in include:

□ General

- All the icons in the toolbar, the dialog boxes, and the RenderManager 🔀 tab now follow the Windows XP look.
- An **OpenGL out** button has been added to the **Preview** dialog box to switch between **OpenGL** and **Ray Trace** previews.
- The default **Screen image gamma correction** value is **1**. In earlier versions, this was **1.5**. Images rendered to screen appear darker in SolidWorks 2005.
- You can view a full size image of a decal from the **Decal Editor** dialog box. Rightclick a decal on the **Manager** tab and select **View Image File**.
- Indirect Illumination
 - The indirect illumination options have moved to the **Illumination** tab of the **Options** dialog box from the **Advanced** tab.
 - The number of indirect illumination rays is shown on the **Illumination** tab of the **Options** dialog box. This value is read-only.
 - You can set the radius for indirect illumination. The radius is the maximum distance from where a photon hits a surface to where the rendering engine stops calculating indirect illumination.
- □ Lights
 - PhotoWorks lighting options are available by clicking **PhotoWorks Properties** in a lighting PropertyManager. See **Lighting** on page 4-9.
 - You can turn lights on and off for your PhotoWorks scene via the RenderManager tab. Right-click a light and toggle **On in PhotoWorks**. This does not affect the visibility of the lights in the SolidWorks modeling environment.

□ Materials

There are five new materials. The folder **\miscellaneous\Studio Materials** holds four materials used by **PhotoWorks Studio**. The folder **\miscellaneous\water** holds the new **liquid** material that uses the enhanced dielectric materials. Note the difference between the **water** material and the **liquid** material:



PhotoWorks Studio

The new PhotoWorks Studio allows you to render a model in an existing scene with lights. You select from one of the studios and the scene and lights are automatically added.

You can change the quality and brightness of the image without customizing settings in the **Options** dialog box or lighting PropertyManagers. Move the sliders in the **PhotoWorks Studio** PropertyManager to change the quality and brightness. Adjusting the brightness slider does not change the properties of the lights in the scene.

To render a model:

- 1 Open indent.sldprt from the File Explorer 🎑.
- 2 Click Edit Material 📴 on the Standard toolbar, or click Edit, Appearance, Material.
- 3 In the PropertyManager, under Materials, expand Iron and select Malleable Cast Iron.
- 4 Click OK 🕢
- 5 Click PhotoWorks Studio on the PhotoWorks toolbar, or click PhotoWorks, PhotoWorks Studio.
- 6 In the PropertyManager, under Scenery, select Infinite White Floor in List of Available Studios.



Click the preview of the scene in the PropertyManager to view a larger preview.

7 Under Scene settings, move the Render Quality slider to low, and click Render.

The model is rendered with the material that you set in SolidWorks and the scene that you set in the **PhotoWorks Studio** PropertyManager. Lights are automatically added to the scene. With the **Render Quality** slider set to **low**, no shadows are cast.

- 8 Under Scene settings, move the Render Quality slider to medium, and click Render.
- 9 Click OK 🕢.

Note one difference is that opaque shadows are in the image. If you continued to increase the quality, transparent shadows and high anti-aliasing quality would be used to render the image.



Caustics

Caustic effects are the result of indirect illumination.

Light is emitted from a light source, goes through one

or more specular reflections or transmissions, hits a diffuse object, and reflects to the viewer. You can enable caustic effects independent of indirect illumination effects on the **lllumination** tab of the **Options** dialog box.

For example, consider light patterns on the bottom of a swimming pool. Light is emitted from a light source, the sun. The light goes through one or more specular transmissions as it passes through the water. The light hits a diffuse object, the bottom of the pool. Finally, the viewer sees the caustic effects on the bottom of the pool.



For caustic effects to appear in PhotoWorks, the following must be true:

- Caustic effects must be turned on in the **Options** dialog box.
- One or more specular materials must be set to cast caustic photons.
- One or more diffuse materials must be set to receive caustic photons.
- A light source must emit caustic photons. Directional, point, and spot lights can emit caustic photons.

To set the caustic options:

- Open \SolidWorks_Office\caustics.sldprt from the File Explorer
- 2 Click **Options** on the PhotoWorks toolbar, or click **PhotoWorks**, **Options**.
- 3 On the Illumination tab, under Caustics, select Enable caustic.
- 4 Click **Apply**, then **Close**.

To set the caustic options on the materials:

1 On the RenderManager ktab, expand Materials. Right-click polished brass and select Edit.

This is the material on the ring in the model.

2 On the Illumination tab, select Cast. Click Apply, then Close.

This specular and reflective material now casts photons.

- 3 Right-click **injected plastic** and select **Edit**. This is the material on the base of the model.
- 4 On the **Illumination** tab, select **Receive**. Click **Apply**, then **Close**.

This diffuse material now receives photons.

To set the caustic options on the light source:

- 1 On the FeatureManager design tree stab, expand Lighting, then right-click Spot1 and select Properties.
- 2 Under Basic, click PhotoWorks Properties.
- 3 Under Advanced, set Energy to 30 and C photons to 10.
- 4 Click OK 🕢.

To render the model:

1 Click **Render** on the PhotoWorks toolbar, or click **PhotoWorks**, **Render**.

Note the distinct dots on the base from the photons emitted by the spot light that reflect off the ring.



- 2 Edit the spot light and change **C photons** to **100**.
- 3 Render the model again.

Note the dots on the base are less clear as more than one photon is reflected on top of another. Also, the dots are fainter because the energy of the spot light is shared among ten times as many photons.



Global Illumination

Global illumination in PhotoWorks includes all forms of indirect illumination other than that caused by caustic effects. Indirect illumination comes from an object in the scene other than a light source. Global illumination typically affects most objects in the scene.

For global illumination effects to appear in PhotoWorks, the following must be true:

- Global illumination effects must be turned on in the **Options** dialog box.
- One or more specular materials must be set to cast global illumination photons.
- One or more diffuse materials must be set to receive global illumination photons.
- A light source must emit global illumination photons. Directional, point, and spot lights can emit global illumination photons.

To set the global illumination options:

- 1 Open \SolidWorks_Office\global_illumination.sldprt from the File Explorer
- 2 Click **Options** on the PhotoWorks toolbar, or click **PhotoWorks**, **Options**.

3 On the Illumination tab, under Global Illumination, select Enable global illumination and All materials cast and receive illumination by default.

Global illumination now affects all materials on the model and in the scene.

4 Click **Apply**, then **Close**.

To add a material:

- 1 Select the face shown.
- 2 Click Materials 💽 on the PhotoWorks toolbar, or click PhotoWorks, Material.
- 3 Expand plastics, miscellaneous and select blue polished plastic.
- 4 On the **Illumination** tab:
 - Select Conductor in Material type.
 - Set Diffuse to 0.9.
 - Set Specular to 0.1.

A higher **Diffuse** value increases the effect of indirect rays cast onto the material.

5 Click **Apply**, then **Close**.

To set the global illumination options for the light:

- 1 In the FeatureManager design tree, expand Lighting, then right-click Directional1 and select Properties.
- 2 Under Basic, click PhotoWorks Properties.
- 3 Under Advanced, set Energy to 60 and G photons to 10000.
- 4 Click **OK** 🕢.

To render the model:

1 Click Render 📓 on the PhotoWorks toolbar, or click PhotoWorks, Render.

Note the effect of the global illumination on the blue wall. The dots from the photons are visible and the wall appears splotchy.





- 2 Edit the directional light and change **G photons** to **100000**.
- 3 Render the model again. Note that it takes longer because of the increased photons. Note the blue wall looks much smoother now.



Decal and Texture Mapping

Improvements have been made to how you add decals and 2D texture mapped materials. When the **Preview** dialog box renders using **Open GL**, you see feedback on the size and orientation of the decal or texture. Arrows and lines appear in the preview to indicate the origin, axis of rotation, height, width, and so on. The image shows an example of planar mapping.

Additional enhancements include:

- **Reset aspect ratio**. Click **Use Image Ratio** to reset the decal or texture to its original size.
- Fit width or fit height to selection. You can fit the decal or texture to the height of the selected face, the width of the selected face, or both the height and width. In earlier versions, you could only fit to the entire face.

To add a decal:

- 1 Open \SolidWorks_Office\coffeecup.sldprt from the File Explorer 2.
- 2 Select the face shown, then click **New Decal** on the PhotoWorks toolbar, or click **PhotoWorks**, **Decal**.
- 3 In the **Preview** dialog box:
 - Click **Render**, **Immediate** to immediately see the effects of changes you make in the **Decal Editor** dialog box.
 - Click OpenGL , or click Render, Opengl.





4 In the **Decal Editor** dialog box, on the **Manager** tab, select the decal shown. Note the preview.



- 5 On the **Texture** tab:
 - Set **About axis** to **115°** to rotate about the axis of the selected cylindrical face. The axis is represented by the green line in the preview and the angle is represented by the red curved arrow.
 - Set Rotation Angle 🐼 to 180° to flip the decal.
 - Clear Fixed aspect ratio.
 - Set Width 📋 to 30. The width is represented by the distance between the pink lines in the preview.
 - Set **Height I** to **45**. The height is represented by the distance between the blue lines in the preview.
- 6 Click **Apply**, then **Close**.
- 7 Click **Render** on the PhotoWorks toolbar, or click **PhotoWorks**, **Render**.

Environment Scenes

Enhancements to environment scenes include:

- **Floors**. Floors have been added to spherical environment scenes.
- **Size/Alignment**. A single value for the radius of a spherical environment replaces the values for length, width, and height.
- **Single image**. A single 2D image is used for a spherical environment. In earlier versions, two copies of the same image were used for the top and bottom of the sphere resulting in a seam where the images met.
- Background image as environment. You can use a 2D image as a reflective spherical or cubical environment. The 2D image appears only as a reflection on the model and is not visible in the background. Select a Scaled image on the Back/
 Foreground tab of the Scene Editor dialog box. Then, select Enable spherical environment or Enable cubical environment.



SolidWorks Animator

SolidWorks Animator has shifted from a path-based interface to a key points-based interface, in which you decide how your assembly should look at various times, and then the SolidWorks Animator application computes the sequences needed to go from one position to the next. Key points-based animation uses three basic user interface elements:

- Timeline. The area that displays the times and types of animation events.
- **Timebar**. The entity you position along the timeline to indicate the time in the animation you are viewing or editing.
- **Key points**. The entities that correspond to assembly components, visual properties, and so on.

Using key points-based animation means:

- You position a timebar along the timeline to define where you want a change to end. Changes can include the motion of an assembly component, different viewpoints, and so on.
- You position the assembly components in the graphics area where you want them to be at the time indicated by the position of the timebar.
- SolidWorks Animator positions the appropriate key points, based on the position of the timebar, and solves the required animation, so that the components reach the positions you designated.

You can animate the following:

- Component position
- Value of a distance mate
- Value of an angle mate
- Component properties
- Viewpoint orientation
- Component color
- Component texture

You can continue to reposition components, viewpoint orientation, texture, and so on as part of the same animation, or you can create multiple animations each with its own key points, component positions, viewpoints, and so on. Animations are no longer configuration specific.

Animation Tabs

To access SolidWorks Animator, use the tabs located at the bottom left of the graphics area. Tabs can include any of the following types:

- **Model**. Selected by default when you open a model. When selected, the graphics area appears normally.
- Animation1. Always displays whenever you open a model. The tab may have an empty animation with no sequences, or it may have an animation that includes multiple sequences.
- Animation [*identifier*]. Displays when animations created using previous releases of SolidWorks Animator are included with the assembly. The appended name identifies the configuration, if any, used to create the animation.
- Animation2. Displays if you created a new tab (see **Key Points** on page 13-28). Each incremental tab can include one or more animated sequences.



Animation tabs appears for parts or assemblies. You can rename any tab by right-clicking the tab and selecting **Rename**.

User Interface

When you select an **Animation** tab, the graphics area splits horizontally. The upper area displays the model, and the lower area splits vertically into two sections:

• Lower left section displays the SolidWorks Animator tools and a duplicate of the FeatureManager design tree so that the assembly components align with the timeline. You can select a component using either FeatureManager design tree.



 Lower right section displays the timeline. You use the timeline to position the timebar so that SolidWorks Animator can assign the corresponding key points .



Driving and Driven Components

When you move a component that drives the motion of related components, the system animates the driven components as well. Along the timeline, the motion of driving components is represented by a green bar, whereas the motion of driven components is represented by a yellow bar (see **Key Points** on page 13-28).

Timeline

The timeline is the temporal interface for the animation. It works in association with positioning assembly components in the graphics area, or adding visual changes to the components. Visual changes to components include altering the model view and the appearance (color, texture, and display properties) of the model.

The timeline is divided by vertical grid lines corresponding to numerical markers showing the time. The numerical markers start at **00:00:00**, and by default, are spaced depending on the size of the window. For example, there may be one marker every one, two, or five seconds along the timeline.

Timebar

The solid black vertical line on the timeline, is the timebar It represents the animation's current time. You can move the timebar by dragging it or by clicking anywhere in the timeline except over a key. When you move the timebar, you change the current time in the animation, and the model updates accordingly.



When the pointer is on the timeline, pressing the space bar advances the timebar to the next increment.

Using the Timeline

To use the timeline to create the animation, first position the timebar where you want the event to end. Then move the components and the viewpoint in the graphics area. Repeat this process for each additional animation sequence.

SolidWorks Animator Tools

The SolidWorks Animator toolbar appears above the SolidWorks Animator FeatureManager design tree, and displays the following tools:

ΤοοΙ	Function
	Play from start
	Play
	Stop
	Display animation mode: → Normal ← Loop ← Reciprocate
-	Record . Records the animation so you can save it to an .avi file.
毁	Animation Wizard. Starts the wizard (see Key Points on page 13-28).
\$ +	Place New Key . Inserts a Key point (a) at the position you select. Different colors represent different functions. For example, a green key, represents a component which you can animate (see Key Points on page 13-28).
◊-	Delete. Deletes a Key point 🔶.
٩	Zoom In . Enlarges the size of the timeline to increase space between the timebars.
P	Zoom Out . Reduces the size of the timeline to display a longer time span.

Key Points

Each **Key point** on the timeline represents a beginning or end of motion in time. Whenever you position a new **Key point**, it corresponds to motion or changes to visual attributes. Some types of key points include:

Key Points

Black key points represent all non-movement attributes, including:

- Viewpoint Orientation **(b)**. You can change the view of the model as part of the animation. Use the tools from the View or Standard Views toolbars, and position the model, relative to the timebar.
- Visual Attributes. These key points include editable attributes such as **Appearance** and **Texture**. Dragging the component key point also moves any associated component attributes.
- Unconstrained Move. Indicates movement that is not restricted.
- Green key points represent any selected key.
- Green key with black border represent component.
 - **Bad Solve**. When constraints in the model prevent a component from moving where you had placed it earlier, the green key will turn red. For example, if you animate a component and then later fix the component or add a mate that restricts its movement, the keys you defined earlier will turn red.
- Interim key points. These are added by Animator to prevent conflicts. Conflicts can occur with components that operate in tandem, such as pistons driven by a crankshaft in an engine. If you move the crankshaft, position the appropriate key point, and then position the key point for a piston further down on the time bar, SolidWorks Animator adds interim key points for the piston to account for their motion.
 - Blue key points represent distance or angle mate movement.

Changebars are horizontal lines that sometimes connect **Key points**. Changebars serve as visual cues to the component, and to the type of motion. Some types of motion include:

Changebars between key points



Key Properties

When you move the pointer over any key point, a balloon displays the basic properties for that key point. The example displays the key properties for **Slide2<1>** at two different instances in the animation.



Some of the key properties include:

- Name of the component, or name of the component the key property is related to.
- Position of the key point along the timeline (the example is on the timebar located at **00:00:00**).
- Visual attributes such as color of the component (the example is mustard color).
- View, such as shaded, wireframe, and so on.
- Interpolation mode (see Shortcuts from the Timeline on page 13-30).
- Encoding, whether the key point encodes viewpoint, component movement, or both.



When you move the pointer over any key point, the graphic area updates to display the corresponding position of the component.

SolidWorks Animator Shortcut Menu

The SolidWorks Animator shortcut menu is dynamic. You can right-click entities from the Animator FeatureManager design tree, from the timeline area, or an **Animation** tab to display a shortcut menu.

Shortcuts from the Animator FeatureManager Design Tree

Component or other assembly item. List component display options (see **Component Display Animation** on page 13-31).

View Orientation. Allows you to select Lock and Suppress view orientations.

- **Suppress**. Select to suppress viewpoint orientation keys in the animation, so that the model view does not change during playback, or while editing the animation. Clear to allow the animation to set the model view.
- Lock. Select during editing to prevent adding new key points as you spin the model. Clear to include changes in viewpoint orientation as part of the animation.
- Suppress is selected.
- b Lock is selected.
- **Suppress** and **Lock** are both cleared.



When **Suppress** is selected, you cannot clear **Lock**. However, when **Suppress** is cleared, you can select or clear **Lock**.

Shortcuts from the Timeline

Key point. Manipulate existing key points positioned when you placed the timebar during animation editing (see **Key Points** on page 13-28).

View Orientation •. Right-click and select any of the following:

- Cut or Copy. Then move your pointer, and select **Paste** where you want to position the new **key point**.
- Place key point. Add a new key point \blacklozenge , or a set of associated key points at the pointer location, then drag the key point left or right to adjust the position.



When you display the shortcut menu and select **Place Key**, the vertical position of your pointer determines which key point or series of associated key points is affected (see **Key Points** on page 13-28).

• Select All. Select all the key points. You can select a key point, and then drag to position all the key points where you place your pointer, or choose Select All and then choose Delete to return the animation to its pre-animation state.



You can select more than one key point from the timeline and choose **Reverse Path** to reverse the animation of entities that correspond to the key points you selected. The position and any visual properties are reversed. No additional reverse animation sequence is created.

Component \blacklozenge . Right-click, select all functions available with a view orientation key point \blacklozenge , plus any of the following:

Interpolation modes

This enables you to control the acceleration or deceleration of a component or a visual property during the playback. For example, if a component changes from time **00:00:02** to time **00:00:06**, you can adjust the playback motion from A to B, by selecting any of the following:

- Linear Z. The default setting moves the component from time 00:00:02 to time 00:00:06 at a uniform velocity from position A to position B.
- Snap . The component remains in a stationary position A until time 00:00:06 is reached, then it snaps to position B.
- **Ease in** \bigcup . The component starts moving uniformly, buts accelerates towards position B as it approaches time **00:00:06**.
- Ease out *C*. The component starts accelerating at time 00:00:02, but as it approaches position B, it decelerates towards time 00:00:06.
- Ease in/Ease out \checkmark . Combines the motion so that the component accelerates to the halfway time between position A and position B, and then decelerates as it approaches time 00:00:06.

Animation Wizard

Start the Animation Wizard. The functions in the Animation Wizard have not changed. You can select **Rotate model**, **Explode**, **Collapse** or **Physical Simulation** if a physical simulation was previously enabled.

Shortcuts from the Animation Tab

Animation. Select Insert, Rename, or Delete to insert a new Animation tab, rename the existing tab, or delete an Animation tab.

Component Display Animation

Right-click any component in the Animator FeatureManager design tree, or in the graphics area to modify the display for that component.

You can animate the display of single or multiple components, and combine different display options within the same or different assembly components.

To use component display options:

- 1 Right-click a component in the Animator FeatureManager design tree.
- 2 Select from the menu items:
 - Hide 🛞. Hide or show the component.
 - Change Transparency Ref. Add transparency to the component. If transparent, select Change Transparency again to remove transparency.
 - **Component Display**. Change how a component displays. Select from SolidWorks display options such as **Wireframe**, **Shaded**, and so on. **Default Display** returns the component display to its original state.



Move with Triad. Add a reference triad to the graphics area that you can position anywhere in the graphics area.

The triad facilitates the movement and the orientation of the assembly based on the X, Y, and Z axes.

- Appearance. Select Color iii or Texture iii to modify either of these visual attributes on the selected component.
- Properties 📷. Display the Component Properties dialog box.
- Zoom to selection . Display an enlarged view of the component. The size of the view is relative to the size of the assembly, and to the number of components. You can also use any of the tools on the View toolbar.



With the Animation tab selected, Collision Detection and Physical Dynamics are disabled if you try to move a component with the Move Component tool on the Assembly toolbar.

Limit Mates

You can add a limit mate (**Distance** or **Angle**) to an assembly, and create the animation based on the movement specified by the mate.



Set an Angle type of limit mate, then animate the rotation. The degree of rotation is defined by the maximum and minimum values you set in the Angle mate.

Once you create the animation, you can click on any section of the timeline to display a preview of the position of the components at that time increment.
To create an animation:

- Open animator\nested_slides.sldasm from the File Explorer .
- 2 Select **Animation1** at the bottom of the graphics area.

The graphics area splits horizontally. The top area displays the model. The bottom area splits vertically into two sections:

- The Animator toolbar and Animator FeatureManager design tree on the left.
- The timeline with the key points and the timebar on the right.
- 3 Click **Rotate View** (3) on the Views toolbar, and spin the model to display the bottom.
- 4 On the timeline, click at the **5** second mark.

The timebar is inserted at the **5** second mark.

5 Drag the component, **Slide2<1>**, into position, as shown.

The retaining pins on **Slide2<1>** should be almost adjacent with the ends of the slots. Note the following:

- All key points that belong to **Slide2<1>** move to the **5** second mark.
- The green changebar indicates a driving component.



If you were to play the animation, the model would return to its original isometric view, because **View Orientation** is set to **Lock**.

- 6 On the timeline, click at the **9** second mark.
- 7 Drag the component **Slide1<1>**, as shown.

The single retaining pin should be almost adjacent with the end of the slot.





The timebar is inserted at the **9** second mark.

- 8 In the Animator FeatureManager design tree, right-click Slide1<1>, and select Component Display, Wireframe.
- 9 Click **Play from start >** on the SolidWorks Animator toolbar.

Slide2<1> begins the animation, and towards the **5** second mark, Slide2<1> starts to move, changing to wireframe as it approaches the **10** second mark.

The timeline appears as follows after you play the animation:



Save Animation to File

You can save a partial animation by selecting a start and end frame value.

To save a partial animation:

- 1 Create the animation.
- 2 Select **Record [**] on the Animator toolbar to save the animation an **.avi** file.
- 3 In the dialog box:
 - a) Browse to a folder.
 - b) Type a name for **File name**.
 - c) Type a value for Frames per second (7.5 is the default).
 - d) Select Enter start and end frame.
 - e) Enter values for a starting frame and an ending frame.
- 4 Click Save.

Access Control

You can add administrative access to the standards and options of SolidWorks Toolbox. An administrator selects a password and forces settings to be view only. Individual users will be able to view, but not modify, the settings without the administrative password. You can restrict the following settings:

- Standards data. The data in the Edit Data tab of the Configure Data dialog box
- Toolbox options. The options on the **Browser** tab of the **Configure Browser** dialog box
- Add My Parts Wizard. The Add My Parts Wizard dialog box
- Smart Fasteners options. The options on the **Smart Fasteners** tab of the **Configure Browser** dialog box

To set administrative access:

- 1 Click **Options** in the Standard toolbar, or click **Tools**, **Options**.
- 2 On the System Options tab, click Data Options.
- 3 Click Edit Standards Data, then click the Access Control tab.

There you create a password and change the settings under **User Access Control**. When a check box is cleared by the administrator, a user can view, but not modify, those settings.

Configure Browser

Read-Only Documents

The read-only options under **Inserting documents into SolidWorks** of the **Document Properties** portion of the **Configure Browser** dialog box have been removed. All Toolbox documents now follow the read-only attributes of the file.

Access to Toolbox Library Data

The information on standards, catalogs, documents, and alternate file names is now accessed from the **Options** dialog box within the SolidWorks software. In earlier versions, you access the information from the **Configure Browser** dialog box.

This redesign facilitates the sharing of the information with Hole Wizard. If you disable an item that is shared by Toolbox and Hole Wizard, the item is disabled for both functions. If you turn off the Toolbox Browser add-in, only the catalogs, chapters, and pages appropriate for Hole Wizard appear in the tree on the **Edit Data** tab of the **Configure Data** dialog box.

Configure Data

There have been many enhancements to the editing of standards, catalogs, and the components in the SolidWorks Toolbox library. Click **Data Options**, **Edit Standards Data** on the **System Options** dialog box to open the **Configure Data** dialog box.

User-defined Standards

User-defined standards appear with a new icon 🕏 before the standard's name.

To create a new standard:

- 1 Click **Options [** on the Standard toolbar, or click **Tools**, **Options**.
- 2 On the System Options tab, click Data Options.
- 3 Click Edit Standards Data.
- 4 On the Edit Data tab, select Standards at the top of the tree.
- 5 Type whatsnew for New Standard Name.
- 6 Select ISO in Derived From and click Create new standard.

A progress bar appears, then a new standard is added to the Toolbox library.

7 Keep the **Configure Data** dialog box open for the next procedure.

Enable/Disable Item

Now, you select a standard, catalog, page, or document in the tree and select **Disabled**. This disables the selected item and all items below it in the hierarchy. The light bulb icon \mathcal{G} changes to \mathcal{G} when you disable an item. The behavior of a disabled item is unchanged from earlier versions of SolidWorks Toolbox.

To disable items in the Toolbox library:

1 If you have not completed the **User-defined Standards** section, you must do so before proceeding.



You can enable and disable items in default standards or user-defined standards. A user-defined standard is used for this example.

- 2 On the Edit Data tab of the Configure Data dialog box, expand whatsnew, then Nuts, then Hex Nuts.
- 3 Select **Hex Nuts**, then select **Disabled**.

Hex Nuts and all of the documents under **Hex Nuts** are now disabled. They will not appear in the Toolbox Browser in the **Task Pane**.

4 Keep the **Configure Data** dialog box open for the next procedure.

Enable/Disable Values

You can now disable individual sizes, lengths, finish types, and other values for the properties of documents. In earlier versions, you could not disable individual values.

To disable a value:

- 1 If you have not completed the **User-defined Standards** section, you must do so before proceeding.
- 2 On the Edit Data tab of the Configure Data dialog box, expand whatsnew, then Nuts, then Hex Nuts Fine Pitch.
- 3 Select Hex Nut Style 1 Fine ISO 8673.
- 4 On the Finish tab, select Disabled next to Washer-face.

The value, **Washer-face**, is now disabled and will not appear when you add a **Hex Nut Style 1 Fine ISO - 8673** to an assembly.

5 Keep the **Configure Data** dialog box open for the next procedure.

Shared Properties

The disabling of some properties is shared within a standard or catalog. This occurs for properties that are common to more than one type of fastener. Shared properties are denoted by a on the tab. For example, if you disable **Schematic** threads for a countersunk bolt, then **Schematic** threads are disabled for all other bolts and screws within the standard or catalog. Some shared properties include: **Finish**, **Thread Display**, and **Drive Type**.

Custom Properties

Custom properties that you add to SolidWorks Toolbox documents appear as a tab in the **Configure Data** dialog box. You must select **Each value for this property requires a new configuration name** when you add the custom property. Custom properties are denoted by \square on the tab.

Alternate File Name

Select a catalog document and add an alternate file name on the **Properties** tab. The behavior of an alternate file name remains unchanged from earlier versions.

Access to More Properties

In earlier versions, you could view and edit the size of the components including diameter, length, thread length, and so on in the **Configure Data** dialog box. Now, you can also view and disable the thread display, finish, hub style, keyway, and many other properties in this dialog box. This allows you to view the available properties of many components in one location before you insert the component into an assembly.

Part Numbers and Descriptions

You can now add the part numbers and descriptions for every configuration of a document. After generating all configurations, you can optionally export the data to Microsoft Excel, enter the part numbers and descriptions, then re-import the data. In earlier versions, you had to enter the part numbers and descriptions one configuration at a time as you added the document to an assembly.

To enter part numbers and descriptions:

- 1 If you have not completed the **User-defined Standards** section, you must do so before proceeding.
- 2 On the Edit Data tab of the Configure Data dialog box, expand whatsnew, then Washers, then Plain Washers.
- 3 Select Washer ISO 8738 Clevis Pin.
- 4 Click the All Configurations tab.

The software generates and displays all the configurations for the washer.

- 5 Click **Export** and save the spreadsheet as **whatsnew washer.xls**.
- 6 Open the spreadsheet in Excel and enter part numbers and descriptions in the appropriate column.

The values in the **Part Numbers** column must be unique. Also, do not delete any columns from the spreadsheet.

- 7 Save and close the spreadsheet.
- 8 In the **Configure Data** dialog box, click **Import** and open **whatsnew washer.xls**.

The part numbers and descriptions appear in the dialog box and appear when you insert the documents into an assembly.

9 Click **OK**.

SolidWorks Utilities

Compare Features

The **Compare Features** tool now supports appearance properties, including colors, optics, and textures.

To compare the appearance properties using Compare Features:

1 Open \SolidWorks_Office\wheel_A.sldprt and \SolidWorks_Office\wheel_B.sldprt from the File Explorer _____.



wheel_A.sldprt



wheel_B.sldprt

- 2 Click Compare Features et al on the Utilities toolbar, or click Utilities, Compare Features.
- 3 In the dialog box:
 - a) Select wheel_A.sldprt in Reference Part.
 - b) Select wheel_B.sldprt in Modified Part.
 - c) Click Compare.
- 4 In the Compare Features: Results dialog box, expand Modified Features.
- 5 Click Pair 1.

The **Color**, **Color values**, and **Transparency** values for both parts are listed because they differ in both parts.

6 Click Pair 2.

The textures for both parts are listed because they each have a different texture.

Compare Geometry

The **Compare Geometry** utility now supports assemblies when evaluating volume comparison only.

The definition of a "modified face" has been updated for the **Compare Geometry** tool. A "modified face" now includes overlapping faces if the intersection area of two faces is more than 50% of the area of the smaller face.

To determine modified faces with the Compare Geometry tool:

1 Open \SolidWorks_Office\block_A.sldprt and \SolidWorks_Office\block_B.sldprt from the File Explorer a.

Block_B.sldprt is a modified version of block_A.sldprt.

- 2 Click Compare Geometry 📑 on the Utilities toolbar, or click Utilities, Compare Geometry.
- 3 In the dialog box:
 - a) Select block_A.sldprt in Reference Document.
 - b) Select block_B.sldprt in Modified Document.
 - c) Click Compare.
- 4 In the Compare Geometry: Results dialog box, expand Face Comparison and Modified Faces.

Pair 1 and **Pair 2** are listed as **Modified Faces**. In previous versions of SolidWorks Utilities, these faces would have been **Unique Faces**.

- 5 Click Close.
- 6 Click **No** when you are prompted to convert the volume comparison results into solid bodies.

Feature Paint

The **Feature Paint** tool allows you to paint texture properties to other features. Additionally, when you paint optical properties, the properties are broken down into transparency, ambience, diffusion, specularity, shininess, and emissivity. In previous versions of SolidWorks Utilities, these properties were contained under **Advanced Color Properties**.

> If texture properties are applied to the target feature but not to the source feature, the texture properties are not removed from the target feature.

To paint texture and optical properties to other features:

1 Open

\SolidWorks_Office\countertop.sldprt from the File Explorer

The countertop has a granite texture and the inside of the sink is beige.

- 2 Click Feature Paint on the Utilities toolbar, or click Utilities, Feature Paint.
- 3 In the dialog box, make sure **Paste** appearance properties is selected.
- 4 In the FeatureManager design tree:
 - a) Select Base-Extrude for Copy properties from.
 - b) Select Cut-Extrude1, Cut-Extrude7, Fillet1, Fillet2, and Fillet3 for Paste properties to.
- 5 Click **Apply**, but do not close the dialog box.

The granite texture is applied to the selected features.

- 6 In the FeatureManager design tree:
 - a) Select Shell1 for Copy properties from.
 - b) Select Boss-Loft1 for Paste properties to.
- 7 Click Apply.

The color and optical properties are applied to the outside of the sink.





Find/Modify/Suppress/Simplify

The **Simplify** tool has been added to the **Find/Modify/Suppress** utility. For every part, SolidWorks Utilities determines an internal calculation of "insignificant volume" based on the size of the part. You can enter a simplification factor that increases or decreases the insignificant volume factor. Supported features below the insignificant volume can be suppressed to a derived configuration so you can perform analysis (using COSMOSXpress) on the simplified part.

To create a simplified part:

- Open \detailing\Top_plate.sldprt from the File Explorer 2.
- 2 Click Simplify part **Q** on the Utilities toolbar, or click Utilities, Simplify.
- 3 In the dialog box:
 - a) Select Fillets in Simplify.
 - b) Set Simplification factor to 1.
 - c) Click **Find Now**. You must perform the **Find** utility before the **Simplify** utility.



A fillet feature is found as insignificant geometry based on the simplification factor. The following attributes are listed in the dialog box:

- **Feature name**. The name of the feature as shown in the FeatureManager design tree.
- Feature type.
- Defining parameter. The parameter that indicates why the feature was found.
- Value. The value of the Defining parameter.
- Limiting value. The Simplification factor multiplied by the internal calculation for insignificant volume.
- State. This displays the text, Suppressed, if the feature is suppressed.
- 4 In the dialog box:
 - a) Under Feature name, select Fillet1.
 - b) Make sure **Create derived configuration** is selected. When the part is simplified, the fillets are suppressed in a derived configuration.
 - c) Click Suppress.

A derived configuration is created, called **Simplify_1**.



Geometry Analysis

The definition of a "small face" has been updated for the **Geometry Analysis** tool. A "small face" is one where all edges of the face are smaller than the specified length *and* the area of the face is less than the square of the specified length of an edge. Previously, a "small face" was one where all of its edges were smaller than a specified length.



Power Select

The **Power Select** tool now supports new feature types including sheet metal features and body features (Curve Driven Patterns, Deform features, Structural Members, and so on). Additionally, the **Power Select** tool uses a new interface to select feature types.

To use the Power Select tool:

- 1 Open \detailing\tree_gate_simplified.sldprt from the File Explorer
- 2 Click Power Select ion the Utilities toolbar, or click Utilities, Power Select.
- 3 In the dialog box:
 - a) Under Select what, clear all items except Features.
 - b) Under Filters and parameters, clear all items except Feature type.
 - c) Expand Weldments in the features list, then select Trim/Extend.
 - d) Click Search.

The utility finds one feature, **Trim/Extend5**, and highlights it in the graphics area.



Reports

When you create a report in SolidWorks Utilities, you can save the report to the Design Binder. You can create reports with the following utilities: **Compare Features**, **Compare Geometry**, **Compare Documents**, **Geometry Analysis**, and **Thickness Analysis**. See **Design Journal** on page 1-7.

To save a report to the Design Binder:

- 1 Open \SolidWorks_Office\bucket.sldprt from the File Explorer 2.
- 2 Click Geometry Analysis 🔯 on the Utilities toolbar, or click Utilities, Geometry Analysis.
- 3 In the PropertyManager:
 - a) Select Insignificant geometry and Small faces.
 - b) Set All Edge Lengths to 50.
 - c) Clear all other check boxes.
 - d) Click Calculate.
- 4 Click Save Report.
- 5 In the dialog box:
 - a) Type a name for **Report name**.
 - b) Select Add report to Design Binder.
- 6 Click Save.
- 7 Click **Cancel** (x) to close the PropertyManager.

The report appears in the FeatureManager design tree in the **Design Binder** folder \diamondsuit with a **.utl** extension. It is embedded in the part, not linked. If you update the part, the report does not update automatically.

- 8 Double-click the report to view it.
- 9 Keep **bucket.sldprt** open for the next procedure.

Thickness Analysis

You can now create reports of the data collected with the **Thickness Analysis** tool. The reports contain extra information to supplement the data included in the **Thickness Analysis** PropertyManager. Additionally, you can use the **Report Manager** utility with reports generated from **Thickness Analysis**.

To save a report with data from the Thickness Analysis tool:

- 1 Open \SolidWorks_Office\bucket.sldprt from the File Explorer if you do not have it open from the previous procedure.
- 2 Click Thickness Analysis 📚 on the Utilities toolbar, or click Utilities, Thickness Analysis.
- 3 In the PropertyManager, under Analysis Parameters:
 - a) Set Target thickness \checkmark_1 to 3.
 - b) Select Show thick regions.
 - c) Set Thick region limit to 6.
 - d) Select Treat corners as zero thickness.
- 4 Click Calculate.
- 5 Click **Save Report**. You can create views in the **Orientation** dialog box before clicking **Save Report** if you want to include custom views in the report.



- 6 In the dialog box:
 - a) Type a name for **Report name**. This is the name of the folder where the report is saved. All reports generated by this utility are named **gtReportIndex.htm**.
 - b) Click **Browse** and navigate to where you want to save the report, then click **OK**.
 - c) Select View report on save.
 - d) Click Save.

The report is generated and opens with the following information:

Options Used. Lists the options you selected for the analysis.

Summary. Displays an abridged version of the Analysis Details.

Analysis Details.

- Critical thickness range. Lists four ranges of critical thickness, with the number of faces and surface area of the model that falls into each category. The % of analyzed area is the total area analyzed that falls into the associated Thickness range.
- Critical features. Lists all features that violate the Target thickness.

Mass Properties. Lists the Surface Area, Volume, and Mass of the part.

Model View(s). Displays the Thickness scale and the Current view of the model.

Chapter 13 SolidWorks Office Add-Ins

Index

3D ContentCentral 1-4, 1-5

Α

align align between lines 10-19 align collinear/radial 10-20 align parallel/concentric 10-20 dimensions 10-4 groups 10-19 space evenly across 10-2 space evenly down 10-2 align between lines 10-19 align collinear/radial 10-20 align parallel/concentric 10-20 align toolbar 10-19-10-20 aligned section views 9-2, 9-4 analysis, mold tool 5-4 angular units in equations 4-3 animation tabs 13-25 animation wizard 13-31 animations, eDrawings Professional 13-5 annotation toolbar 10-20 annotations 10-2-10-14 align 10-20 alignment 10-2 area hatch/fill 10-2, 10-6 bills of materials 10-16 blocks 10-3 cosmetic threads 10-4 datum target symbols 10-4 Design Library 10-17 dimensions 10-4 geometric tolerance symbols 10-5 hide/show 10-6 highlight 10-6 hole callouts 10-7

insert model items 10-17 library features 10-7 move 10-7 notes 10-8, 10-9, 10-10 select 10-11 surface finish symbols 10-11 weld beads 10-12 weld symbols 10-14 **Application Programming Interface** (API) 12-2 eDrawings 13-2 PDMWorks 13-14 apply to all, lofts 3-16 arc segments, weld 6-3 area hatch/fill 10-2. 10-6 assemblies 7-1–7-9 component configurations 8-4 exploded views 7-3-7-5 external references 7-6 flexible sub-assemblies 7-7 importing 12-5 interference detection 7-8–7-9 level of detail option 7-2 performance 7-2 suspend automatic rebuilds 7-2 attach components in exploded views 7-5 AutoCAD import/export 12-5 Moving from AutoCAD 1-18 SolidWorks DWGEditor 12-4 autodimension 2-2, 10-15 auto-space exploded views 7-4

В

bend features 3-9 bills of materials 10-16 blocks 10-3

С

caustics, PhotoWorks 13-18 center of gravity 4-12 centerlines and guide curves, lofts 3-12 changebars 13-26, 13-28 check read-only files 1-15 collaboration 1-14 collapse Task Pane 1-2 commands, repeat 1-11 comments 1-8 compare documents in PDMWorks 13-11 drawings 9-2 components display animation 13-31 driving and driven 13-26 compression, eDrawings 13-2 configurations 8-2-8-5 assembly components 8-4 library features 11-7 mass properties 4-12-4-13 materials 8-5 tolerances 8-2-8-3 constant width fillets 3-8 coordinates 4-14 Copy Settings Wizard 1-16 cores, mold 5-2 cosmetic threads display 10-18 FeatureManager design tree 10-4 crop views 9-2 curvature continuity, lofts 3-13 curvature to face. lofts 3-13 curve direction. deforms 3-6 curve to curve match tangency options, deforms 3-6 curved weldments 6-3 custom properties bills of materials 10-16 parts 4-2 customize by work flow 1-10 registry settings 1-16 user interface 1-9, 1-16 cut lists, weldments 6-2

D

datum target symbols 10-4 decals, PhotoWorks 13-22 defer updates 7-2 deforms 3-4 curve direction 3-6 curve to curve match tangency options 3-6 surface push 3-4 surface tangent 3-6 delete connectors. lofts 3-17 Design Binder 1-7 Design Journal 1-7-1-8 Design Library 1-4-1-6 3D ContentCentral 1-4, 1-5 drag files 1-5 filters 1-4 library features 11-2 new folder 1-6 referencing folders 1-5 shortcuts 1-5 SolidWorks Toolbox 1-4 design tables mass properties 4-13 tolerances in 8-3 detached drawings 9-2 detail views 9-2 dimensions 2-27 align 10-4 annotations 10-4 autodimension 10-15 configurable tolerances 8-2-8-3 configure tolerances 10-4 display 10-4 driven by global variables 4-6 equations 4-3-4-5 internal dimensions 11-7 locate 11-7 modify 4-3, 10-4 override 10-4 status indicator 4-2 directional light 4-9 distance between entities 4-14 dock Task Pane 1-2 documentation 1-18 download options, eDrawings 13-3 DrawCompare 9-2 drawing sheets 9-5 drawing views aligned section 9-2, 9-4 borders 9-6

child views 9-7 component and view commands 9-6 crop 9-2 delete 9-7 detail 9-2 lock view focus 9-7 lock view position 9-7 move 9-7, 10-7 overlap 9-7 projected 9-4 PropertyManagers 9-8 rename 9-7 section 9-4 select 9-8 drawings aligned section views 9-2, 9-4 bills of materials 10-16 compare 9-2 crop views 9-2 detached 9-2 detail views 9-2 drawing toolbar 9-9 edge selection 9-8 FeatureManager design tree 9-9 lightweight 9-3 line styles 10-18 OLE objects 9-3 options 9-3 projected views 9-4 section views 9-4 sheets 9-5 sketch selection 9-9 sketches 9-9 DWGEditor. See SolidWorks DWGEditor DXF/DWG eDrawings 13-3 import/export 12-5 SolidWorks DWGEditor 12-4 dynamic lighting 4-9-4-12

Е

edges heal 5-4 in drawings 9-8 eDrawings 13-2–13-6 API 13-2 compression 13-2 download options 13-3 DXF/DWG import 13-3 executables 13-4

general items 13-2 shadows 13-4 tablet PCs 13-4 toolbar buttons 13-4 XREF paths 13-3 eDrawings Professional animations 13-5 passwords 13-6 SolidNetWork License 13-6 SolidNetWork License (SNL) 12-7 equations 4-3-4-5 add 4-4 angular units 4-3 delete 4-5 edit 4-5 executables, eDrawings 13-4 expand Task Pane 1-2 exploded views 7-3-7-5 external references, do not create 7-6 extrusions, start plane 3-8

F

faces move 5-5-5-7 straddle 5-7 Feature Palette 1-4 FeatureManager design tree comments 1-8 Design Binder 1-7 drawing icons 9-9 materials, recently used 1-9 features 3-1-3-21 deforms 3-4 extrusions 3-8 fillets 3-8 flexes 3-9 general 3-2 indents 3-10 lofts 3-12 mirrors 3-19 move/copy bodies 3-19 smart selection 3-2 split line curves 3-20 sweeps 3-21 triad 3-4, 3-9, 3-19 FeatureWorks 13-7–13-9 Hole Wizard holes 13-7 miter flanges 13-9 step-by-step recognition 13-9 File Explorer 1-3

File Locations 1-5 fillets, constant width 3-8 flex features 3-9 flexible sub-assemblies 7-7 flip relations 2-10 float Task Pane 1-2 formatting toolbar 10-20 forming tools filter 1-4

G

geometric tolerance symbols 10-5 getting started 1-2 global illumination, PhotoWorks 13-20 global variables 4-5-4-7 groups 10-19 guide curves alignment in lofts 3-14 centerlines and, in lofts 3-12 draft angle in lofts 3-14 influence in lofts 3-15

Н

handle colors, lofts 3-18 handles 2-8 heal edges 5-4 helixes 11-2 help 1-18 hide/show annotations 10-6 highlighting 1-9 hole callouts 10-7 Hole Wizard holes, FeatureWorks 13-7

I

import/export 12-4-12-6 assemblies 12-5 AutoCAD 12-5 Intermediate Data Format (IDF) 12-6 Mechanical Desktop 12-5 SolidWorks DWGEditor 12-4 Unigraphics 12-6 indent features 3-10 individual segment weight control, lofts 3-16 infinite lines 2-18 insert model items 10-17 mold folders 5-5 installation administrative images 12-7 SolidNetWork License (SNL) 12-7 interactive What's New 1-18

interference detection 7-8–7-9 Intermediate Data Format (IDF) 12-6 internal dimensions 11-7 interpolation modes 13-30 intersection split lines 3-20

Κ

key points 13-24, 13-28 key properties 13-29

L

large assembly mode 7-2 level of detail option 7-2 library features 11-2-11-10 annotations 10-7, 11-2 configurations 11-7 Design Library 1-4, 11-2 dimensions 11-7 FeatureManager design tree 11-6 links to library part 11-9 machine design 11-10 PropertyManager 11-7 save as 11-6 library features, planes 11-3 lighting 4-9-4-12 directional 4-9 PhotoWorks 13-16 point 4-10 spot 4-10 lightweight drawings 9-3 line styles 10-18, 12-5 lines 2-18-2-19 linked values 4-7-4-8 lofts 3-12-3-18 centerlines and guide curves 3-12 curvature continuity 3-13 delete connectors 3-17 draft angle at guide curve 3-14 guide curve alignment 3-14 guide curve influence 3-15 handle colors 3-18 individual segment weight control 3-16 mesh previews 3-17 PropertyManager changes 3-12 synchronization 3-17 undo connector commands 3-17

Μ

machine design library features 11-10 overview 1-18 mass properties 4-12-4-13 materials configurable 8-5 recently used 1-9 mates, SolidWorks Animator 13-32 measure tool 4-13-4-15 display coordinates 4-14 measure between entities 4-14 Mechanical Desktop 12-5 menus customize 1-10 PDMWorks 13-10 merge edges 5-4 mesh previews, lofts 3-17 mirror sheet metal features 3-19 sketch entities 2-25 miter flanges, FeatureWorks 13-9 modify dimensions 4-3 mold design online tutorial 1-18 overview 1-18 mold tools 5-1-5-14 cores 5-2 folders 5-5 heal edges 5-4 MoldflowXpress 5-4 move face 5-5-5-7 parting lines 5-7-5-8 parting surface 5-9 planar surface from co-planar loops 5-10 shut-off surfaces 5-13 tooling splits 5-11 undercut detection 5-14 MoldflowXpress 5-4 move face 5-5-5-7 move/copy bodies 3-19 Moving from AutoCAD 1-18 multibody folders 4-15 tooling splits 5-11 multi-user environment 1-14

Ν

no external references 7-6 notes 10-8–10-10 insert annotations 10-10 leader display 10-8 PropertyManager 10-8 rich text format 10-9 variables 10-10

0

offset a face 5-5 offset entities splines 2-17 tool 2-2-2-3 OLE objects 9-3 online help 1-18 resources 1-2 tutorial 1-18 Open in SolidWorks 1-3, 1-17 options collaboration 1-17 cosmetic threads 10-18 drawings 9-3 File Explorer 1-17 line styles 10-18 macro editing 1-17 PDMWorks 13-14 organize solid bodies 4-15 override dimensions 10-4

Ρ

part numbers 13-38 parting lines 5-7-5-8 parting surface 5-9, 5-12 parts 4-1-4-16 custom properties 4-2 equations 4-3-4-5 global variables 4-5-4-7 lighting 4-9-4-12 linked values 4-7-4-8 mass properties 4-12-4-13 measure tool 4-13-4-15 multibody 4-15 passwords eDrawings Professional 13-6 PDMWorks 13-14 SolidWorks Toolbox 13-35

PDMWorks 13-10-13-15 bulk check in 13-15 client check in 13-12 compare documents 13-11 copy projects 13-15 delete documents 13-14 lock Vault 13-14 open 13-10 options 13-14 passwords 13-14 print files 13-12 revision tables 13-11 search 13-13 SolidWorks DWGEditor 13-12 SolidWorks Task Scheduler 13-12 Task Pane 13-10 toolbars and menus 13-10 triggers 13-15 update files 13-12 Web Portal 13-15 performance, assemblies 7-2 PhotoWorks 13-16-13-23 caustics 13-18 decals 13-22 global illumination 13-20 indirect illumination 13-16 lights 13-16 materials 13-17 OpenGL 13-16 previews 13-16, 13-22 reflective environment 13-23 scenes 13-17, 13-23 studio 13-17 texture mapping 13-22 pin Task Pane 1-2 planar surfaces 5-10 planes, library features 11-3 point light 4-10 projected views 9-4 properties, weldment 6-6

Q

quick snaps 2-4, 2-7 Quick Tips 1-18

R

rebuild suspended 7-2 recent commands 1-11 registry settings 1-16 relations 2-15 reload 1-15 render, PhotoWorks 13-17 repeat last command 1-11 revision tables in PDMWorks 13-11 rotate a face 5-6

S

section views 9-4 selection cross select 1-12 filters 1-13 select other 1-12 shadows, eDrawings 13-4 shared values 4-7-4-8 sheet metal features. mirror 3-19 shut-off surfaces 5-13 side cores 5-2 silhouette split lines 3-20 sketch snaps 2-5-2-6 sketch tools mirror 2-25 offset entities 2-2 trim 2-20 sketching 2-2-?? circles 2-4 constrain in 3D sketches 2-28 dimensions 2-27 lines 2-18 relations display 2-28 select in drawings 9-9 snap and inference 9-9 splines 2-8–2-17 smart selection 3-2 solid bodies 4-15 SolidNetWork License (SNL) borrow licenses 12-7 eDrawings Professional 12-7, 13-6 SolidWorks Animator 13-24-13-34 animation tabs 13-25 changebars 13-26, 13-28 component display animation 13-31 interpolation modes 13-30 key points 13-24, 13-28 key points and edits 13-30 key properties 13-29 save partial animation 13-34 shortcuts 13-29 timebar 13-24, 13-27 timeline 13-24, 13-26 tools 13-25, 13-27

user interface 13-25-13-31 view orientation 13-29-13-30 SolidWorks DWGEditor 12-4, 13-12 SolidWorks Resources 1-2 SolidWorks Task Scheduler 13-12 SolidWorks Toolbox 13-35-13-38 access controls 13-35 configure browser 13-35 configure data 13-36 in Design Library 1-4 in PDMWorks 13-11 part numbers 13-38 password protection 13-35 user-defined standards 13-36 SolidWorks Utilities 13-39-13-45 Compare Features 13-39 Compare Geometry 13-40 Feature Paint 13-41 Find/Modify/Suppress/Simplify 13-42 Geometry Analysis 13-43 Power Select 13-43 Reports 13-44 Thickness Analysis 13-45 space components in exploded views 7-4 splines 2-8-2-17 add curvature control 2-11 add tangency control 2-11 flip relations 2-10 handles 2-8 modify curvature control 2-12 offsets 2-17 PropertyManager 2-9-2-10 relations 2-15 restrictions 2-15 shortcut menus 2-11 sketching 2-8 splines on surface 2-16 tangent magnitude 2-9 tangent radial direction 2-9 tools 2-15 split faces 5-7, 5-8 split lines, silhouette and intersection 3-20 splits, tooling 5-11 spot light 4-10 status bar measurements 4-13 rebuild suspended 7-2 step-by-step recognition, FeatureWorks 13-9 straddle faces 5-7 sub-assemblies, flexible 7-7

surface finish symbols 10-11 surface push deform type 3-4 surface tangent, deforms 3-6 surfaces parting 5-9 planar from co-planar loops 5-10 shut-off 5-13 splines on surface 2-16 trim with 3D sketch 2-2 suspend automatic rebuilds 7-2 sweeps 3-21 synchronization, lofts 3-17 system options external references 7-6 level of detail 7-2

т

table toolbar 10-20 tablet PCs, eDrawings 13-4 target bodies deforms 3-5 indents 3-10 Task Pane 1-2–1-6 Design Library 1-4-1-6 docked or floating 1-2 expanded and collapsed 1-2 File Explorer 1-3 PDMWorks 13-10 pinned and unpinned 1-2 SolidWorks Resources 1-2 Task Scheduler. See SolidWorks Task Scheduler text comments 1-8 timebar 13-24, 13-27 timeline 13-24, 13-26 to next options, loft guide curves 3-15 tolerances, configurable 8-2-8-3 tool bodies deforms 3-5 indents 3-10 toolbars 1-11 align 10-19-10-20 annotation 10-20 drawing 9-9 eDrawings buttons 13-4 formatting 10-20 PDMWorks 13-10 Standard 1-11 table 10-20 Toolbox. See SolidWorks Toolbox

```
tooling splits 5-11
translate a face 5-6
triad
  features 3-4, 3-9, 3-19
  SolidWorks Animator 13-31
trim 2-20-2-24
  corner trim 2-21
  power trim 2-20
  surfaces with 3d sketch 2-2
  trim away inside 2-22
  trim away outside 2-23
  trim to closest 2-24
  weldments 6-4-6-6
twist
  features 3-9
  sweeps 3-21
```

U

undercut detection 5-14 undo, loft connector commands 3-17 Unigraphics 12-6 user interface 1-2, 1-9, 1-16 user-defined standards 13-36

۷

variables, global 4-5–4-7 view orientation, SolidWorks Animator 13-29, 13-30 voice comments 1-8

W

weight control, lofts 3-16 Welcome to SolidWorks 1-18 weld beads caterpillar 10-12 end treatment 10-12 weld symbols 10-14 weldments 6-2–6-6 curved structural members 6-3 cut lists 6-2 online tutorial 1-18 properties 6-6 trim 6-4–6-6 What's Wrong? 1-9

Х

XREF paths, eDrawings 13-3